

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 693Z

AAD1908-179

*Not Authored
1/1/19 @ 5300h*

Vehicle No.:
Chassis No.:
Vehicle Make: *27 AUG 2019*
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHF 693Z
VF1ABL15AUC281172
RENAULT
LATITUDE
24.8.19
EQ
31/12/2014

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>Br</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>Del/br</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>SL</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$ <i>SL</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$ <i>SL</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$ <i>SL</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$ <i>SL</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$ <i>SL</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$ <i>CM</i> 43.61 ✓
10	1 BUMPER BEAM REAR	\$ <i>Br</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>N</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>N</i> 225.95 X
13	1 OUTER PANEL REAR (End Panel)	\$ <i>N</i> 1,471.77 X
14	1 OUTER PANEL REAR (End Panel) TRIM	\$ <i>SL</i> 404.56 X
15	1 TAILLAMP RH	\$ <i>SL</i> 552.55 X
16	1 TAILLAMP PANEL RH	\$ <i>N</i> 986.70 X
17	1 TAILLAMP LH	\$ <i>SL</i> 552.55 X
18	1 TAILLAMP PANEL LH	\$ <i>N</i> 986.70 X
19	1 BOOT REAR	\$ <i>Br</i> 2,872.68 ✓
20	1 BOOT FINISHER	\$ <i>SL</i> 470.06 X
21	1 BOOT WHEATERSTRIP	\$ <i>SL</i> 323.05 X
22	1 BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 493.35 X
23	1 BOOT REFLECTOR LAMP RH	\$ <i>SL</i> 493.35 X
24	1 BOOT BADGE 'RENAULT'	\$ <i>N</i> 225.36 ✓
25	1 BOOT BADGE	\$ <i>N</i> 225.36 ✓
26	1 BOOT STRUT LH	\$ <i>SL</i> 276.08 X
27	1 BOOT STRUT RH	\$ <i>SL</i> 276.08 X

Trans-cab Auto Services Pte Ltd

AAD1908-179

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 693Z

28	1	BOOT HINGE LH	\$	<i>na</i>	367.84	X
29	1	BOOT HINGE RH	\$	<i>na</i>	367.84	X
30	1	BOOT INNER TRIM	\$	<i>sa</i>	586.45	X
31	1	BOOT SWITCH	\$	<i>sa</i>	168.13	X
32	1	BOOT LOCK	\$	<i>na</i>	202.67	X
33	1	BOOT LOCK CATCH	\$	<i>na</i>	74.40	X
TOTAL			\$		16,046.87	
10%			\$		1,604.69	
			\$		14,442.19	

Special Nett

1	1SET	PARKING AID	\$	<i>sa</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>na</i>	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	✓
11	1	BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	✓
12	1	EXHAUST MOUNTING REAR	\$	<i>sa</i>	17.82	} X
13	2	REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00	
14	1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	
16	1	BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	
17	1SET	BOOT FINISHER CLIP	\$	<i>na</i>	24.20	
18	1	TAILLAMP CLIP LH	\$	<i>na</i>	5.00	
19	1	TAILLAMP CLIP RH	\$	<i>na</i>	5.00	
TOTAL			\$		1,384.02	

TOTAL PARTS \$ 15,826.21

LABOUR

To Check Electrical Lighting Concerned. \$ 170.00 *2ok*

Trans-cab Auto Services Pte Ltd

AAD1908-179

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 693Z

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	4001
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	4401
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X

TOTAL \$ 11,550.00

Over All Total \$ 27,376.21

LUMP SUM (REPAIR DAY)

15 DAYS

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: