

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5062C**AAD1908-185***Not Authored
1/1/2013*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

*27 AUG 2019***SHC 5062C**

VF1ABL15AUC276089

RENAULT

LATITUDE

24.8.19

AXA

2/12/2013

PART		LIST	
1	BUMPER COVER FRT	\$	Bu 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	Dis 181.75 ✓
1	BUMPER ABSORBER FRT	\$	Sm 394.68 X
1	BUMPER RETAINER FRT RH	\$	Dis 151.41 ✓
1	BUMPER SUPPORT FRT	\$	Sm 123.88 X
1	BUMPER UNDERTRAY FRT	\$	Sm 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	Sm 266.80 ✓
1	BUMPER FOG LAMP GRILLE RH	\$	Dis 207.21 ✓
1	BUMPER BEAM FRT	\$	As 914.08 X
1	HEADLAMP RH	\$	mgcm 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	R 152.15 X
1	FENDER PANEL FRT RH	\$	As 783.83 ✓
1	WHEELARCH FRT RH	\$	Sm 278.84
1	FENDER BRACKET LOWER RH	\$	Sm 15.79
1	FENDER INSULATOR RH	\$	Sm 130.84 X
1	TOW COVER FRT	\$	Sm 28.61
1	FRONT BRACE PANEL	\$	R 177.22
1	RADIATOR GRILLE ✓	\$	mgcm Sm 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT' ✓	\$	na Sm 225.36
1	RADIATOR GRILLE FRAME ✓	\$	CRM Sm 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	Sm 615.90
1	FRAME FULL SUPPORT BRACKET	\$	R 89.79
1	BONNET	\$	R 1,941.63
1	BONNET INSULATOR	\$	Sm 405.73 X
1	BONNET STRUT LH	\$	Sm 88.61
1	BONNET STRUT RH	\$	Sm 88.61
1	BONNET HINGE LH	\$	R 348.31
1	BONNET HINGE RH	\$	R 348.31
1	BONNET LOCK	\$	R 305.48

Trans-cab Auto Services Pte Ltd**AAD1908-185**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5062C

1	BONNET CABLE	\$	Su	119.19	}
1	BONNET CABLE COVER	\$	Su	161.03	
1	BONNET SEAL OUTER	\$	Su	92.36	
1	BONNET SEAL INNER	\$	Su	157.28	
1	DOOR PANEL FRT RH	\$	M	2,844.66	
1	DOOR MIRROR ASSY RH	\$	Su	1,483.40	
1	DOOR WHEATHESTRIIP FRONT RH	\$	Su	410.66	
1	DOOR SEAL FRONT RH	\$	Su	162.02	
1	LOWER ARM RH L70Y	\$	Su	685.76	
1	KNUCKLE ARM RH L70Y	\$	Su	846.98	
1	ABSORBER FRT RH L70Y	\$	Su	360.54	
1	DRIVESHAFT RH	\$	M	1,747.45	
1	STABILIZER BAR FRT	\$	Su	604.65	
1	WIPER RESERVOIR MOTOR	\$	Su	270.06	
1	WIPER RESERVOIR	\$	Su	348.25	
1	WIPER RESERVOIR NECK	\$	Su	136.11	
1	DOOR HARNESS WIRE RH	\$	Su	2,670.00	
1	SUBFRAME OUTER FRT	\$	Su	2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	Su	92.36	
1	SUBFRAME BRACKET OUTER RH	\$	Su	92.36	
TOTAL		\$		30,180.58	
10%		\$		3,018.06	
		\$		27,162.52	

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	X
1	FRONT DOOR STICKER 'Classic'	\$	na	80.00	X
1	BUMPER CLIP FRT	\$	na	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	}
1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	}
1	WHEELARCH CLIP FRT RH	\$	na	30.50	
1	FRONT RIGHT TYRE	\$	sta	300.00	
1	FRONT RIGHT TYRE RIM	\$	Su	380.00	

Trans-cab Auto Services Pte Ltd**AAD1908-185**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5062C

1SET	Front licence plate with holder	\$	80.00	} X
1SET	RADIATOR GRILLE SCREW	\$	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	
1	WINDSCREEN SEALANT	\$	253.80	
1	FRONT WINDSCREEN MOULDING	\$	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	7.30	
2	BONNET STRUT L70Y	\$	88.61	
2	BONNET CABLE CLIP L70Y	\$	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	10.85	
TOTAL		\$	1,882.88	

TOTAL PARTS	\$	29,045.40
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	5001 4401
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of front windscreen fittings and conduct water seepage test.	\$	170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201

Trans-cab Auto Services Pte Ltd**AAD1908-185**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5062C

To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00 X
TOTAL	\$	15,560.00
Over All Total	\$	44,605.40

LUMP SUM (REPAIR DAY)~~20 DAYS~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: