

Estimate Cost Of Repairs

Vehicle # SKZ1120M

QTY	DESCRIPTIONS	UNITS	AMOUNTS
1 pce	Rear bumper fascia <i>Repair X</i>	\$	455.90 X
1 pce	Rear bumper n/s side retainer <i>X NN</i>	\$	61.20 X
1 pce	N/s rear lamp assy <i>Sub</i>	\$	320.00 /
1 pce	N/s rear fender <i>Buc</i>	\$	765.80 /
1 pce	N/s rear fender inner shield <i>X NN</i>	\$	46.70 X
1 pce	N/s rear air intake grille <i>X</i>	\$	114.75 X
1 pce	N/s rear door <i>Buc</i>	\$	866.35 /
1 pce	N/s rear door outer handle <i>Sub</i>	\$	62.40 /
1 pce	N/s rear door protector <i>Cut</i>	\$	23.80 /
1 pce	N/s rear door glass outer moulding <i>el</i>	\$	110.00 /
1 pce	N/s rear door regulator gear <i>X NN</i>	\$	158.20 X
1 pce	N/s rear door regulator motor and gear assy <i>X NN</i>	\$	667.35 X
1 pce	N/s rear door inner lock <i>Im</i>	\$	161.70 /
1 pce	N/s rear door locking actuator <i>X NN</i>	\$	248.90 X
1 pce	N/s rear door 1/4 glass pillar <i>X NN</i>	\$	140.75 X
1 pce	N/s rear door channel felt <i>X</i>	\$	95.60 X
1 pce	N/s rear door rubber <i>X NN</i>	\$	35.00 X
1 pce	N/s rear door hinges <i>X</i>	\$	134.40 X
1 pce	N/s rear door arrestor <i>X NN</i>	\$	131.80 X
1 pce	N/s rear door inner trim board <i>X</i>	\$	255.00 X
1 pce	N/s front door <i>Buc</i>	\$	772.30 /
1 pce	N/s front door outer handle <i>X</i>	\$	62.40 X
1 pce	N/s front door regulator motor and gear assy <i>X NN</i>	\$	671.55 X
1 pce	N/s front door protector <i>Cut</i>	\$	30.60 /
1 pce	N/s front door inner lock <i>X</i>	\$	231.05 X
1 pce	N/s front door locking actuator <i>X NN</i>	\$	189.75 X
1 pce	N/s front door channel felt <i>X</i>	\$	101.60 X
1 pce	N/s front door rubber <i>X NN</i>	\$	38.40 X
1 pce	N/s door center pillar <i>X Repair</i>	\$	523.60 X
1 pce	N/s rocker panel <i>X Repair</i>	\$	278.60 X
1 pce	Rear windscreen moulding <i>Mc</i>	\$	87.60 /
1 pce	N/s rear knuckle arm <i>X NN</i>	\$	184.30 X
1 pce	N/s rear wheel bearing <i>Mc</i>	\$	466.95 /
1 pce	N/s rear shock absorber <i>X NN</i>	\$	183.20 X

\$ 8,677.50
 Less 25% \$ (2,169.38)
 \$ 6,508.13

UK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spot painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal responsibility is accepted
- Repairs must be carried out by a qualified and insured company

Authorised Signature _____
 Date _____

	S/Nett			
1 pce	Rear windscreen glass sealant		\$	80.00
1 pce	N/s rear wheel		\$	300.00
1 pce	N/s rear tyre		\$	250.00
	Labour			
	To remove damaged lamps and necessary wirings to enable necessary repairs, check, replace damaged lamps and refit.		\$	50.00
	To disconnect rear suspensions assy., and rear carrier assy. to enable necessary repairs, check, replace damaged parts and refit same.		\$	280.00
	To check wheel alignment – computerize.		\$	60.00
	To remove ganishes, upholstery, carpets and necessary interior fittings to enable repairs and replace of parts, refit same.		\$	150.00
	To remove rear windscreen glass and fittings, Check, replace damaged parts, refit same. (Bonded type windscreen glass)		\$	180.00
	To remove both n/s doors' complete fittings And glass assy., check, replace damaged Parts, transfer all fittings to new door and refit.		\$	280.00
	To remove damaged parts, jack and cut out Damaged body panels, jack out, straighten up Damaged body panels and repair body parts and fittings, whichever possible and necessary, replace and weld necessary damaged parts, refit and realign whichever parts necessary. [Incl. alignments of body members.]		\$	1,400.00
	Paint replacement parts and repaint damaged Sections with welded portions in and outside.		\$	1,200.00
	7 Days			
	Unpaid repair			
	After repair photos			
	Am. Qian - 8288 0282			
	28/8/19			
	Total		\$	10,738.13

50
250
300

30

50

✓

60

100

120

800

1100

2320

5370.67

20% 3500