

Khanchana

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

ROC:53360061L

GST:53360061L

QT19/PC656C/TPC-549

Lonpac Insurance Bhd

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC626C

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Front windscreen / CRA	1	3,800.00	3,800.00
2.	Front windscreen inner moulding / MC	1	680.00	680.00
3.	Front LH rear view mirror assy / BR	1	1,350.00	1,350.00
4.	Sealant	8	40.00	320.00
5.	Labour to remove & refit front windscreen	1	1,000.00	1,000.00
6.	Check wiring	1	20.00	20.00
7.	Labour charges	1	600.00	600.00
8.	Spray painting	1	800.00	800.00
SUB-TOTAL				SS8,570.00

- Price before 7% gst

Thank you

Yours faithfully,



Winnie Chai

HP: 9850-9666

Steve (LKK) MC Rejude 29/8/17, 12:00pm
8333 8811 3 dy

LIS

By ALM

P- 4680

L- 1990

6670

LIS- 5336

5350

3500 /
500 /
1200 /
5200
- 10%
4680

800

450

400