

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10308

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1036/2019/NS
Date : 30-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Leo Chin Hao
Address : 43A Lorong L Telok Kurau
Singapore 425461
Telephone : 96900909
Type of Claim : Third Party Claim
Policy No. : DMPCSN3046811900
Vehicle No : **SMM 534 D**
Model Code : Audi A1 SB 1.0 TFSI S tronic
Model / Year : 27/1/2016
Engine No : CHZ 057780
Chassis No : WAUZZZ8X4GB059793
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Aug-19
Place of Accident : Outside 43A Lorong L Telok Kurau

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMM 534 D

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00	
3	To respray rear bumper and rhs rear fender.	\$ 1,800.00	
4	To carry out diagnostic checks.	S/N \$ 192.00	
	TOTAL LABOUR CHARGES	: \$ <u>3,322.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SMM 534 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,306.00	
2	REAR BUMPER STICKY PAD	2 \$ 11.00	
3	REAR BUMPER FIXING PARTS	\$ 68.00	
4	REAR BUMPER SPOILER	\$ 384.00	
5	REAR LIGHT REFLECTOR - RH	\$ 27.00	
6	REAR BUMPER CARRIER	\$ 450.00	
7	REAR BUMPER GUIDE SECTION - RH	\$ 44.00	
8	REAR PARKING AID SENSOR	2 \$ 419.00	
9	SUNDRIES	\$ 200.00	
	FRONT TOTAL SPARE PARTS	: \$ 2,909.00	
	FRONT TOTAL LABOUR CHARGES	: \$ 3,322.00	
	GRAND TOTAL	: \$ 6,231.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant