

ASS. REC. BY:

REP:

CS/SMO/19015241/Ktf3 n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Thelma Choo

of SMO

Date/Time: 29/08/2019

Merimen

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 5702

Insured: FB3 4521K

at Workshop/nr: Transcab Auto Services Pte Ltd

Tel:

of No 2 Ang Mo Kio Street 63

Policy No: D18MTMCO1007260

Claim No: CMTD1904104

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26.8.2019

(If Make is known)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 09:47am @ 29/08/2019 Person Contacted:

Condy

Vehicle: IN / OUT

Date/Time

Action/Instruction: 1. Show bill (✓)

FB3 4521K - X

SHC 5702 - CC3/112146/23016/Kun342 D.O.A. 27/12/2016

30/8@16:36- Revised via merimen. 1A

Lump Sum \$3000- (Red: 51191.19; 94%) confirm

REF: SMO

## ASSIGNMENT

From: Date: 29.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / RV / MV

To Inspect Vehicle No: SHC 5170Z

at Workshop no: Trans-rab

of NO 2 AMK Street 63

Insured

Policy No

Claims No

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repair:

02

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

map

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SHC 5170Z 01 14

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Logan 1995

Colour: White / Red AC Insured / Std / NI / NA

Sp. Reading: 782235 T&amp;R: Insured / Std / NI / NA

Eng/No:

C/Nr: VF1ABL15AUC 276693

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Skilun

Front

Rear

R/Bal:

8

mm

R/Bal:

8

mm

L/Bal:

8

mm

L/Bal:

8

mm

D.O.A

26/8/19

D.O.A

29/8/19

Survey held at:

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

N/S Fr

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

61 Pay 83100

RECEIVED 06 NOV 2019

Date/Time, File Pass to?

611 Typst

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

☐

Prel. Report

☐

Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Ins (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

3-Hrs. fee

Phone

Others

TOTAL

450  
11

461

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Thelma Choo

Date: 30 Aug 2019

## Preliminary Advice

Insured Vehicle No : FBJ4521K

TP Vehicle No : SHC5170Z

Make : RENAULT LATITUDE

Date of Inspection : 29/08/2019

Inspection At : TRANS-CAB AUTO SERVICES PTE LTD  
NO 2 ANG MO KIO STREET 63  
SINGAPORE 569111

Accident Date : 26/08/2019

Assignment Date : 29/08/2019

Est. Duration of Repair : 2.00

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	54,291.19
Revised Amount	:S\$	3,861.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,861.00

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Survey on 'WP'

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019		29 Aug 2019 09:21 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	TAN HUI MING ZAC, ID: S9638987F								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHC5170Z	Date of Loss:	26/08/2019 19:00 - :59						
Claim Type:	TP / CMTD1904104	Policy/Cover Note No.:	D18MTMC01007260 (Comprehensive)						
Vehicle Reg. No. (Insured):	FBJ4521K	Policy No. (Claimant):							
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd ( ) No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ..., [Final Rpt due 09/09/2019]								
Adj Asp. Remarks:	WS: 62130998 CANDY KONG -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All Search Tasks Create New Task Complete</span>									
Due Date:	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAuto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Tuesday, 5 November 2019 3:48 PM  
**To:** Denise Tay (LKKAuto)  
**Subject:** FW: SHC 5170Z / TP / DOA: 26/8/2019 -- AAD1908-213  
**Attachments:** ESTIMATE.pdf

Hi Denise

Sorry for the delay.

Amount confirm \$ 3,100 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]  
**Sent:** Tuesday, 5 November, 2019 11:53 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** RE: SHC 5170Z / TP / DOA: 26/8/2019

Dear Wai Yin,

Can confirm?

Best Regards,  
**Denise Tay** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 30 October 2019 3:34 PM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** SHC 5170Z / TP / DOA: 26/8/2019

Dear Wai Yin,

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	B78K

**Vehicle Details**

Vehicle No.:	SHC5170Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000821
Chassis No.:	VF1ABL15AUC276693
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Jan 2014
First Registration Date:	14 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2022
PARF Rebate Amount:	\$8,748.00

**Intended COE Rebate Details**

COE Expiry Date:	13 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,888.00
COE Rebate Amount:	\$18,106.00
<b>Total Rebate Amount:</b>	<b>\$26,854.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Aug 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/08/2019 16:00
Date Of Accident	26/08/2019 19:20
Exact Location Of Accident	YISHUN AVENUE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5170Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	SIM TAY SAH@ERIC SIM YONG HUAT
NRIC No	S1416220H
Date Of Birth	10/03/1960
Occupation	OUTDOOR
Date Of Driving Pass	01/12/1977
Driving Experience	41 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93806861
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 225 PENDING ROAD #05-173
Postcode	670225
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : BENARD YEO - 92256505 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI N.P.C
Police Station Address	ROAD: 20 CLEMENTI AVE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20190827/2070

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ4521K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	



Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SMM7468R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

FAROUD

NRIC/Passport Number

Contact Number

97315757

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

plc se attach police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190828/2016

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

1 of 3

Report No. T/20190828/2016

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/08/2019 05:43	Vide Report No.: T/20190827/2070	Station Diary No.: 14
--	-------------------------------------	--------------------------

Informant's Particulars				
Name of Informant: SIM TAY SAH		Address: APT BLK 225 PENDING ROAD #05-173 SINGAPORE 670225		
ID Type / ID No.: NRIC NO / S1416220H		Contact No.: Home/Office: Mobile: 93806861		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 59	Date of Birth: 10/03/1960	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/08/2019 19:20	Type of Location: YISHUN DAM BRIDGE
Location: Along Road 1 YISHUN AVENUE 1  YISHUN AVENUE 1 YISHUN DAM BRIDGE				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
FBJ4521K	Motorcycle			Blue	No Damage	0
SHC5170Z	Car			Red	Slightly Damaged	1

**SINGAPORE  
POLICE FORCE**

T/20190828/2016

2 of 3

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

Report No. T/20190828/2016

**CONTINUATION OF REPORT****Brief Details.**

On 26/08/2019 at about 1917hrs, I was parked along Yishun Avenue 1 near Yishun Dam Bridge with my red coloured taxi bearing registration number SHC5170Z. I was parked stationary at the first lane at that time as traffic light was red. Next moment, one motorcycle bearing registration number FBJ4521K came from the rear and hit onto the body of the vehicle beside me (SMM7468R), driver of (SMM7468R) is one namely Faroud (97315757).

After hitting onto right side body of (SMM7468R) vehicle. The motorcycle lost balance and hit onto the front left side portion of my vehicle before falling down to the road with his motorbike. After which, my passenger and I quickly came out and render assistance to the rider. The rider is conscious and manage to pull his own motorbike. The rider still told both Faroud and me that he can private settle with us. Subsequently, the rider just pushed the bike away from us.

As the rider suffered some injury on his leg, we told the rider to take care of his injury first and talk about settlement thereafter. We managed to exchange our contact numbers. No ambulance or police were called down. My passenger and I did not suffer any injury.

However, later in the night at about 2300hrs, the rider message both Faroud and me to lodge a report instead of private settle.



**SINGAPORE  
POLICE FORCE**



T/20190828/2016

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

3 of 3

Report No. T/20190828/2016

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

Sgt 3 MUHAMMAD FADZIL BIN ROHAIZAD

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
28/08/2019 05:43

Officer In Charge Of Case:  
TP / AEIT /  
Staff Sgt WONG SIEU LUI  
Contact No.: 65476151

SN 117

Classification Of Case:

Authentication Stamp  
NP168

Singapore

Police Force



**SINGAPORE  
POLICE FORCE**



T/20190827/2070

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

1 of 3

Report No. T/20190827/2070

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/08/2019 12:46		Vide Report No.:		Station Diary No.: 58
<b>Informant's Particulars</b>				
Name of Informant: SIM TAY SAH		Address: APT BLK 225 PENDING ROAD #05-173 SINGAPORE 670225		
ID Type / ID No.: NRIC NO / S1416220H		Contact No.: Home/Office: Mobile: 93806861		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 59	Date of Birth: 10/03/1960	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/08/2019 19:20	Type of Location: Straight Road
Location: Along Road 1 YISHUN AVENUE 7  Yishun Damn Bridge				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBJ4521K	Motorcycle			Blue	No Damage	0
SHC5170Z	Car			Red	Slightly Damaged	1



**SINGAPORE  
POLICE FORCE**



T/20190827/2070

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

2 of 3

Report No. T/20190827/2070

**CONTINUATION OF REPORT**

**Brief Details.**

On 26/08/2019 at about 1917hrs, I was parked along Yishun Avenue 7 near Yishun Dam Bridge with my red coloured taxi bearing registration number SHC5170Z. I was parked stationary at the first lane at that time as traffic light was red. Next moment, one motorcycle bearing registration number FBJ4521K came from the rear and hit onto the body of the vehicle beside me (SMM7468R), driver of (SMM7468R) is one namely Faroud (97315757).

After hitting onto right side body of (SMM7468R) vehicle. The motorcycle lost balance and hit onto the front left side mirror of my vehicle before falling down to the road with his motorbike. After which, my passenger and I quickly came out and render assistance to the rider. The rider is conscious and manage to pull his own motorbike. The rider still told both Faroud and me that he can private settle with us. Subsequently, the rider just pushed the bike away from us.

As the rider suffered some injury on his leg, we told the rider to take care of his injury first and talk about settlement thereafter. We managed to exchange our contact numbers. No ambulance or police were called down. My passenger and I did not suffer any injury.

However, later in the night at about 2300hrs, the rider message both Faroud and me to lodge a report instead of private settle.





**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999



T/20190827/2070

3 of 3

Report No. T/20190827/2070

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / Sgt 2 LIH JUN JUN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 27/08/2019 12:48
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIE JIU Contact No.: 65476461	Classification Of Case: SN 37
Authentication Stamp NP168 	

**Trans-cab Auto Services Pte Ltd**

AAD1908-213

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5170Z**

1	BONNET CABLE COVER	\$	161.03
1	BONNET SEAL OUTER	\$	92.36
1	BONNET SEAL INNER	\$	157.28
1	LOWER ARM LH L70Y	\$	685.76
1	KNUCKLE ARM LH L70Y	\$	846.98
1	ABSORBER FRT LH L70Y	\$	360.54
1	DRIVESHAFT LH	\$	1,747.45
1	STABILIZER BAR FRT	\$	604.65
1	STEERING PINION RACK L70Y	\$	4,413.11
1	AUTO COMPUTER	\$	5,032.17
1	INJECTION COMPUTER	\$	4,706.30
1	RHD HYDRAULIC POWER(RQCK&PINION)	\$	5,154.52
1	STEERING PUMP ELECTRIC L70Y	\$	2,306.90
1	AIR CLEANER BOX	\$	464.20
1	AIR CLEANER HOSE	\$	175.85
1	AIR CLEANER LOWER	\$	271.26

**TOTAL \$ 41,542.57**  
**10% \$ 4,154.26**  
**\$ 37,388.31**

**Special Nett**

1	BUMPER CLIP FRT	\$	na 66.00
1	BUMPER BRACKET CLIP FRT LH	\$	na 12.00
1	BUMPER SUPPORT CLIP FRT LH	\$	na 10.50
1	BUMPER GRILLE LOWER CLIP	\$	na 69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00
1	WHEELARCH CLIP FRT LH	\$	na 30.50
1	FRONT LEFT TYRE	\$	sm 300.00
1	FRONT LEFT TYRE RIM	\$	sm 380.00
1SET	Front licence plate with holder	\$	sm 80.00
1SET	RADIATOR GRILLE SCREW	\$	sm 16.00
1SET	RADIATOR GRILLE FRAME CLIP	\$	na 52.00
1	WINDSCREEN SEALANT	\$	na 253.80
1	FRONT WINDSCREEN MOULDING	\$	na 120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na 100.00
6	BONNET INSULATOR CLIP L70Y	\$	na 7.30
2	BONNET STRUT L70Y	\$	sm 88.61

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5170Z**

AAD1908-213

*Not Authored  
11 Sep 8 3100h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

29 AUG 2019

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHC 5170Z**

VF1ABL15AUC276693

RENAULT

LATITUDE

26.8.19

**SOMPO**

14/1/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bro/lt</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>Sm</i> 151.41 X
1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 266.80 X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>It</i> 914.08 X
1	HEADLAMP LH	\$	<i>ngjst</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT LH	\$	<i>It</i> 152.15 X
1	FENDER PANEL FRT LH	\$	<i>It</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Sm</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>Sm</i> 15.79
1	FENDER INSULATOR LH	\$	<i>Sm</i> 130.84
1	TOW COVER FRT	\$	<i>Sm</i> 28.61
1	FRONT BRACE PANEL	\$	<i>It</i> 177.22
1	RADIATOR GRILLE	\$	<i>Sm</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>Sm</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>It</i> 89.79
1	BONNET	\$	<i>It</i> 1,941.63
1	BONNET INSULATOR	\$	<i>Sm</i> 405.73
1	BONNET STRUT LH	\$	<i>Sm</i> 88.61
1	BONNET STRUT RH	\$	<i>Sm</i> 88.61
1	BONNET HINGE LH	\$	<i>It</i> 348.31
1	BONNET HINGE RH	\$	<i>It</i> 348.31
1	BONNET LOCK	\$	<i>It</i> 305.48
1	BONNET CABLE	\$	<i>Sm</i> 119.19

**Trans-cab Auto Services Pte Ltd**

AAD1908-213

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5170Z

2	BONNET CABLE CLIP L70Y	\$	~ 6.31	X
2	BONNET CABLE COVER SCREW L70Y	\$	~ 10.85	X
TOTAL		\$	1,722.88	

TOTAL PARTS	\$	39,111.19
-------------	----	-----------

**LABOUR**

Putty and spray painting of the affected portion.	\$	6,000.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	4001
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of front windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X

**Trans-cab Auto Services Pte Ltd****AAD1908-213**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5170Z**

To remove and refit interior fittings, trimmings, garnish,  
fittings and other, to enable repair.

	\$	<i>nn</i> 380.00 <i>X</i>
<b>TOTAL</b>	<b>\$</b>	<b>15,180.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>54,291.19</b>

**LUMP SUM (REPAIR DAY)***20 DAYS**2 days*

LISC Auto Consultants hence notify the Repairer of the following:

- To remove blemishes spray painting
- To display damaged panels during recovery
- Parts prices are subject to confirmation
- Third party survey is so a "Witness Precursor" task
- No illegal modification is allowed
- Supplementary items, work as required and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19015241/KTF3N2

Date: 14/11/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTMC01007260
Claimant Vehicle No :	SHC5170Z	Insured Vehicle No :	FBJ4521K
Date of Loss:	26/08/2019	Nature of Claim:	TP
		Claim No:	CMTD1904104

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHC5170Z	Engine No:	M9R8839C000821
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC276693
Reg. Date:	14/01/2014 (Man. Year: 2013)	Odometer:	782235 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	39,111.19	2,970.91	36,140.28	92.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,180.00	890.00	14,290.00	94.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>54,291.19</b>	<b>3,860.91</b>	<b>50,430.28</b>	<b>92.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	54,291.19	3,100.00	51,191.19	94.29
<b>+ GST 7.00/7.00% (S\$)</b>	3,800.38	217.00	3,583.38	94.29
<b>Nett Amount (S\$)</b>	<b>58,091.57</b>	<b>3,317.00</b>	<b>54,774.57</b>	<b>94.29</b>

## INSPECTION

Date of Assignment:	29/08/2019	
Date Inspected:	29/08/2019	Inspected At: Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2019)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5170Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Broken/Cut	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
8	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
9	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
10	1		*HEADLAMP LH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
11	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
12	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
13	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
14	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
15	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
16	1		*TOW COVER FRT	Serviceable	28.61 FL	*- FL
17	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
18	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
19	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
20	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
21	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
22	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
23	1		*BONNET	Repair	1,941.63 FL	*- FL
24	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
25	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
26	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
27	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
28	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
29	1		*BONNET LOCK	Repair	305.48 FL	*- FL
30	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
31	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
32	1		*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
33	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
34	1		*LOWER ARM LH L70Y	Serviceable	685.76 FL	*- FL
35	1		*KNUCKLE ARM LH L70Y	Serviceable	846.98 FL	*- FL
36	1		*ABSORBER FRT LH L70Y	Serviceable	360.54 FL	*- FL
37	1		*DRIVESHAFT LH	Serviceable	1,747.45 FL	*- FL
38	1		*STABILIZER BAR FRT	Serviceable	604.65 FL	*- FL
39	1		*STEERING PINION RACK L70Y	Serviceable	4,413.11 FL	*- FL
40	1		*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
41	1		*INJECTION COMPUTER	Serviceable	4,706.30 FL	*- FL
42	1		*RHD HYDRAULIC POWER (RACK & PINION)	Serviceable	5,154.52 FL	*- FL
43	1		*STEERING PUMP ELECTRIC L70Y	Serviceable	2,306.90 FL	*- FL
44	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
46	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
47	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
48	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
49	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
50	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
51	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
52	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
53	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
54	1		*WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
55	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	*- FS
56	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
57	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
58	1		*SET RADIATOR GRILLE SCREW	Serviceable	16.00 FS	*- FS
59	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
60	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS
61	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
62	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
63	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS
64	2		*BONNET STRUT L70Y	Serviceable	88.61 FS	*- FS
65	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
66	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>43,265.45</b>	<b>3,293.68</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>4,154.26</b>	<b>322.77</b>

<b>Total Parts (\$\$)</b>	<b>39,111.19</b>	<b>2,970.91</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
6	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
10	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
13	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>15,180.00</b>	<b>890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >