

(08/11/13) wef

ASS. REC. BY: *maria*

REF:

VIC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐
☐

: Preli. Report

: Final Report

Add Fee:

☐
☐
☐
☐

: Site Insp

: Interview

: Tech. Invs

: Weekend

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

(\$ S + RS, SI

) Photos

) Others

)

TOTAL

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

STD106

Yr Regn:

3.11

CA1

Porsche Cayenne

c.c

3598

Black

A/C:

Insured / Std / NI / NA

118075

T/Radio: Insured / Std / NI / NA

W9122292215LA05264

Good

Inorder

Inorder

Nil / S/Rim

25-5/55 R18

25-5/55 R18

cont. in file

6

6

28/8/19

29/8/19

22/1

22/1

22/1

25/9/19 1/5 @ 10.000 confirmed with Alan.

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
2/1/19
1/5 @ 10,000
29/8/19 Sdy.

VEHICLE NO: SJD 10G

QTY	PARTICULAR			
1 PCS	FRONT BUMPER	1988.30	de/ueqat	\$2,880.00 ✓
1 PCS	FRONT BUMPER SIDE HOLDER N/S		11	\$199.00 x
1 PCS	FRONT BUMPER PDC SENSOR N/S	288.50	Shock	\$315.00 ✓
1 PCS	FRONT BUMPER DAYLIGHT LAMP N/S	836.90	one	\$1,005.00 ✓
1 PCS	FRONT BUMPER FOG LAMP N/S	482.30	one	\$625.00 ✓
1 PCS	FRONT BUMPER SIDE GRILLE N/S		one	\$245.00 ✓
1 PCS	FRONT BUMPER SIDE LAMP N/S	311.20	scr	\$399.00 ✓
1 PCS	FRONT BUMPER LOWER GARNISH	712.10	gnd	\$899.00 ✓
1 PCS	FRONT BUMPER SPONGE		11	\$288.00 x
1 PCS	FRONT BUMPER REINFORCEMENT		11	\$995.00 x
1 SET	FRONT BUMPER CLIPS		scr	\$60.00 ✓
1 PCS	HEADLAMP N/S	3267.10	scr	\$3,880.00 ✓
1 PCS	FRONT FENDER N/S		2	\$1,095.00 x
1 PCS	FRONT FENDER OUTER PROTECTOR GARNISH N/S	388.20	gnd	\$422.00 ✓
1 PCS	FRONT SHOCK ABSORBER N/S	822.00	bul	\$895.00 ✓
1 PCS	FRONT LOWER ARM N/S	898.10	bul	\$1,225.00 ✓
1 PCS	FRONT KNUCKLE ARM N/S	1425.20	bul	\$1,680.00 ✓
1 PCS	FRONT KNUCKLE ARM BEARING N/S	420	scr	\$560.00 ✓
1 PCS	FRONT STEERING RACK ASSY		scr	\$4,880.00 x
1 PCS	FRONT STEERING TIE ROD END A/S		bul	\$482.00 ✓
1 PCS	FRONT SPORT RIM N/S "18 INCH"		2	\$1,800.00 x
1 PCS	FRONT DRIVE SHAFT N/S		scr	\$2,102.00 x
				\$26,931.00
	LABOUR CHARGES			
	TO CHECK WIRING			\$80.00 20
	TO DISMANTLE & REFIX FRONT PDC SENSOR			\$80.00 50
	TO CONDUCT WHEEL ALIGNMENT			\$150.00 60
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE			\$380.00 150
	TO SPRAY RUST PROOFING		11	\$80.00 x
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$980.00 400
	TO PUTTY & SPRAY PAINTING			\$900.00 480
			TOTAL	\$29,581.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12628.30
102
11365.47
12525.47