



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 28/08/2019

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SG1695B
Case Reference Number	BUS/08/19/1053
Registration Date	11/2/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Muhamad Shahrizad Bin Sairi
Type of Accident	Side Swipe
Accident Date and Time	25/8/2019 8:18 PM
Accident Reported Date and Time	25/8/2019 12:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1695B - RIGHT REAR TO FRONT PORTION SGV209S (TP) - INSURED WITH AIG
Prepared Date and Time	26/8/2019 5:07 PM
Chassis Number	WEB62808323129412
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,650.00	\$0.00
Total Spray Cost	\$1,218.00	\$0.00
Total Spare Part Cost	\$5,909.71	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$9,777.71	\$0.00
Lump Sum Total	\$8,850.00	\$0.00
Number of Repair Days	6.0	5
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	26/08/2019 5:16 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve CLKIK)
w/kl m/kl d/kl
28/8/19, 2.22pm
5 dy
L/S
Ry AL spj



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/08/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,650.00	2120
Total Labour	\$2,650.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,218.00	1126
Total Spray Painting & Panel Beating	\$1,218.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009880	VE		LAMP, TAIL-REAR RH, FOR MB CITARO O530	1.00	\$1,261.71	10.00	\$1,135.54	Replace	/ BR
6010141	ENGINE	6287503206	FLAP, RADIATOR, FOR MB CITARO O530	1.00	\$5,445.00	10.00	\$4,900.50	Replace	/ DO
6010012	VE	0005446911	LAMP, SIDE MARKER, FOR MB CITARO O530 BUS	4.00	\$94.50	10.00	\$340.20	Replace	/ BR
6009909	BODY RH		BUMPER, REAR, RH, FOR MB CITARO O530	1.00	\$837.84	10.00	\$754.06	Replace	/ BR
6010010	VE		LAMP, EXTERIOR, REAR FOGLAMP, FOR MB CITARO	1.00	\$63.15	10.00	\$56.84	Replace	/ BR
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Replace	/ n/c
Total					\$7,902.20		\$7,387.14		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: