



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/09/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG1695B
Case Reference Number	BUS/08/19/1053
Registration Date	11/2/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Muhamad Shahrizad Bin Sairi
Type of Accident	Side Swipe
Accident Date and Time	25/8/2019 8:18 PM
Accident Reported Date and Time	25/8/2019 12:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103072
Special Instruction to ARC, if any	SG1695B - RIGHT REAR TO FRONT PORTION SGV209S (TP) - INSURED WITH AIG
Prepared Date and Time	26/8/2019 5:07 PM
Chassis Number	WEB62808323129412
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,650.00	\$2,120.00
Total Spray Cost	\$1,218.00	\$1,126.00
Total Spare Part Cost	\$5,909.71	\$5,909.71
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$9,777.71	\$9,155.71
Lump Sum Total	\$9,800.00	\$9,150.00
Number of Repair Days	6.0	5.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	26/08/2019 5:16 PM	28/08/2019 1:36 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/09/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,650.00	\$2,120.00
Total Labour	\$2,650.00	\$2,120.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,218.00	\$1,126.00
Total Spray Painting & Panel Beating	\$1,218.00	\$1,126.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009880	VE		LAMP, TAIL, REAR RH, FOR MB CITARO O530	1.00	\$1,261.71	10.00	\$1,135.54	Replace	Replace
6010141	ENGINE	6287503206	FLAP, RADIATOR, FOR MB CITARO O530	1.00	\$5,445.00	10.00	\$4,900.50	Replace	Replace
6010012	VE	0005446911	LAMP, SIDE MARKER, FOR MB CITARO O530 BUS	4.00	\$94.50	10.00	\$340.20	Replace	Replace
6009909	BODY RH		BUMPER, REAR, RH, FOR MB CITARO O530	1.00	\$837.84	10.00	\$754.06	Replace	Replace
6010010	VE		LAMP, EXTERIOR, REAR FOGLAMP, FOR MB CITARO	1.00	\$63.15	10.00	\$56.84	Replace	Replace
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Replace	Replace
Total					\$7,902.20		\$7,387.14		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

7387.14
- 20% Lurp Sum
5909.71
2120
1126
L/S - 9155.71
= 9150



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757105
FAX Number : 63685582
Estimator Telephone Number : 68682623
Accident Reporting Number : 68682672

Date Generated : 28/08/2019

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SG16958
Case Reference Number	BUS/08 19/1053
Registration Date	11/2/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Muhamad Shahrizad Bin Sari
Type of Accident	Side Swipe
Accident Date and Time	25/8/2019 8 18 PM
Accident Reported Date and Time	25/8/2019 12 45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG16958 - RIGHT REAR TO FRONT PORTION SGV209S (TP) - INSURED WITH AIG
Prepared Date and Time	26/8/2019 5 07 PM
Chassis Number	WEB62808323129412
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,850.00	\$0.00
Total Spray Cost	\$1,218.00	\$0.00
Total Spare Part Cost	\$5,909.71	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$9,777.71	\$0.00
Lump Sum Total	\$8,858.00	\$0.00
Number of Repair Days	5.0	5
Prepared / Adjusted By	Boon Chew Tay	
ARC Surveyor Sign Off Date	28/08/2019 5:18 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve CLKK)
with App doc
28/8/19, 2.22pm
S dy
L/S
RJ AL SM

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: