

ESTIMATE TO REPAIR

VEHICLE NO. : YN 7811 K
 MAKE : MITSUBISHI
 MODEL : CANTER FEB21ERB21ER4SDEB
 YEAR : 2014
 CHASSIS NO : FEB21EA01176

SURVEYOR NAME :
 DATE OF SURVEY : 24 FEB 2020
 TIME OF SURVEY :

DATE : 17-Feb-20
 DATE OF ACCIDENT : 23-Aug-19
 THIRD PARTY REF : SHD 4830 D
 THIRD PARTY REF : FIRST CAPITAL INSURANCE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper			\$ <i>B₁</i> 1,020.35	✓
2 pcs	front bumper side rubber		\$ 353.75	\$ <i>S₁</i> 707.50	X
1 pc	front grille			\$ 1,053.45	?
2 pcs	head lamp		\$ 501.47	\$ 1,002.94	?
2 pcs	tail lamp	<i>old cm</i>	\$ 194.25	\$ 388.50	✓
1 pc	rear no plate lamp			\$ <i>B₂</i> 79.82	✓
1 pc	rear bumper			\$ <i>B₃</i> 675.00	✓
	less 10%				\$ 4,927.56
					\$ 492.76
					\$ 4,434.80
1 pc	rear step wooden panel	S.Nett		\$ <i>CM</i> 300.00	✓
1 pc	rear end wooden panel	S.Nett		\$ <i>CM</i> 500.00	✓
1 set	number plate	S.Nett		\$ <i>B₁</i> 50.00	2500
	To putty & spray paint.			\$ 800.00	5000
	To check front wiring & front head lights			\$ 35.00	✓
	Labour charges.			\$ 600.00	4800
TG/VL	TOTAL				\$ 6,719.80

*Not Withhold
 1/1 day @?
 Resurvey After Paint
 4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Email: edmund@ltd.sg
 Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd