

ESTIMATE TO REPAIR

VEHICLE NO. : YN 7811 K
MAKE : MITSUBISHI
MODEL : CANTER FEB21ERB21ER4SDEB
YEAR : 2014
CHASSIS NO : FEB21EA01176

SURVEYOR NAME :
DATE OF SURVEY : 24 Feb 2020
TIME OF SURVEY :

DATE : 17-Feb-20
DATE OF ACCIDENT : 23-Aug-19
THIRD PARTY REF : SHD 4830 D
THIRD PARTY REF : FIRST CAPITAL INSURANCE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper			\$ B 1,020.35	✓
2 pcs	front bumper side rubber		\$ 353.75	\$ 707.50	X mtg cra
1 pc	front grille			\$ 1,053.45	? mtg cra
2 pcs	head lamp		\$ 501.47	\$ 1,002.94	? mtg cra
2 pcs	tail lamp	cls cm	\$ 194.25	\$ 388.50	✓ 194.25
1 pc	rear no plate lamp			\$ B 79.82	✓
1 pc	rear bumper			\$ B 675.00	✓
	less 10%			\$ 4,927.56	
				\$ 492.76	
				\$ 4,434.80	
1 pc	rear step wooden panel	S.Nett	3019.36	\$ CMA 300.00	✓
1 pc	rear end wooden panel	S.Nett	SN 825.00	\$ CMA 500.00	✓
1 set	number plate	S.Nett	Supply 713.29	\$ B 50.00	2500
	To putty & spray paint.		1015.00	\$ 800.00	500
	To check front wiring & front head lights		55.72	\$ 35.00	✓
	Labour charges.			\$ 600.00	480
TG/VL	TOTAL			\$ 6,719.80	
	Exhaust tail pipe			Not Authorised	
	#951.05			6/1 Aug 8?	
	233.76			Recovery After Repair	
	713.29			Today	
	photos email				
	6994 - 7006				
	29/02/20				
	email to				
	WhatsApp				
				4450	
				APPROVED	

