

ESTIMATE TO REPAIR

VEHICLE NO. : YN 7811 K
 MAKE : MITSUBISHI
 MODEL : CANTER FEB21ERB21ER4SDEB
 YEAR : 2014
 CHASSIS NO : FEB21EA01176

SURVEYOR NAME :
 DATE OF SURVEY : 24 Feb 2020
 TIME OF SURVEY :

DATE : 17-Feb-20
 DATE OF ACCIDENT : 23-Aug-19
 THIRD PARTY REF : SHD 4830 D
 THIRD PARTY REF : FIRST CAPITAL INSURANCE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper			\$ B 1,020.35	✓
2 pcs	front bumper side rubber		\$ 353.75	\$ 707.50	X
1 pc	front grille			\$ 1,053.45	2
2 pcs	head lamp		\$ 501.47	\$ 1,002.94	2
2 pcs	tail lamp	cls cm	\$ 194.25	\$ 388.50	4 x 194.25
1 pc	rear no plate lamp			\$ B 79.82	✓
1 pc	rear bumper			\$ B 675.00	✓
	less 10%			\$ 4,927.56	
				\$ 492.76	
				\$ 4,434.80	
1 pc	rear step wooden panel	S.Nett	3019.36	\$ CM 300.00	✓
1 pc	rear end wooden panel	S.Nett	SN 825.00	\$ CM 500.00	✓
1 set	number plate	S.Nett	Supply 713.29	\$ B 50.00	2500
	To putty & spray paint.		1015.00	\$ 800.00	500
	To check front wiring & front head lights		55.72	\$ 35.00	✓
	Labour charges.			\$ 600.00	480
TG/VL	TOTAL			\$ 6,719.80	
	Exhaust tail pipe			Not with handle	
	#951.05			6/1 Aug 8?	
	233.76			Recovery After Repair	
	713.29			today	
	photos email			29/02/20	
	6994 - 7006			email to	
				waath	
				4450	
				APPROVED	

