

Khamchua

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 8608 0808

Email: auburnauto.claim@gmail.com

Vehicle No: SME425C

Model: TOYOTA ALLION

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Front bumper side grille X	\$ 180.00
1	Front Bumper Lower Grill X	\$ 150.00
1	Front bonnet lock X	\$ 380.00
1	Front bonnet inner rubber X	\$ 68.20
1	Front bonnet outer rubber X	\$ 86.20
1	Front bumper inner sponge / BR	\$ 135.90
1	Front bumper side retainers / BR	\$ 145.20
1	Front fender inner shield X	\$ 426.50
1	Front headlamp lower bracket X	\$ 186.00
1	Front grille chrome moulding X	\$ 285.90
1	Front grille logo / N/C	\$ 188.80
1	Front grille / BR	\$ 628.60
2	Front bumper reinforcement X	\$ 680.60
1	Front bonnet lock (lock panel) / 00	\$ 380.00
2	L/H and R/H Mud Flap X	\$ 160.00
2	L/H and R/H Headlight / CUT	\$ 1,220.00
1	Bumper (front) / BR	\$ 850.00
1	Front Left Passenger Rim X	\$ 420.00
1	Front R/H Fender X	\$ 660.00
1	Car Plate and Carplate Holder / CUT	\$ 190.00 35
1	Chrome "Toyota" logo X	\$ 135.00
1	Condenser / 00	\$ 780.00
1	Radiator / 00	\$ 450.00
1	Bumper inner Foam / BR	\$ 380.00

\$ 9,166.90

c/f: \$ 9,616.90

S/N. Labour Charges

1	To establish mirror motor & reset wiring focussing	\$	150.00	X
2	To check wiring and reset headlamps focussing.	\$	180.00	30
3	To apply tuff kote.	\$	200.00	30
4	Panel beating.	\$	1,400.00	400
5	To sand-down, patch-work, re-spray paint.	\$	1,400.00	400
		\$	3,330.00	

Total Repair Cost: \$ 12,496.90

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve CLKK
(Contact) 8322 8813
(Email) _____
(Signature) 
(Date/Time) 29/8/19

with prejudice
3 days
L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: