

# AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 8608 0808

Email: auburnauto.claim@gmail.com

Vehicle No: SME425C

Model: TOYOTA ALLION

| QTY                      | Description                         | Repairer's Estimate |          |
|--------------------------|-------------------------------------|---------------------|----------|
| Spare Parts - List Items |                                     |                     |          |
| 1                        | Front bumper side grille X          | \$                  | 180.00   |
| 1                        | Front Bumper Lower Grill X          | \$                  | 150.00   |
| 1                        | Front bonnet lock (lock panel) - 00 | \$                  | 380.00   |
| 1                        | Front bonnet inner rubber X         | \$                  | 68.20    |
| 1                        | Front bonnet outer rubber X         | \$                  | 86.20    |
| 1                        | Front bumper inner sponge / BR      | \$                  | 135.90   |
| 1                        | Front bumper side retainers / BR    | \$                  | 145.20   |
| 1                        | Front fender inner shield X         | \$                  | 426.50   |
| 1                        | Front headlamp lower bracket X      | \$                  | 186.00   |
| 1                        | Front grille chrome moulding X      | \$                  | 285.90   |
| 1                        | Front grille logo / MC              | \$                  | 188.80   |
| 1                        | Front grille / BR                   | \$                  | 628.60   |
| 2                        | Front bumper reinforcement X        | \$                  | 680.60   |
| 1                        | Front bonnet lock X                 | \$                  | 380.00   |
| 2                        | L/H and R/H Mud Flap X              | \$                  | 160.00   |
| 2                        | L/H and R/H Headlight / CUT         | \$                  | 1,220.00 |
| 1                        | Bonnet X                            | \$                  | 950.00   |
| 1                        | Front Left Passenger Rim X          | \$                  | 420.00   |
| 1                        | Front R/H Fender X                  | \$                  | 660.00   |
| 1                        | Car Plate and Carplate Holder X     | \$                  | 190.00   |
| 1                        | Chrome "Toyota" logo X              | \$                  | 135.00   |
| 1                        | Condenser / 00                      | \$                  | 780.00   |

add

Radiator /

\$ 8,436.90

c/f: \$ 9,616.90

**S/N. Labour Charges**

|   |                                                    |    |                 |     |
|---|----------------------------------------------------|----|-----------------|-----|
| 1 | To establish mirror motor & reset wiring focussing | \$ | 150.00          | X   |
| 2 | To check wiring and reset headlamps focussing.     | \$ | 180.00          | 30  |
| 3 | To apply tuff kote.                                | \$ | 200.00          | 30  |
| 4 | Panel beating.                                     | \$ | 1,400.00        | 400 |
| 5 | To sand-down, patch-work, re-spray paint.          | \$ | 1,400.00        | 300 |
|   |                                                    | \$ | <u>3,330.00</u> |     |

Total Repair Cost: \$ 11,766.90

Survey: 1st / 2nd / 3rd (delete accordingly)

**Surveyor Details:**

(Name) Steve (LKK)  
(Contact) 8322 8813  
(Email) Steve.chen@lkkauh.com  
(Signature)   
(Date/Time) 29/8/19, 10.20 am

3 days

L/S

**LKK Auto Consultants** hereby notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_