

Khoo

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 8608 0808

Email: auburnauto.claim@gmail.com

Vehicle No: SME425C

Model: TOYOTA ALLION

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Front bumper side grille X <i>N/A</i>	\$ 180.00 X
1	Front Bumper Lower Grill X <i>N/A</i>	\$ 150.00 X
1	Front bonnet lock X <i>N/A</i>	\$ 380.00 X
1	Front bonnet inner rubber X <i>N/A</i>	\$ 68.20 X
1	Front bonnet outer rubber X <i>N/A</i>	\$ 86.20 X
1	Front bumper inner sponge / <i>BR</i>	\$ 135.90 /
1	Front bumper side retainers / <i>BR</i>	\$ 145.20 /
1	Front fender inner shield X <i>N/A</i>	\$ 426.50 X
1	Front headlamp lower bracket X <i>N/A</i>	\$ 186.00 X
1	Front grille chrome moulding X <i>N/A</i>	\$ 285.90 X
1	Front grille logo / <i>MC</i>	\$ 188.80 <i>78</i> /
1	Front grille / <i>BR</i>	\$ 628.60 <i>349</i> /
2	Front bumper reinforcement X <i>N/A</i>	\$ 680.60 X
1	Front bonnet lock (lock panel) / <i>DD</i>	\$ 380.00 <i>182.25</i> /
2	L/H and R/H Mud Flap X <i>N/A</i>	\$ 160.00 X
2	L/H and R/H Headlight / <i>CUT</i>	\$ 1,220.00 /
1	Bumper (front) / <i>BR</i>	\$ 850.00 <i>682</i> /
1	Front Left Passenger Rim X <i>N/A</i>	\$ 420.00 X
1	Front R/H Fender X <i>N/A</i>	\$ 660.00 X
1	Car Plate and Carplate Holder / <i>CUT</i>	\$ 190.00 <i>35</i> /
1	Chrome "Toyota" logo X <i>N/A</i>	\$ 135.00 X
1	Condenser / <i>DD</i>	\$ 780.00 /
1	Radiator / <i>DD</i>	\$ 450.00 /
1	Bumper inner Foam / <i>BR</i>	\$ 380.00 <i>128</i> /

\$ 9,166.90

Pg 1 of 2

4185.35
- 25%
3139.01

c/f: \$ 9,616.90

S/N.	Labour Charges		
1	To establish mirror motor & reset wiring focussing	\$	150.00 X
2	To check wiring and reset headlamps focussing.	\$	180.00 30
3	To apply tuff kote.	\$	200.00 30
4	Panel beating.	\$	1,400.00 400
5	To sand-down, patch-work, re-spray paint.	\$	1,400.00 400
		\$	3,330.00

Total Repair Cost: \$ 12,496.90

P- 3139.01
L- 860
3999.01
L/S - 3199.20
= 3200

860

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve CLKK
(Contact) 8322 8813
(Email)
(Signature)
(Date/Time) 29/8/19

W/L for/di
3 days
L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: