

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : GXXX9128N
CASCIANI SANDRO EDUARDO
BLK 26 BEDOK NORTH DRIVE
#09-35
SINGAPORE 465499
TEL : FAX :
PH : 91064838
ATTN :

ESTIMATE BILL

Number : EB00005250
Date : 27/08/2019
Case No : AD00010630
Vehicle No : SCY2282Y
Chassis : JM6BM42A8G0326501
Year of Mfr 2015
Policy No
Model : MAZDA 3 4-DOOR
SEDAN 1.5L SP.6EAT

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER	1.0	448.22	20	358.58
2	FRONT GRILLE	1.0	77.94	20	62.35
3	FRONT BUMPER TOP GARNISH	1.0	168.41	20	134.73
4	FRONT EMBLEM	1.0	25.49	20	20.39
List Price - Parts Sub Total					576.05
Parts Total					576.05
5	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00
6	SPRAY PAINT ON THE AFFECTED AREAS	1.0	300.00	0	300.00
7	ANTI-RUST COATING	1.0	50.00	0	50.00
Labour 1 Sub Total					850.00
SINGAPORE DOLLARS : ONE THOUSAND FIVE HUNDRED TWENTY-FIVE AND CENTS EIGHTY-SEVEN ONLY					1,525.87
Less Excess					0.00
SUBTOTAL					1,426.05
GST 7.00%					99.82
TOTAL					1,525.87

Date of accident : 17/08/2019 04:00 PM. Place : SENTOSA GOLF CLUB PANAMARICANA CARPARK

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE