

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 301 BEDOK INDUSTRIAL PARK 1
BEDOK NORTH VLE 4
#01-2008/1012 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 8355 6243 8121
ROC No: 90094141D GST Reg No: 20-004141D

TO: GXXX9128N

CASCIANI SANDRO F DU ARDO
BLK 26 BEDOK NORTH DRIVE
#09-35
SINGAPORE 465499
TEL: 6441 5655
PTEL 91064838
MTEL:

ESTIMATE BILL

Number: EB00005250
Date: 17-08-2019
Case No: AD00010630
Vehicle No: SCY2282Y
Chassis: IM6BM42 Asc0326501
Year of Mfr: 2015
Policy No:
Model: MAZDA 3 4-DOOR
SEDAN 1.5L SP 6E M

Term:

Sn	DESCRIPTION	QTY	UNIT PRICE	DISC	AMOUNT
1	FRONT BUMPER	1.0	448.22	20	358.58
2	FRONT GRILLE	1.0	77.94	20	62.35
3	FRONT BUMPER TOP GARNISH	1.0	168.41	20	134.73
4	FRONT EMBLEM	1.0	25.49	20	20.39
List Price - Parts Sub Total					576.05
Parts Total					576.05
5	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00
6	SPRAY PAINT ON THE AFFECTED AREAS	1.0	300.00	0	300.00
7	ANTI-RUST COATING	1.0	50.00	0	50.00
Labour Sub Total					850.00
p/p 470.39					
p. 25.49					
202					
20.39					
470.39					
SINGAPORE DOLLARS ONE THOUSAND FIVE HUNDRED TWENTY-FIVE AND CENTS EIGHTY-SEVEN ONLY			Less Excess	0.00	
			SUBTOTAL	1,426.05	
			GST 7.00%	99.82	
			TOTAL	1,525.87	

Date of accident: 17-08-2019 04:00 PM Place: SENTOSA GOLF CLUB PANAMERICAN CARPARK

L & O L

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE