

INSP/011

INS. CASE OWNER:

CC4 / FWD1901

5288

A963-9

LKK:
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

26/8/19

Date / Time:

26/8/19

Registered in Merimen:

26/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLH 5016M

Name of Insured:

CHRISTOPHER ZEN KIMBERLY

Insured Tel No.:

HP:

27/8/19

Excess Sec II :SS

D.O.A.:

Claim No.:

1201900029552

Policy No.:

DVPV2018-00016674

Make / Model:

TANCHA

Place of Accident:

PIE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGC 34292



INSRS:

WSP:

Tel:

Liability:

RMKS:

perfect
works

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
	5/10/19 2-8	Non-Reporting ltr (1st):	
	6/11/19 1-1	Non-Reporting ltr (2nd):	
12/10	- REC LOR to P (Pending LOD).	Non-Reporting ltr (Final):	
4/11	- File pass RT type report.	Notification ltr (if non-pickup):	
6/12	- Pending mandale approval. ✓	Call OI:	
12/12	- offer \$4907.45 (Pending acceptance).	After call ltr to OI:	
	- Rate @ \$4907.45, file pass SUH send DV.	Documentation Check List:	Handler Typist
23/12/19	- File pass to LSP to close.	Notification ltr (if non-pickup)	☒ ☐
		After call ltr to OI:	☒ ☐
		Authorisation To Act:	☒ ☐
		Release Voucher:	☒ ☐
		Final Repair Bill:	☒ ☐
		Car Rental Invoice:	☒ ☐
		Towing Invoice:	☒ ☐
		LTA / GIA:	☒ ☐
		Medical Bill:	☒ ☐
		PIR:	☒ ☐
		Mandate/Reject Instruction:	☒ ☐
		LOD	☒ ☐
		Payment Breakdown Form:	☒ ☐
		Post-Repair Photos:	☒ ☐
		Others:	☒ ☐
PRELIMINARY ADVICE Date/Time:		Sent By:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	46	Confirm by: Adrian	
SS	4000.00 (12 days) Reduction: \$1400.40 = 7%	Email	Call
FINAL SETTLEMENT Date/Time: 15/12/19		Confirm with: CHM	
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 28	Email	Call
Repair Cost:	SS 4000.00	If NO or B 28, Ass. Lia: 07.	
Loss of Rental (LOR):	SS 900.00 (9 days) x \$100	(c-s (01 3rd)	
Loss of Use (LOU):	SS (5 x days)	COPY SENT WIM 09	
Loss of Income (LOI):	SS (5 x days)		
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LO ☐ [Tick only one]	1) Claim status: Normal/Reject/Private Settle	
GIA/UTA Search:	SS 9.45	2) Report Format: TP	
Medical:	SS -	3) Survey fee: 0500/-	
Disbursement:	SS - (e.g. Tow/Independent)		
Legal Cost:	SS -		
Total:	SS 4907.45	Global Sum SS:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS 4907.45	Name 1:	Garage 833 WP
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

PERFECT WERKZ

Block 25 Kaki Bukit Road 4 #06-51 Synergy@KB Singapore 417800
HP: 92712214 Fax: (65) 69664526 ROC : 53364512C

LIM CHOON HUAN
25 KAKI BUKIT ROAD4
06-51 SYNERGY @KB
Singapore 417800

29th August 2019

Tp FWD.
Cecilia

Accident date: 27th AUGUST 2019

Estimated repair cost for vehicle no: SGC3529Z TOYOTA COROLLA ALTIS 1.6 A

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Backed</i>		\$733.50 ✓
2	2	Rear boot lid hinges <i>Repair</i>	\$86.40	\$172.80 +
3	1	Rear boot lid 1.6 logo		\$30.00 ✓
4	1	Rear Boot Lid VVTI logo <i>new</i>		\$50.30 ✓
5	1	Rear boot lid emble logo		\$53.40 ✓
6	1	Rear boot lid Corolla logo		\$49.34 ✓
7	1	Rear boot lid Altis logo		\$50.28 ✓
8	2	Rear boot lid side reflector <i>new</i>	\$285.00	\$570.00 ✓
9	1	Rear boot lid inner lock <i>new</i>		\$122.80 ✓
10	1	Rear boot lid inner rubber <i>new</i>		\$205.00 ✓
11	1	Rear boot lid center moulding <i>new</i>		\$203.75 ✓
12	2	Rear tail lamp <i>new</i>	\$320.00	\$640.00 ✓
13	2	Rear tail lamp panel <i>Repair</i>	\$383.20	\$766.40 +
14	4	Rear tail lamp clips <i>new</i>	\$12.90	\$51.60 20
15	1	Rear bumper <i>Distorted</i>		\$550.65 ✓
16	2	Rear bumper side bracket outer <i>new</i>	\$28.50	\$57.00 ✓
17	2	Rear bumper side bracket inner <i>new</i>	\$38.80	\$77.60 ✓
18	8	Rear bumper clips <i>new</i>	\$5.00	\$40.00 30
19	1	Rear bumper reverse sensor <i>Damaged</i>		\$300.00 200(20)
20	2	Rear bumper bracket <i>Dented</i>	\$83.10	\$166.20 ✓
21	1	Rear bumper reinforcement <i>new</i>		\$350.00 +
22	1	Rear bumper inner sponge <i>new</i>		\$180.00 +
23	1	Rear end panel <i>Distorted</i>		\$655.00 ✓
24	1	Rear End Panel Top Garnish <i>Dented</i>		\$179.28 ✓
25	2	Rear fender inner trim board <i>new</i>	\$420.20	\$840.40 +
26	10	Rear fender inner trim board clips <i>new</i>	\$5.00	\$50.00 +
27	1	Rear spare tire panel top cover <i>new</i>		\$329.20 ✓
28	1	Rear spare tire panel sealant <i>new</i>		\$250.00 +
29	1	Rear spare tire panel lock <i>new</i>		\$220.00 ✓
30	1	Front bonnet <i>Distorted</i>		\$680.75 ✓
31	2	Front bonnet hinges <i>new</i>	\$55.20	\$110.40 +
32	1	Front bonnet lock <i>Damaged</i>		\$155.00 ✓
33	1	Front bonnet inner rubber <i>new</i>		\$114.00 +
34	6	Front bonnet inner rubber clips <i>new</i>	\$12.90	\$77.40 +
35	1	Front bonnet inner sponge <i>crushed</i>		\$184.20 ✓
36	1	Front bonnet lock panel <i>new</i>		\$121.10 ✓
37	10	Front bonnet inner sponge clips <i>new</i>	\$12.90	\$129.00 30
38	2	Front headlamp <i>new</i>	\$950.00	\$1,900.00 770.80
39	1	Front grille <i>new</i>		\$280.70 ✓
40	2	Front grille side nizzer <i>new</i>	\$0.00	\$0.00 +
41	1	Front grille emble logo <i>new</i>		\$65.00 ✓
42	1	Front bumper <i>Distorted</i>		\$415.65 ✓
43	2	Front Bumper Side Bracket <i>new</i>	\$53.10	\$106.20 64
44	8	Front bumper clips <i>new</i>	\$12.90	\$103.20 30

45	1	Front bumper number plate	Best		\$50.00 ✓
46	1	Front bumper reinforcement	Best		\$281.70 ✓
47	2	Front bumper fog lamp cover	HM	\$131.10	\$262.20 ✓
48	2	front bumper reinforcement bracket	HM	\$131.10	\$262.20 ✓
49	1	front support panel	Rep's		\$1,810.20 ✓

6721.65

Subtotal :- \$15,053.40

2041.23

211.20

Labour charges

To remove & re-fix cushion

\$100.00 60

To remove & re-fix reverse sensor

\$100.00 50

To remove & re-fix rear windscreen

\$120.00 X

Gum

\$50.00 X

To Check Wiring System

2630

\$60.00 ✓

Tuff kote

\$120.00 60

Panel beating

\$1,200.00 ✓

Spray painting

\$1,200.00 ✓

Subtotal :- \$2,950.00

Total :- \$18,003.40

total: 7871.23.

L/S: 41K (Net Value)

12 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	012F
Vehicle Information	
Vehicle No.:	SGC3529Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	3ZZ4537110
Chassis No.:	MR053ZEC107109072
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,772.00
Original Registration Date:	19 Jan 2006
First Registration Date:	19 Jan 2006
Transfer Count:	2
Actual ARF Paid:	\$15,157.00
PARF Eligibility Information	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Information	
COE Expiry Date:	18 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$28,317.00
COE Rebate Amount:	\$7,870.00
Total Rebate Amount:	\$7,870.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Aug 2019

OK

Exclusive Roadshow Deal - up to \$10,000 off all Toyota Models.

Bedok Mall, Level 1 Atrium, 28 Aug - 3 Sep 2019


SEARCH Price Range Depreciation > 10 year(s) Vehicle Type

Used Car Comparison

— Comparing 4 Vehicles —

Toyota Corolla Altis 1.6A (COE till 10/2020)



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 04/2021)



Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 05/2021)



Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 04/2021)



Add to Shortlist

CAR DETAILS

Price	\$12,998	\$14,779	\$15,800	\$14,500
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	24-Oct-2005	18-Apr-2006	15-May-2006	27-Jun-2006
Manufactured	2005	2006	2006	2006
Mileage	-	-	-	187,890 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,598 cc	1,598 cc	1,598 cc	1,598 cc
Road Tax	\$1,039 /yr	\$965 /yr	\$965 /yr	\$965 /yr
Power	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)
Curb Weight	1,115 kg	1,115 kg	1,115 kg	1,115 kg
Features	Fuel Efficient And Powerful 1.6L 16 Valve DOHC VVTi Engine, Smooth Auto Transmission With Ect, Dual SRS Airbags, ABS, Digital Climate Control Aircon.	-	-	Fuel Efficient And 1 DOHC VVTi Engine Transmission With Airbags, ABS, Digit Aircon.
Accessories	Original Leather Seats, Multi Steering Control And Retractable Mirrors With Indicators.	-	-	Beige Original Leat Steering Control Ar With Indicators.
Description	Good Buy! Best Deal! Call Now! \$0 Drive Away! Rock Solid Altis! Fuel Consumption Of 14km/L. Very High Paper Value! Minimum Controlled Lost! STA Evaluation Welcome! All Loan Schemes Available! 100% Safe Purchase From A Premium Dealer! Call Our Friendly Sales Staffs For A Test Drive Today!	-	-	Rare 2k Candy Pur Loan Applicable! A Needed! Extremely Risk With High Pap Tear Mostly Replac Now To Schedule / Appointment! Oper
COE	\$28,399	\$23,039	\$22,789	\$23,039
OMV	\$16,493	\$15,950	\$15,950	\$15,950
ARF	\$13,655	\$17,545	\$17,545	\$17,545
Depreciation	\$11,240 /yr	\$9,020 /yr	\$9,230 /yr	\$8,660 /yr
No. of Owners	4	4	3	3
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	COE Car	COE Car, Direct Owner Sale	COE Car	COE Car
Availability	Available	Available	Available	Available
Remarks	COE expiry date 2021-04-30	COE expiry date 2021-04-30	COE expiry date 2021-04-30	COE expiry date 2021-04-30

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Wednesday, 28 August 2019 1:55 PM
To: admin-d@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com
Cc: lionel.tan@fwd.com; motorclaims.sg@fwd.com
Subject: SGC3529Z & SLH5016M doa 27/8/19
Attachments: SLH5016M OI GIA.pdf

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Venessa Chan - SGUser

Sent: Wednesday, August 28, 2019 1:54 PM

To: chan pick yuen

Cc: Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

Subject: SGC3529Z & SLH5016M doa 27/8/19

Hi Chris,

Thank you for your selection of LKK Auto Consultants.
We will proceed to assign survey.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims

P. Chris

T: 3.14p.m

V: 14


E: ✓

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]

Sent: Wednesday, August 28, 2019 1:50 PM

To: Venessa Chan - SGUser

Cc: Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

Subject: Re: SGC3529Z & SLH5016M doa 27/8/19

Dear Sir / Mdm ,

LKK Auto Consultant Pte Ltd.

please let us have your surveyor reply soon. Thanks

Get [Outlook for iOS](#)

From: venessa.chan@fwd.com <venessa.chan@fwd.com>

Sent: Wednesday, August 28, 2019 1:49:02 PM

To: chris_chanbebe@hotmail.com <chris_chanbebe@hotmail.com>

Cc: motorclaims.sg@fwd.com <motorclaims.sg@fwd.com>; lionel.tan@fwd.com <lionel.tan@fwd.com>

Subject: SGC3529Z & SLH5016M doa 27/8/19

WITHOUT PREJUDICE

Dear Chris,

We refer to your email dated on 28.08.2019 of the PRI Notice of your client's vehicle SGC3529Z.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]

Sent: Wednesday, August 28, 2019 1:38 PM

To: Motor Claims SG - SG Common

Subject: SGC3529Z & SLH5016M doa 27/8/19

Dear Sir / Mdm ,

Enclosed is our clients GIA report.

Please let us have your 10 name list of surveyor to survey our clients vehicle: SGC3529Z . Thanks

Best Regards

Chris Chan

Perfect Werkz

Hp:92712214

Get [Outlook for iOS](#)

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT

been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Print Received Message

This mail is associated with :

***SGC3529Z (1201900025552)**

[SLH5016M]

TP

Lim Choon Huan

Aug 27 2019 12:00AM

[CRISTOPHER TEH KIM BENG]

Perfect Werkz

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 10/12/2019 14:02 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4907.45) - SGC3529Z - Claim Handler: Lionel Tan

Approved:4907.45.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2019 Edit Reg		28 Aug 2019 00:00 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CRISTOPHER TEH KIM BENG , ID: 572725498								
Main Claimant:	Lim Choon Huan , ID: S1420012F								
Vehicle Reg. No.:	SGC3529Z	Date of Loss:	27/08/2019 00:00 - :59 [163 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900025552	Policy/Cover Note No.:	PNPV2018-00014624 (Comprehensive) Coverage: 07/11/2018 - 06/11/2019						
Vehicle Reg. No. (Insured):	SLH5016M	Policy No. (Claimant):	P10135281R00						
		Excess:							
Repairer:	Perfect Werkz (HQ) NO. 25 KAKI BUKIT ROAD 4 #06-S1 SYNERGY @ KB, 417800 Kaki Bukit - Tel: 87788855								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Claimant's Insurer:	Auto & General Insurance (Singapore) Pte. Limited. (HQ) - Tel: 6540 2180								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (10/12/2019): Alert - Adj Mandate Approved (S\$4907.45) - SGC3529Z - Claim Handler: Lionel Tan									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGC3529Z (1201900025552)
[SLH5016M]

TP

Lim Choon Huan

Aug 27 2019 12:00AM

[CRISTOPHER TEH KIM BENG]

Perfect Werkz

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/10/19 14:06	General View		Load JPG	☒
2	18/10/19 14:06	General View		Load JPG	☒
3	18/10/19 14:06	General View		Load JPG	☒
4	18/10/19 14:06	General View		Load JPG	☒
5	18/10/19 14:06	General View		Load JPG	☒
6	18/10/19 14:06	General View		Load JPG	☒
7	18/10/19 14:06	General View		Load JPG	☒
8	18/10/19 14:06	General View		Load JPG	☒
9	18/10/19 14:06	General View		Load JPG	☒
10	18/10/19 14:06	General View		Load JPG	☒
11	18/10/19 14:06	General View		Load JPG	☒
12	18/10/19 14:06	General View		Load JPG	☒
13	18/10/19 14:06	General View		Load JPG	☒
14	18/10/19 14:06	General View		Load JPG	☒
15	18/10/19 14:06	General View		Load JPG	☒
16	18/10/19 14:06	General View		Load JPG	☒
17	18/10/19 14:06	General View		Load JPG	☒
18	18/10/19 14:06	General View		Load JPG	☒
19	18/10/19 14:06	General View		Load JPG	☒
20	18/10/19 14:06	General View		Load JPG	☒
21	18/10/19 14:06	General View		Load JPG	☒
22	18/10/19 14:06	General View		Load JPG	☒
23	18/10/19 14:06	General View		Load JPG	☒
24	18/10/19 14:06	General View		Load JPG	☒
25	18/10/19 14:06	General View		Load JPG	☒
26	18/10/19 14:06	General View		Load JPG	☒
27	18/10/19 14:06	General View		Load JPG	☒
28	18/10/19 14:06	General View		Load JPG	☒
29	18/10/19 14:06	General View		Load JPG	☒
30	18/10/19 14:06	General View		Load JPG	☒
31	18/10/19 14:06	General View		Load JPG	☒
32	18/10/19 14:06	General View		Load JPG	☒
33	18/10/19 14:06	General View		Load JPG	☒
34	18/10/19 14:06	General View		Load JPG	☒
35	18/10/19 14:06	General View		Load JPG	☒
36	18/10/19 14:06	General View		Load JPG	☒
37	18/10/19 14:06	General View		Load JPG	☒
38	18/10/19 14:06	General View		Load JPG	☒
39	18/10/19 14:06	General View		Load JPG	☒
40	18/10/19 14:06	General View		Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	18/10/19 14:06	General View	 Load JPG	☒
42	18/10/19 14:06	General View	 Load JPG	☒
43	18/10/19 14:06	General View	 Load JPG	☒
44	18/10/19 14:06	General View	 Load JPG	☒
45	18/10/19 14:06	General View	 Load JPG	☒
46	18/10/19 14:06	General View	 Load JPG	☒
47	18/10/19 14:06	General View	 Load JPG	☒
48	18/10/19 14:06	General View	 Load JPG	☒
49	18/10/19 14:06	General View	 Load JPG	☒
50	18/10/19 14:06	General View	 Load JPG	☒
51	18/10/19 14:06	General View	 Load JPG	☒
52	18/10/19 14:06	General View	 Load JPG	☒
53	18/10/19 14:08	Reinspection Photo	 Load JPG	☒
54	18/10/19 14:08	Reinspection Photo	 Load JPG	☒
55	18/10/19 14:08	Reinspection Photo	 Load JPG	☒
56	18/10/19 14:08	Reinspection Photo	 Load JPG	☒
57	18/10/19 14:08	Reinspection Photo	 Load JPG	☒
58	18/10/19 14:08	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/19 15:46	EMAIL FROM FWD DD 29082019	 Load PDF	
2	29/08/19 15:46	FWD EMAIL TO OI DD 28082019	 Load PDF	
3	29/08/19 15:46	OI GIA REPORT	 Load PDF	
4	03/09/19 11:45	TP GIA REPORT	 Load PDF	
5	03/09/19 11:45	TP ESTIMATE	 Load PDF	
6	05/12/19 14:55	WORKSHOP INVOICE	 Load PDF	
7	05/12/19 14:55	RENTAL RECEIPT	 Load PDF	
8	05/12/19 14:55	LTA SEARCH	 Load PDF	
9	27/12/19 14:54	AUTHORISATION TO ACT FORM	 Load PDF	
10	27/12/19 14:54	Release Voucher	 Load PDF	
11	27/12/19 14:54	LOD	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLH5016M (Insd veh)	Model:	TOYOTA COROLLA 1.6 (A)
	SGC3529Z (TP veh)		
Date of Accident:	27/08/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	18,003.40
Final Repair Cost	:	\$	4,000.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	900.00 9 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,907.45
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____ 100 _____ (%)			
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%) Assessed Liability (*): _____ 0 _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	GARAGE 833 LLP	:	\$ 4,907.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

27 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19015288/AGB3Q2

Date: 27/12/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00014624
 Claimant: SGC3529Z Insured Vehicle No: SLH5016M
 Vehicle No: SGC3529Z Insured Vehicle No: SLH5016M
 Date of Loss: 27/08/2019 Nature of Claim: TP Claim No: 1201900025552

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGC3529Z
 Make & Model: TOYOTA COROLLA, 1.6 (A) Engine No: 3ZZ4537110
 Reg. Date: 19/01/2006 (Man. Year: 2005) Chassis No: MR053ZEC107109072
 Colour: Silver Odometer: 376057 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/50R16 Rear Tyre Size: 195/50R16
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,053.40	5,241.24	9,812.16	65.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	2,630.00	320.00	10.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,003.40	7,871.24	10,132.16	56.28
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	18,003.40	4,000.00	14,003.40	77.78
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,907.45		

INSPECTION

Date of Assignment: 28/08/2019
 Date Inspected: 28/08/2019 Inspected At: Perfect Werkz (HQ)
 NO. 25 KAKI BUKIT ROAD 4 #06-51
 SYNERGY @ KB
 Singapore 417800
 Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2019)
Parts:	143	TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC3529Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	733.50 F	*733.50 FL
2	2		*REAR BOOT LID HINGES	Repair	172.80 F	*- FL
3	1		*REAR BOOT LID 1.6 LOGO	Necessary	30.00 F	*30.00 FL
4	1		*REAR BOOT LID VVTI LOGO	Necessary	50.30 F	*50.30 FL
5	1		*REAR BOOT LID EMBLE LOGO	Necessary	53.40 F	*53.40 FL
6	1		*REAR BOOT LID COROLLA LOGO	Necessary	49.34 F	*49.34 FL
7	1		*REAR BOOT LID ALTIS LOGO	Necessary	50.28 F	*50.28 FL
8	2		*REAR BOOT LID SIDE REFLECTOR	Not Necessary	570.00 F	*- FL
9	1		*REAR BOOT LID INNER LOCK	Damaged	122.80 F	*122.80 FL
10	1		*REAR BOOT LID INNER RUBBER	Cut	205.00 F	*205.00 FL
11	1		*REAR BOOT LID CENTER MOULDING	Not Necessary	203.75 F	*- FL
12	2		*REAR TAIL LAMP	Cracked	640.00 F	*640.00 FL
13	2		*REAR TAIL LAMP PANEL	Repair	766.40 F	*- FL
14	4		*REAR TAIL LAMP CLIPS	Necessary	51.60 F	*20.00 FL
15	1		*REAR BUMPER	Distorted	550.65 F	*550.65 FL
16	2		*REAR BUMPER SIDE BRACKET OUTER	Necessary	57.00 F	*57.00 FL
17	2		*REAR BUMPER SIDE BRACKET INNER	Not Necessary	77.60 F	*- FL
18	8		*REAR BUMPER CLIPS	Necessary	40.00 F	*30.00 FL
19	1		*REAR BUMPER REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
20	2		*REAR BUMPER BRACKET	Dented	166.20 F	*166.20 FL
21	1		*REAR BUMPER REINFORCEMENT	Not Necessary	350.00 F	*- FL
22	1		*REAR BUMPER INNER SPONGE	Not Necessary	180.00 F	*- FL
23	1		*REAR END PANEL	Distorted	655.00 F	*655.00 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	179.28 F	*179.28 FL
25	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	840.40 F	*- FL
26	10		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FL
27	1		*REAR SPARE TIRE PANEL TOP COVER	Not Necessary	329.20 F	*- FL
28	1		*REAR SPARE TIRE PANEL SEALANT	Not Necessary	250.00 F	*- FL
29	1		*REAR SPARE TIRE PANEL LOCK	Not Necessary	220.00 F	*- FL
30	1		*FRONT BONNET	Distorted	680.75 F	*680.75 FL
31	2		*FRONT BONNET HINGES	Not Necessary	110.40 F	*- FL
32	1		*FRONT BONNET LOCK	Damaged	155.00 F	*155.00 FL
33	1		*FRONT BONNET INNER RUBBER	Not Necessary	114.00 F	*- FL
34	6		*FRONT BONNET INNER RUBBER CLIPS	Not Necessary	77.40 F	*- FL
35	1		*FRONT BONNET INNER SPONGE	Crumpled	184.20 F	*184.20 FL
36	1		*FRONT BONNET LOCK PANEL	Bent	121.10 F	*121.10 FL
37	10		*FRONT BONNET INNER SPONGE CLIPS	Necessary	129.00 F	*30.00 FL
38	2		*FRONT HEADLAMP	Cracked	1,900.00 F	*770.80 FL
39	1		*FRONT GRILLE	Cracked	280.70 F	*280.70 FL
40	2		*FRONT GRILLE SIDE NIZZER (NPA)	Not Necessary	0.00 F	*- FL
41	1		*FRONT GRILLE EMBLE LOGO	Necessary	65.00 F	*65.00 FL
42	1		*FRONT BUMPER	Deformed	415.65 F	*415.65 FL
43	2		*FRONT BUMPER SIDE BRACKET	Necessary	106.20 F	*64.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	8		*FRONT BUMPER CLIPS	Necessary	103.20 F	*30.00 FL
45	1		*FRONT BUMPER NUMBER PLATE	Bent	50.00 F	*50.00 FL
46	1		*FRONT BUMPER REINFORCEMENT	Bent	281.70 F	*281.70 FL
47	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	262.20 F	*- FL
48	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	262.20 F	*- FL
49	1		*FRONT SUPPORT PANEL	Repair	1,810.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,053.40	6,921.65
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,680.41
Total Parts (\$\$)	15,053.40	5,241.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX CUSHION	New	100.00	60.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	0.00
4	GUM	New	50.00	0.00
5	TO CHECK WIRING SYSTEM	New	60.00	60.00
6	TUFF KOTE	New	120.00	60.00
7	PANEL BEATING	New	1,200.00	1,200.00
8	SPRAY PAINTING	New	1,200.00	1,200.00
Gross Labour Cost (S\$)			2,950.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >