

PERFECT WERKZ

Block 25 Kaki Bukit Road 4 #06-51 Synergy@KB Singapore 417800
HP: 92712214 Fax: (65) 69664526 ROC : 53364512C

LIM CHOON HUAN
25 KAKI BUKIT ROAD4
06-51 SYNERGY @KB
Singapore 417800

29th August 2019

TP FWD.
Cecilia.

Accident date: 27th AUGUST 2019

Estimated repair cost for vehicle no: SGC3529Z TOYOTA COROLLA ALTIS 1.6 A

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Buckled</i>		\$733.50	✓
2	2	Rear boot lid hinges <i>Repair</i>	\$86.40	\$172.80	+
3	1	Rear boot lid 1.6 logo		\$30.00	✓
4	1	Rear Boot Lid VVTI logo <i>NEW</i>		\$50.30	✓
5	1	Rear boot lid emble logo		\$53.40	✓
6	1	Rear boot lid Corolla logo		\$49.34	✓
7	1	Rear boot lid Altis logo		\$50.28	✓
8	2	Rear boot lid side reflector <i>Not new</i>	\$285.00	\$570.00	X
9	1	Rear boot lid inner lock <i>Damaged</i>		\$122.80	✓
10	1	Rear boot lid inner rubber <i>lt</i>		\$205.00	✓
11	1	Rear boot lid center moulding <i>new</i>		\$203.75	X
12	2	Rear tail lamp <i>cracked</i>	\$320.00	\$640.00	✓
13	2	Rear tail lamp panel <i>Repair</i>	\$383.20	\$766.40	X
14	4	Rear tail lamp clips <i>New</i>	\$12.90	\$51.60	20
15	1	Rear bumper <i>Distorted</i>		\$550.65	✓
16	2	Rear bumper side bracket outer <i>new</i>	\$28.50	\$57.00	✓
17	2	Rear bumper side bracket inner <i>new</i>	\$38.80	\$77.60	X
18	8	Rear bumper clips <i>new</i>	\$5.00	\$40.00	30
19	1	Rear bumper reverse sensor <i>Damaged</i>		\$300.00	200(SN)
20	2	Rear bumper bracket <i>Dented</i>	\$83.10	\$166.20	✓
21	1	Rear bumper reinforcement <i>new</i>		\$350.00	X
22	1	Rear bumper inner sponge <i>new</i>		\$180.00	X
23	1	Rear end panel <i>Distorted</i>		\$655.00	✓
24	1	Rear End Panel Top Garnish <i>Delaid</i>		\$179.28	✓
25	2	Rear fender inner trim board <i>3 new</i>	\$420.20	\$840.40	+
26	10	Rear fender inner trim board clips	\$5.00	\$50.00	X
27	1	Rear spare tire panel top cover <i>new</i>		\$329.20	X
28	1	Rear spare tire panel sealant <i>new</i>		\$250.00	X
29	1	Rear spare tire panel lock <i>new</i>		\$220.00	X
30	1	Front bonnet <i>Distorted</i>		\$680.75	✓
31	2	Front bonnet hinges <i>new</i>	\$55.20	\$110.40	+
32	1	Front bonnet lock <i>Damaged</i>		\$155.00	✓
33	1	Front bonnet inner rubber <i>new</i>		\$114.00	+
34	6	Front bonnet inner rubber clips <i>new</i>	\$12.90	\$77.40	+
35	1	Front bonnet inner sponge <i>crushed</i>		\$184.20	✓
36	1	Front bonnet lock panel <i>Bent</i>		\$121.10	✓
37	10	Front bonnet inner sponge clips <i>New</i>	\$12.90	\$129.00	30
38	2	Front headlamp <i>cracked</i>	\$950.00	\$1,900.00	770.80
39	1	Front grille <i>cracked</i>		\$280.70	✓
40	2	Front grille side nizzer <i>new</i>	\$0.00	\$0.00	+
41	1	Front grille emble logo <i>new</i>		\$65.00	✓
42	1	Front bumper <i>Delaid</i>		\$415.65	✓
43	2	Front Bumper Side Bracket <i>new</i>	\$53.10	\$106.20	64
44	8	Front bumper clips <i>new</i>	\$12.90	\$103.20	30

45	1	Front bumper number plate	Bent		\$50.00	✓
46	1	Front bumper reinforcement	Bent		\$281.70	✓
47	2	Front bumper fog lamp cover	new	\$131.10	\$262.20	X
48	2	front bumper reinforcement bracket	HM	\$131.10	\$262.20	X
49	1	front support panel	Repair		\$1,810.20	X

6721.65

Subtotal :- \$15,053.40

5041.23

S.V. 20

Labour charges

To remove & re-fix cushion

\$100.00 60

To remove & re-fix reverse sensor

\$100.00 50

To remove & re-fix rear windscreen

\$120.00 X

Gum

\$50.00 X

To Check Wiring System

2630

\$60.00 ✓

Tuff kote

\$120.00 60

Panel beating

\$1,200.00 ✓

Spray painting

\$1,200.00 ✓

Subtotal :- \$2,950.00

Total :- \$18,003.40

total: 7871.23

4/5: AK (Nett Value)

12 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: