

PERFECT WERKZ

Block 25 Kaki Bukit Road 4 #06-51 Synergy@KB Singapore 417800
HP: 92712214 Fax: (65) 69664526 ROC : 53364512C

LIM CHOON HUAN
25 KAKI BUKIT ROAD4
06-51 SYNERGY @KB
Singapore 417800

29th August 2019

Accident date: 27th AUGUST 2019

Estimated repair cost for vehicle no: SGC3529Z TOYOTA COROLLA ALTIS 1.6 A

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$733.50
2	2	Rear boot lid hinges	\$86.40	\$172.80
3	1	Rear boot lid 1.6 logo		\$30.00
4	1	Rear Boot Lid VVTI logo		\$50.30
5	1	Rear boot lid emble logo		\$53.40
6	1	Rear boot lid Corolla logo		\$49.34
7	1	Rear boot lid Altis logo		\$50.28
8	2	Rear boot lid side reflector	\$285.00	\$570.00
9	1	Rear boot lid inner lock		\$122.80
10	1	Rear boot lid inner rubber		\$205.00
11	1	Rear boot lid center moulding		\$203.75
12	2	Rear tail lamp	\$320.00	\$640.00
13	2	Rear tail lamp panel	\$383.20	\$766.40
14	4	Rear tail lamp clips	\$12.90	\$51.60
15	1	Rear bumper		\$550.65
16	2	Rear bumper side bracket outer	\$28.50	\$57.00
17	2	Rear bumper side bracket inner	\$38.80	\$77.60
18	8	Rear bumper clips	\$5.00	\$40.00
19	1	Rear bumper reverse sensor		\$300.00
20	2	Rear bumper bracket	\$83.10	\$166.20
21	1	Rear bumper reinforcement		\$350.00
22	1	Rear bumper inner sponge		\$180.00
23	1	Rear end panel		\$655.00
24	1	Rear End Panel Top Garnish		\$179.28
25	2	Rear fender inner trim board	\$420.20	\$840.40
26	10	Rear fender inner trim board clips	\$5.00	\$50.00
27	1	Rear spare tire panel top cover		\$329.20
28	1	Rear spare tire panel sealant		\$250.00
29	1	Rear spare tire panel lock		\$220.00
30	1	Front bonnet		\$680.75
31	2	Front bonnet hinges	\$55.20	\$110.40
32	1	Front bonnet lock		\$155.00
33	1	Front bonnet inner rubber		\$114.00
34	6	Front bonnet inner rubber clips	\$12.90	\$77.40
35	1	Front bonnet inner sponge		\$184.20
36	1	Front bonnet lock panel		\$121.10
37	10	Front bonnet inner sponge clips	\$12.90	\$129.00
38	2	Front headlamp	\$950.00	\$1,900.00
39	1	Front grille		\$280.70
40	2	Front grille side nizzer	\$0.00	\$0.00
41	1	Front grille emble logo		\$65.00
42	1	Front bumper		\$415.65
43	2	Front Bumper Side Bracket	\$53.10	\$106.20
44	8	Front bumper clips	\$12.90	\$103.20

45	1	Front bumper number plate		\$50.00
46	1	Front bumper reinforcement		\$281.70
47	2	Front bumper fog lamp cover	\$131.10	\$262.20
48	2	front bumper reinforcement bracket	\$131.10	\$262.20
49	1	front support panel		\$1,810.20

Subtotal :- \$15,053.40

Labour charges

To remove & re-fix cushion \$100.00

To remove & re-fix reverse sensor \$100.00

To remove & re-fix rear windscreen \$120.00

Gum \$50.00

To Check Wiring System \$60.00

Tuff kote \$120.00

Panel beating \$1,200.00

Spray painting \$1,200.00

Subtotal :- \$2,950.00

Total:- \$18,003.40