

L/S 140 Ton


KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19004162	Page	1
	8 SHENTON WAY	Date	: 23. Sep 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	:		
Registration No	: SKQ7665R	Engine No	: L15B73625180		
Chassis No	: MRHFC1660JT000287	Date Time	: 23. Sep 2019 8:59:55 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2018	Surveyor Name	:		
Owner's Name	: SOH JUNQIANG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 22/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:SOH JUNQIANG						
	OWNER INSURER:AVIVA LTD						
	ACC DATE:22/08/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:AXA INSURANCE						
	TP VEH:SDV 8059 X						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>bl</i>	1	45.00		45.00	3.15	48.15
71101-TEA-T00ZZ	FACEFR.BUMPER <i>de</i>	1	579.90	25	434.92	30.44	465.36
71102-TBA-A00	GRILLE, FR.BUMPER LOWER <i>X SUC</i>	1	69.70	25	52.27	3.66	55.93
71130-TEA-T00	BEAM COMPFR.BUMPER <i>? X SUC</i>	1	345.90	25	259.42	18.16	277.58
71193-TEA-T01	SPACERR.FR.BUMPER SIDE <i>de</i>	1	10.40	25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE <i>de</i>	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER <i>de</i>	16	2.30	25	27.60	1.93	29.53
71121-TEA-T02	BASE,FR.GRILLE CHROME <i>com</i>	1	79.90	25	59.92	4.19	64.11
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE <i>X SUC</i>	1	85.60	25	64.20	4.49	68.69
71129-TEA-T01	EXTENSION ASSYL.FR.GRILLE <i>X SUC</i>	1	85.60	25	64.20	4.49	68.69
71125-TEA-T01	MOLDINGFR.GRILLE <i>de</i>	1	100.40	25	75.30	5.27	80.57
75700-TBA-A00	EMBLEM <i>? de</i>	1	15.00	25	11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM <i>? de</i>	2	2.10	25	3.15	0.22	3.37
Sum Item					<u>1112.83</u>	<u>77.89</u>	<u>1,190.72</u>
BOSUN	SUNDRIES	1	100.00	<i>30</i>	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	380.00	<i>280</i>	380.00	26.60	406.60
BKBU01R	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	1	1500.00	<i>560</i>	1500.00	105.00	1605.00

Printed on 23/9/2019 9:05:45 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19004162	Page	2
	: 8 SHENTON WAY	Date	: 23. Sep 2019		
	: #27-01 AXA TOWER	Customer No.	: WZA006		
	: SINGAPORE 068811	Svc Advisor	:		
Registration No	: SKQ7665R	Engine No	: L15B73625180		
Chassis No	: MRHFC1660JT000287	Date Time	: 23. Sep 2019 8:59:55 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2018	Surveyor Name	:		
Owner's Name	: SOH JUNQIANG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 22/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1000.00	450	1000.00	70.00	1070.00
Sum Labor					2980.00	208.60	3,188.60

Survey By

Date & Time

Excess

Status

Signature

Total Amount 4,092.83 286.49 4,379.32

Total (Inclusive of GST) 4,379.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 23/9/2019 9:05:45 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0127537 / AXA INSURANCE
Chassis No: MRHFC1660JT000287
License No: SKQ7665R
Mileage: 178
Engine No: L15B73625180

Document No: SVO19061651
Printed By: JACKNG
Order Date: 23. September 2019
Order Time: 11:02:12 AM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Includ	Amount
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:SOH JUNQIANG						
	OWNER INSURER:AVIVA LTD						
	ACC DATE:22/08/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:AXA INSURANCE						
	TP VEH:SDV 8059 X						
	SUPPLEMENTARY PART						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00 ✓		45.00	3.15	48.15
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90 ✓	25	434.92	30.44	465.36
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40 ✓	25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40 ✓	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	16	2.30 ✓	25	27.60	1.93	29.53
71121-TEA-T02	BASE,FR.GRILLE CHROME	1	79.90 ✓	25	59.92	4.19	64.11
75700-TBA-A00	EMBLEM	1	15.00 ✓	25	11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM	2	2.10 ✓	25	3.15	0.22	3.37
91555-TBA-K01	CLIPAMBIENT SENSOR (S) New ✓	1	5.40	25	4.05	0.28	4.33
	SUM PARTS:				601.49	42.10	643.59
BOSUN		1	30.00 ✓		30.00	2.10	32.10
	SUNDRIES						
BML01I		1	280.00 ✓		280.00	19.60	299.60
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)						
BKBU01R	0671	1	560.00 ✓		560.00	39.20	599.20
	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON ATTACHMENT ITEMS.						
BP02R	1610	1	450.00 ✓		450.00	31.50	481.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)						
	SUM LABOUR:				1,320.00	92.40	1,412.40
	TOTAL SGD				1,921.49	134.50	2,055.99
	Total Payable (SGD)						2,055.99

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0127537 / SOH JUNQIANG

Chassis No: MRHFC1660JT000287

License No: SKQ7665R

Mileage: 178

Engine No: L15B73625180

Document No: SVO19061651

Printed By: JACKNG

Order Date: 23. September 2019

Order Time: 11:02:12 AM

Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Incl	
						Amount	GST
91555-TBA-K01	CLIPAMBIENT SENSOR <i>new</i>	1	5.40	25	4.05	0.28	4.33
					SUM PARTS:	4.05	0.28
							4.33
					TOTAL SGD	4.05	0.28
							4.33

Total Payable (SGD)

4.33

GST Amount is calculated from individual line(s)