

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 208C****AAD1908-198***Not Authen'd*  
*1/Imp &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

28 AUG 2019

**SHD 208C**

VF1ABL15AUC281574

RENAULT

LATITUDE

25.8.19

**AXA**

2/10/2015

| PART |                                 | LIST |          |
|------|---------------------------------|------|----------|
| 1    | BUMPER COVER FRT                | \$   | 1,259.42 |
| 1    | BUMPER SPOILER FRT              | \$   | 181.75   |
| 1    | BUMPER ABSORBER FRT             | \$   | 394.68   |
| 1    | BUMPER RETAINER FRT RH          | \$   | 151.41   |
| 1    | BUMPER SUPPORT FRT              | \$   | 123.88   |
| 1    | BUMPER UNDERTRAY FRT            | \$   | 472.83   |
| 1    | BUMPER GRILLE LOWER FRT         | \$   | 266.80   |
| 1    | BUMPER FOG LAMP GRILLE RH       | \$   | 207.21   |
| 1    | BUMPER BEAM FRT                 | \$   | 914.08   |
| 1    | HEADLAMP RH                     | \$   | 1,184.43 |
| 1    | HEADLAMP PANEL FRT RH           | \$   | 152.15   |
| 1    | FENDER PANEL FRT RH             | \$   | 783.83   |
| 1    | WHEELARCH FRT RH                | \$   | 278.84   |
| 1    | FENDER BRACKET LOWER RH         | \$   | 15.79    |
| 1    | FENDER INSULATOR RH             | \$   | 130.84   |
| 1    | TOW COVER FRT                   | \$   | 28.61    |
| 1    | FRONT BRACE PANEL               | \$   | 177.22   |
| 1    | RADIATOR GRILLE                 | \$   | 1,707.78 |
| 1    | RADIATOR GRILLE BADGE 'RENAULT' | \$   | 225.36   |
| 1    | RADIATOR GRILLE FRAME           | \$   | 1,353.75 |
| 1    | FRAME FULL SUPPORT PANEL        | \$   | 615.90   |
| 1    | FRAME FULL SUPPORT BRACKET      | \$   | 89.79    |
| 1    | BONNET                          | \$   | 1,941.63 |
| 1    | BONNET INSULATOR                | \$   | 405.73   |
| 1    | BONNET STRUT LH                 | \$   | 88.61    |
| 1    | BONNET STRUT RH                 | \$   | 88.61    |
| 1    | BONNET HINGE LH                 | \$   | 348.31   |

X

**Trans-cab Auto Services Pte Ltd****AAD1908-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 208C**

|              |                       |           |                  |
|--------------|-----------------------|-----------|------------------|
| 1            | BONNET HINGE RH       | \$        | 348.31           |
| 1            | BONNET LOCK           | \$        | 305.48           |
| 1            | BONNET CABLE          | \$        | 119.19           |
| 1            | BONNET CABLE COVER    | \$        | 161.03           |
| 1            | BONNET SEAL OUTER     | \$        | 92.36            |
| 1            | BONNET SEAL INNER     | \$        | 157.28           |
| 1            | DOOR PANEL FRT RH     | \$        | 2,844.66         |
| 1            | DOOR MIRROR ASSY RH   | \$        | 1,483.40         |
| 1            | WIPER RESERVOIR MOTOR | \$        | 270.06           |
| 1            | WIPER RESERVOIR       | \$        | 348.25           |
| 1            | WIPER RESERVOIR NECK  | \$        | 136.11           |
| 1            | DOOR HARNESS WIRE RH  | \$        | 2,670.00         |
| <b>TOTAL</b> |                       | <b>\$</b> | <b>22,525.36</b> |
| <b>10%</b>   |                       | <b>\$</b> | <b>2,252.54</b>  |
|              |                       | <b>\$</b> | <b>20,272.83</b> |

**Special Nett**

|      |                                    |    |        |
|------|------------------------------------|----|--------|
| 1    | FRONT DOOR STICKER 'Trans-cab'     | \$ | 80.00  |
| 1    | FRONT DOOR STICKER 'Classic'       | \$ | 80.00  |
| 1    | BUMPER CLIP FRT                    | \$ | 66.00  |
| 1    | BUMPER BRACKET CLIP FRT RH         | \$ | 12.00  |
| 1    | BUMPER SUPPORT CLIP FRT RH         | \$ | 10.50  |
| 1    | BUMPER GRILLE LOWER CLIP           | \$ | 69.00  |
| 1SET | FRAME FULL SUPPORT PANEL CLIP      | \$ | 70.00  |
| 2    | FRAME FULL SUPPORT PANEL NUT       | \$ | 20.00  |
| 2    | FRAME FULL SUPPORT PANEL STUD      | \$ | 30.00  |
| 1    | WHEELARCH CLIP FRT RH              | \$ | 30.50  |
| 1    | FRONT RIGHT TYRE                   | \$ | 300.00 |
| 1    | FRONT RIGHT TYRE RIM               | \$ | 380.00 |
| 1SET | Front licence plate with holder    | \$ | 80.00  |
| 1SET | RADIATOR GRILLE SCREW              | \$ | 16.00  |
| 1SET | RADIATOR GRILLE FRAME CLIP         | \$ | 52.00  |
| 1    | WINDSCREEN SEALANT                 | \$ | 253.80 |
| 1    | FRONT WINDSCREEN MOULDING          | \$ | 120.00 |
| 1    | FRONT WINDSCREEN INNER SPONGE SEAL | \$ | 100.00 |
| 6    | BONNET INSULATOR CLIP L70Y         | \$ | 7.30   |

**Trans-cab Auto Services Pte Ltd****AAD1908-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 208C**

|   |                               |    |         |
|---|-------------------------------|----|---------|
| 2 | BONNET STRUT L70Y             | \$ | 88.61 X |
| 2 | BONNET CABLE CLIP L70Y        | \$ | 6.31 X  |
| 2 | BONNET CABLE COVER SCREW L70Y | \$ | 10.85 X |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>1,882.88</b> |
|--------------|-----------|-----------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>22,155.70</b> |
|--------------------|-----------|------------------|

**LABOUR**

|                                                                                                                           |    |               |
|---------------------------------------------------------------------------------------------------------------------------|----|---------------|
| Putty and spray painting of the affected portion.                                                                         | \$ | 6,000.00 2201 |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | na 6,000.00 X |
| To rust-proofing of the affected areas.                                                                                   | \$ | 170.00 X      |
| To transfer of front windscreen fittings and conduct water seepage test.                                                  | \$ | 170.00 X      |
| To transfer of front fender fittings, attachment and perform water seepage test.                                          | \$ | 380.00 X      |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | 170.00 X      |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 220.00 X      |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00 X      |
| To transfer of front bumper fittings, attachment and perform water seepage test.                                          | \$ | 380.00 X      |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | 380.00 X      |

**Trans-cab Auto Services Pte Ltd****AAD1908-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 208C**

To transfer of front door fittings, attachment and  
perform water seepage test.

\$ *nn* 380.00 X

To transfer of bonnet fittings, attachment and  
perform water seepage test.

\$ *4* 380.00 X

Labour charge to mount and dismount vehicle on jig  
bench, to facilitate repair.

\$ *4* 380.00 X**TOTAL \$ 15,180.00****Over All Total \$ 37,335.70****LUMP SUM (REPAIR DAY)****20 DAYS***1 day*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: