

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 208C**AAD1908-198***Not Authored*
1/10/15

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

28 AUG 2019

SHD 208C

VF1ABL15AUC281574

RENAULT

LATITUDE

25.8.19

AXA

2/10/2015

PART		LIST	
1	BUMPER COVER FRT	\$	1,259.42
1	BUMPER SPOILER FRT	\$	181.75
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT RH	\$	151.41
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	266.80
1	BUMPER FOG LAMP GRILLE RH	\$	207.21
1	BUMPER BEAM FRT	\$	914.08
1	HEADLAMP RH	\$	1,184.43
1	HEADLAMP PANEL FRT RH	\$	152.15
1	FENDER PANEL FRT RH	\$	783.83
1	WHEELARCH FRT RH	\$	278.84
1	FENDER BRACKET LOWER RH	\$	15.79
1	FENDER INSULATOR RH	\$	130.84
1	TOW COVER FRT	\$	28.61
1	FRONT BRACE PANEL	\$	177.22
1	RADIATOR GRILLE	\$	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36
1	RADIATOR GRILLE FRAME	\$	1,353.75
1	FRAME FULL SUPPORT PANEL	\$	615.90
1	FRAME FULL SUPPORT BRACKET	\$	89.79
1	BONNET	\$	1,941.63
1	BONNET INSULATOR	\$	405.73
1	BONNET STRUT LH	\$	88.61
1	BONNET STRUT RH	\$	88.61
1	BONNET HINGE LH	\$	348.31

X

Trans-cab Auto Services Pte Ltd**AAD1908-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 208C

1	BONNET HINGE RH	\$	348.31
1	BONNET LOCK	\$	305.48
1	BONNET CABLE	\$	119.19
1	BONNET CABLE COVER	\$	161.03
1	BONNET SEAL OUTER	\$	92.36
1	BONNET SEAL INNER	\$	157.28
1	DOOR PANEL FRT RH	\$	2,844.66
1	DOOR MIRROR ASSY RH	\$	1,483.40
1	WIPER RESERVOIR MOTOR	\$	270.06
1	WIPER RESERVOIR	\$	348.25
1	WIPER RESERVOIR NECK	\$	136.11
1	DOOR HARNESS WIRE RH	\$	2,670.00
TOTAL		\$	22,525.36
10%		\$	2,252.54
		\$	20,272.83

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00
1	FRONT DOOR STICKER 'Classic'	\$	80.00
1	BUMPER CLIP FRT	\$	66.00
1	BUMPER BRACKET CLIP FRT RH	\$	12.00
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50
1	BUMPER GRILLE LOWER CLIP	\$	69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00
1	WHEELARCH CLIP FRT RH	\$	30.50
1	FRONT RIGHT TYRE	\$	300.00
1	FRONT RIGHT TYRE RIM	\$	380.00
1SET	Front licence plate with holder	\$	80.00
1SET	RADIATOR GRILLE SCREW	\$	16.00
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00
1	WINDSCREEN SEALANT	\$	253.80
1	FRONT WINDSCREEN MOULDING	\$	120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00
6	BONNET INSULATOR CLIP L70Y	\$	7.30

Trans-cab Auto Services Pte Ltd**AAD1908-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 208C

2	BONNET STRUT L70Y	\$	88.61 X
2	BONNET CABLE CLIP L70Y	\$	6.31 X
2	BONNET CABLE COVER SCREW L70Y	\$	10.85 X

TOTAL	\$	1,882.88
--------------	-----------	-----------------

TOTAL PARTS	\$	22,155.70
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00 2201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	na 6,000.00 X
To rust-proofing of the affected areas.	\$	4 170.00 X
To transfer of front windscreen fittings and conduct water seepage test.	\$	4 170.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	4 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00 X
To check steering geometry and computer wheel alignment	\$	4 220.00 X
To Check Electrical Lighting Concerned.	\$	4 170.00 X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	4 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1908-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 208C

To transfer of front door fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 X

To transfer of bonnet fittings, attachment and
perform water seepage test.

\$ *4* 380.00 X

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *4* 380.00 X**TOTAL \$ 15,180.00****Over All Total \$ 37,335.70****LUMP SUM (REPAIR DAY)****20 DAYS***1 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: