

ANCHOR

INS. CASE OWNER:

Peter

CC4 ASM AXA1901

5299, R1 9/19

LKK
IDAC:

Surveyor:

Rasul

DOI:

ASSIGNMENT
10/9/19

Date / Time:

21/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR 3430K

Name of Insured:

SENG SUBE KHOR

Insured Tel No.:

HP:

21/8/19

Excess Sec II :SS

D.O.A.:

Claim No.:

S9M02V8Z (174778)

Policy No.:

VRI/4A420489

Make / Model:

MERCEDES

Place of Accident:

PIR

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

G8G 602P



INSRS:
WSP: Falcon
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
		Non-Reporting Itr (1st):	
		Non-Reporting Itr (2nd):	
		Non-Reporting Itr (Final):	
		Notification Itr (if non-pickup):	
		Call OI:	
		After call Itr to OI:	
		Documentation Check List: Handler	Typist
		Notification Itr (if non-pickup):	
		After call Itr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:	Post-Repair Photos:	Others:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	Email	Call	
Repair Cost:	45	SS 1650.00 (4 days) Reduction: \$1569.05 % 49				
FINAL SETTLEMENT	Date/Time: 4/2/2020	Confirm with: Andy	Email	Call		
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27			
Repair Cost:	(W/ART) SS 1765.50					
Loss of Rental (LOR):	SS 425.00	(4 days) x \$107 (W/ART)				
Loss of Use (LOU):	SS -	(S x days)				
Loss of Income (LOI):	SS -	(S x days)				
LOR only ☒	LOU only ☐	LOR + LOU ☐	LOR + LO ☐	[Tick only one]		
GIA/LTA Search	SS / 2.00					
Medical:	SS -					
Disbursement:	SS -	(e.g. Tow/ Independent)				
Legal Cost:	SS -					
Total:	SS 2195.50	Global Sum SS:				
FINAL PAYMENT	Date/Time:	Confirm with:	Email	Call		
Payee 1:	SS 2195.50	Name 1:	Falcon - Avv Auto Services Pte Ltd			
Payee 2: (Strike if N.A.)	SS	Name 2:				
Payee 3: (Strike if N.A.)	SS	Name 3:				

✓ GIB

CORP SECT



FALCON-AIR

POWER HYDRAULICS & ENGINEERING PTE LTD
C/O BLK K NO.8 PANDAN LOOP SINGAPORE
128226

Attention : Motor Claim Department
Contact : 82643063

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003525

Date : 29/08/2019
Vehicle Num : GBG6021P
Make/Model : TOYOTA DYNA
Chassis/Eng# : KDY31-8027989
Accident Date : 25/08/2019
Claim No :
Reference : TP VS AXA
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	RH TAIL LAMP <i>cm</i>		220.00
2.	1	RH TAIL LAMP HOLDER <i>XNN</i>		71.60
3.	1	TAILGATE <i>bl</i>		1,010.00
4.	1	DYNA STICKER <i>cm</i>		32.00
5.	1	CORNER RUBBER <i>mc</i>		43.00
6.	1	RH SIDE GATE LOCK <i>XNN</i>		113.70
7.	1	REAR END PANEL <i>repair</i>		584.30
8.	1	REAR NUMBER PLATE BASE <i>bl</i>		145.80
List Total S\$:				2,225.40
25.00% Discount S\$:				556.35
				1,669.05
SPECIAL NETT ITEMS				
1.	1	70 KM/HR STICKER <i>re</i>		10.00
2.	1	REAR NUMBER PLATE <i>ce</i>		40.00
Special Nett Total S\$:				50.00
LABOUR :				
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				550.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of FalconAir Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-DPOWER HYDRAULICS & ENGINEERING PTE LTD
C/O BLK K NO.8 PANDAN LOOP SINGAPORE
128226Attention: Motor Claim Department
Contact: 82643063

Estimate: ES003525

Date: 29/08/2019
Vehicle Num: GBG6021P
Make/Model: TOYOTA DYNA
Chassis/Eng#: KDY31-8027989
Accident Date: 25/08/2019
Claim No.:
Reference: TP VS AXA
Policy No.:

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO RUSTPROOF ON ACCIDENT DAMAGE AREAS^{MV}
TO CUT OUT REWELD REAR END PANEL. REPAIR RH SIDE LOWER
BODY, RH SIDE GATE INCLUDES KNOCKING & REPLACEMENT
OF PARTS

400 ~~700.00~~

Labour Total S\$:

1,500.00

SingDollars: Three Thousand Two Hundred Nineteen & Cents Five Only

E. & O.E.

Total S\$:

3,219.05

for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
the Reparer of the following:

- To survey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Total parts survey & fit without Reparer's fee
- No illegal modification is allowed
- Supplementary work is subject to final approval of Reparer

Acknowledged by Reparer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Cecilia



FALCON-AIR

POWER HYDRAULICS & ENGINEERING PTE LTD
C/O BLK K NO 8 PANDAN LOOP SINGAPORE
128228

Attention: Motor Claim Department
Contact: 82643063

Cecilia
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-0

Estimate: ES003525

Date: 29/08/2019
Vehicle Num: G8G8021P
Make/Model: TOYOTA DYNA
Chassis/Eng: KDY31-8027369
Accident Date: 25/08/2019
Claim No:
Reference: TP VS AXA
Policy No:

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS:				
1.	1	RH TAIL LAMP <i>cm</i>		220.00
2.	1	RH TAIL LAMP HOLDER <i>X 302</i>		71.60
3.	1	TAILGATE <i>hl</i>		1,010.00
4.	1	DYNA STICKER <i>an</i>		32.00
5.	1	CORNER RUBBER <i>ms</i>		48.00
6.	1	RH SIDE GATE LOCK <i>X 302</i>		113.70
7.	1	REAR END PANEL <i>repair</i>		584.30
8.	1	REAR NUMBER PLATE BASE <i>hl</i>		145.80
List Total S\$				2,225.40
25.00% Discount S\$				556.35
				1,669.05
SPECIAL NETT ITEMS:				
1.	1	70 KM/HR STICKER <i>an</i>		10.00
2.	1	REAR NUMBER PLATE <i>an</i>		35 420.00
Special Nett Total S\$				50.00
LABOUR:				
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				550 550.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD
a subsidiary of FalconAir Holdings Pte Ltd

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862
Branches: Tampines 2: 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6789-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128228) Tel: 6779-5665 Fax: 6779-1110
Websites: www.falconair.com.sg E-mail: ems@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

**FALCON-AIR**

POWER HYDRAULICS & ENGINEERING PTE LTD
 C/O BLK K NO. 8 RANDAN LOOP SINGAPORE
 128226

Attention: Motor Claim Department
 Contact: 82643063

Estimate: ES003525

Date: 29/08/2019
 Vehicle Num: GBG6021P
 Make/Model: TOYOTA DYNA
 Chassis/Eng: KDY31-8027989
 Accident Date: 25/08/2019
 Claim No:
 Reference: TP VS AXA
 Policy No:

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO RUSTPROOF ON ACCIDENT DAMAGE AREAS
 TO CUT OUT REWELD REAR END PANEL. REPAIR RH SIDE LOWER
 BODY. RH SIDE GATE INCLUDES KNOCKING & REPLACEMENT
 OF PARTS

400 ~~700.00~~

Labour Total S\$:

1,500.00

Form
Hp 90010068
4 days
4/5
10/09/19 @ 1625
Resy after repair

SingDollars: Three Thousand Two Hundred Nineteen & Cents Five Only

E & O.E.

Total S\$

3,219.05

for FALCON AIR AUTO SERVICES PTE LTD

L&K Auto Consultants hereby notify the Repairer of the following:

- To retaining below-mentioned policy number
- To display damaged property during recovery
- Parts prices are subject to confirmation
- Third party claims is not a liability of the Repairer
- No legal responsibility is assumed
- Supplementary claims must be returned
- Is subject to final appraisal from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of FalconAir Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 900A #01-200 S(28840) Tel: 6779-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 & 2) #01-202/203 Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: ertel@falconair.com.sg

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003525

Date : 02/09/2019
Vehicle Num. : GBG6021P
Make/Model : TOYOTA DYNA
Chassis/Eng# : KDY31-8027989
Accident Date : 25/08/2019
Claim No. :
Reference : TP VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	RH TAIL LAMP		220.00
2.	1	RH TAIL LAMP HOLDER X		X
3.	1	TAILGATE		1,010.00
4.	1	DYNA STICKER		32.00
5.	1	CORNER RUBBER		48.00
6.	1	RH SIDE GATE LOCK X		X
7.	1	REAR END PANEL X		X
8.	1	REAR NUMBER PLATE BASE		145.80
List Total S\$:				1,455.80
25.00% Discount S\$:				363.95
				1,091.85 ✓
SPECIAL NETT ITEMS :				
1.	1	70 KM/HR STICKER		10.00
2.	1	REAR NUMBER PLATE		35.00
Special Nett Total S\$:				45.00 ✓
LABOUR :				
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				550.00

CONTINUE / ...

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003525

Date : 02/09/2019
Vehicle Num : GBG6021P
Make/Model : TOYOTA DYNA
Chassis/Eng# : KDY31-8027989
Accident Date : 25/08/2019
Claim No :
Reference : TP VS AXA
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO RUSTPROOF ON ACCIDENT DAMAGE AREAS TO CUT OUT REWELD REAR END PANEL, REPAIR RH SIDE LOWER BODY, RH SIDE GATE INCLUDES KNOCKING & REPLACEMENT OF PARTS		400.00
		Labour Total S\$:		950.00

SingDollars : Two Thousand Eighty-Six & Cents Eighty-Five Only

	E. & O.E.	Total S\$:	2,086.85
	L/S LESS 20%		417.37
			1669.48
		L/S	1650.00
			4 DAYS

for FALCON AIR AUTO SERVICES PTE LTD

Service Request Details

Claim

S9M01YBZ

Reference

None 

Loss Date

August 25, 2019

Report Date

Aug 27, 2019 9:07:00 AM

Request Date

August 29, 2019

Due Date

September 5, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBG6021P

P: Andy
T: 1:07p.m
V: Out
E: ✓

MODEL

DYNA 150-3.0 D (M)

Service Address

...

Primary Contact/Insured

SENG SWEE KHENG

90 PUNGGOL DRIVE, #18-04, 828794, Singapore

96461416

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: ANDY <andy@falconair.com.sg>
Sent: Thursday, 29 August, 2019 11:43 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: pandan@falconair.com.sg
Subject: [EXTERNAL] GBG6021P CLAIMING TP AGAINST SLR3430K (AXA) DOA 25/08/2019
Attachments: SAS2660024.PDF; ESTIMATE.pdf; VEHICLE SEARCH.pdf

Categories: Namrata

Dear Sir/Madam

Kindly arrange TP survey for this case.

We only prefer the surveyor company listed below as they do the correspondence directly with you.

1. LKK AUTO CONSULTANTS

Kindly arrange survey / advise liability

Best Regards

Andy

Falcon-Air Auto Services Pte Ltd

Add : No. 8 Pandan Loop (Blk K / Blk 1) Singapore 128226 Tel No : +65

67795665 Fax No : +65 6779 1110

Your message is ready to be sent with the following file or link attachments:

SAS2660024

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/09/2019

Survey Details:

Date of loss	25-Aug-19
Date of appointment	29-Aug-19
Date of survey	10-Sep-19
Location of survey	FALCON-AIR AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	GBG 6021P
Make and Model	TOYOTA DYNA 3.0 MANUAL
Date of registration	13/9/2017
Excess	
Market Value	\$55,000
Parf Rebate	\$30,800
Nett Loss	\$24,200

Repair details:

Initial Estimate	\$ 3,219.05
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,136.85
Check items (estimate)	\$ -
Labour	\$ 950.00
Total	\$ 2,086.85
Lump Sum(if applicable)	\$ 1,650.00
Number of days for repair	4



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 1,765.50	W/GST
Loss of use	\$ -	
Loss of rental (W/GST)	\$ 428.00	4days x \$107
Loss of income	\$ -	
LTA search fees	\$ 2.00	
Others	\$ -	
Proposed Total	\$ 2,195.50	

 <MANDATE IA> - S9M01YBZ {ACCIDENT INVOLVING
SLR 3430K(OI) & GBG 6021P(TP) ON 25/08/2019}

Type

 Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$2195.50 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

[Reply](#)



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Tax Invoice : TI101104

Date : 20/09/2019
Vehicle Num: GBG6021P
Make/Model: TOYOTA DYNA
Chassis/Eng#: KDY31-8027989
Accident Date: 25/08/2019
Claim No.:
Reference: TP NTUC VS AXA L/S \$1650.00
Policy No.:

LUMPSUM REPAIR
INCLUSIVE OF PARTS, LABOUR & PAINT

Amount S\$

1,650.00

SingDollars : One Thousand Seven Hundred Sixty-Five & Cents Fifty Only

E. & O.E.	Total S\$:	1,650.00
	7% GST S\$:	115.50
	Amount Due S\$:	1,765.50

for FALCON AIR AUTO SERVICES PTE LTD



FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

POWER HYDRAULICS & ENGINEERING PTE LTD
C/O BLK K NO.8 PANDAN LOOP SINGAPORE
128226

Contact : 82643063

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Tax Invoice : PL114709

Invoice Date : 20/09/2019
Vehicle Num. : GBG6021P
Make/Model : TOYOTA DYNA
Mileage(Km) :
POW/O/RO# :
Ref./Remark : SEARCH FEE

S/N	Quantity	Particular	Unit Price	Amount S\$
1.		BEING SEARCH FEE FOR VEHICLE DOA 25/08/2019 AXA	1.87	1.87

SingDollars : Two Only

E. & O.E.

Total S\$	1.87
7% GST S\$	0.13
Amount Due S\$	2.00



Terms : Cash

Customer's Signature/Co. Stamp

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6789-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg



Pls proceed DS with quantum as proposed

Type

🔔 Question

Message

LOR is subject to rental vehicle.

Reply

Cecilia Chong (LKK Auto)

From: ANDY <andy@falconair.com.sg>
Sent: Monday, 23 September 2019 10:03 AM
To: Cecilia Chong (LKK Auto)
Subject: RE: GBG6021P CLAIMING TP AGAINST SLR3430K (AXA) DOA 25/08/2019
Attachments: invoices & documents.pdf

Dear Cecilia,

We are pleased to have a direct settlement with you based on the following

1) COR	-----	
1,765.50		
2) RENTAL @ \$100 X 4DAYS	-----	428.00
3) LTA SEARCH FEE	-----	
2.00		

Total : \$ 2,195.50

Attached tax invoices for your reference.
Kindly send the discharge voucher @ our Pandan Branch.

Thanks & best regards
Andy
Falcon-Air Auto Services Pte Ltd
Add : No. 8 Pandan Loop (Blk K / Blk 1) Singapore 128226 Tel No : +65 6779
5665 Fax No : +65 67791110

-----Original Message-----

From: ANDY [mailto:andy@falconair.com.sg]
Sent: Friday, September 06, 2019 11:47 AM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Cc: 'Admin A' <admin-a@lkkauto.com>
Subject: FW: GBG6021P CLAIMING TP AGAINST SLR3430K (AXA) DOA 25/08/2019

Dear Cecilia,

Good morning
Kindly advise the liability/ direct settlement

Best Regards
Andy
Falcon-Air Auto Services Pte Ltd
Add : No. 8 Pandan Loop (Blk K / Blk 1) Singapore 128226 Tel No : +65
67795665 Fax No : +65 6779 1110

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19015299/R1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:PETER

Date : 10-02-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 3430K	Veh. Inspected	GBG 6021P
Policy No.	VA1/GA430489	Coverage (\$)	0.00
Claim No.	S9M01YBZ	Excess (\$)	0.00
Assign From		Assign Date	29/08/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA 3.0 M	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDY2318027989	Colour	WHITE
Odometer	82718	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/25 R15	BRIDGESTONE	6 mm
L/H Front Tyre	175/25 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	165 R13C (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	165 R13C (D)	BRIDGESTONE	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/08/2019	Inspection Date	10/09/2019
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 6021P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH TAIL LAMP (CONSISTENT)	CRACKED	220.00	220.00
1	RH TAIL LAMP HOLDER (CONSISTENT)	NOT NECESSARY	71.60	-
1	TAILGATE (CONSISTENT)	BENT	1,010.00	1,010.00
1	DYNA STICKER (CONSISTENT)	NECESSARY	32.00	32.00
1	CORNER RUBBER (CONSISTENT)	MISSING	48.00	48.00
1	RH SIDE GATE LOCK (CONSISTENT)	NOT NECESSARY	113.70	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	584.30	-
1	REAR NUMBER PLATE BASE (CONSISTENT)	BENT	145.80	145.80
	LESS 25% DISCOUNT		-556.35	-363.95
			1,669.05	1,091.85
<u>SPECIAL NETT ITEMS</u>				
1	70KM/H STICKER (SN) (CONSISTENT)	NECESSARY	10.00	10.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	CRACKED	40.00	35.00
			50.00	45.00
<u>LABOUR</u>				
	SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER /OUTER		800.00	550.00
	TO RUSTPROOF ON ACCIDENT DAMAGE AREAS.(NPA)	NOT NECESSARY	-	-
	TO CUT OUT REWELD REAR END PANEL ,REPAIR RH SIDE LOWER BODY ,RH SIDE GATE INCLUDES KNOCKING & REPLACEMENT OF PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		700.00	400.00
			1,500.00	950.00
GRAND TOTAL			3,219.05	2,086.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CC4/ASM19015299/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

59M01YBZ

Reference

CC4/ASM19015299/R1ga3u2

Loss Date

25 August 2019

Report Date

27 Aug 2019 9:07:00 AM

Request Date

29 August 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

GBC6021P

Make

TPND TOYOTA

Model

DYNA 150-3.0 D (M)

Service Address

...

Primary Contact/Insured

SENG SWEE KIHENG

90 PUNGGOL DRIVE, #18-04, 828794, Singapore

96461416

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Actions

Next Step

Wait for Approve invoice

Add Invoice

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
LKK Inspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
LKK Adjustment 1.a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	12 February 2020
ATA AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2019
LOI.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2019
MANDATE IA DO 25092019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2019
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2019
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2019
PAIR COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2019
TP EST LIST MAILED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 September 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP-IA 6021.pdf	Reports & Statement	Others	UKK AUTO CONSULTANTS PTE LTD (TP)	12 September 2019
 TP PHU EMAIL FROM WORKSHOP WIT ESTIMATE & TP GIA.mpg	Letters and Correspondence	Workshop	DHIWAR Namrata	29 August 2019