

FALCON-AIR

POWER HYDRAULICS & ENGINEERING PTE LTD
C/O BLK K NO.8 PANDAN LOOP SINGAPORE
128226

Attention : Motor Claim Department
Contact : 82643063

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003525

Date : 29/08/2019
Vehicle Num. : GBG6021P
Make/Model : TOYOTA DYNA
Chassis/Eng# : KDY31-8027989
Accident Date : 25/08/2019
Claim No. :
Reference : TP VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	RH TAIL LAMP (m)		220.00
2.	1	RH TAIL LAMP HOLDER X		71.60
3.	1	TAILGATE bl		1,010.00
4.	1	DYNA STICKER m		32.00
5.	1	CORNER RUBBER m		48.00
6.	1	RH SIDE GATE LOCK X		113.70
7.	1	REAR END PANEL repair		584.30
8.	1	REAR NUMBER PLATE BASE bl		145.80
List TotalS\$:				2,225.40
25.00% Discount S\$:				556.35
				1,669.05
SPECIAL NETT ITEMS :				
1.	1	70 KM/HR STICKER ne		10.00
2.	1	REAR NUMBER PLATE m		35 40.00
Special Nett Total S\$:				50.00
LABOUR :				
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				JSU 800.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862


Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

**FALCON-AIR**

POWER HYDRAULICS & ENGINEERING PTE LTD
C/O BLK K NO.8 PANDAN LOOP SINGAPORE
128226

Attention : Motor Claim Department
Contact : 82643063

Estimate : ES003525

Date : 29/08/2019
Vehicle Num. : GBG6021P
Make/Model : TOYOTA DYNA
Chassis/Eng# : KDY31-8027989
Accident Date : 25/08/2019
Claim No. :
Reference : TP VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO RUSTPROOF ON ACCIDENT DAMAGE AREAS TO CUT OUT REWELD REAR END PANEL, REPAIR RH SIDE LOWER BODY, RH SIDE GATE INCLUDES KNOCKING & REPLACEMENT OF PARTS		400 700.00

Labour Total S\$:

1,500.00

SingDollars : Three Thousand Two Hundred Nineteen & Cents Five Only

E. & O.E.

Total S\$: 3,219.05



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg