



FALCON-AIR

POWER HYDRAULICS & ENGINEERING PTE LTD
C/O BLK K NO.8 PANDAN LOOP SINGAPORE
128226

Attention : Motor Claim Department
Contact : 82643063

Cecilik
FALCON-AIR AUTO SERVICES PTE LTD
CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003525

Date : 29/08/2019
Vehicle Num : GBG6021P
Make/Model : TOYOTA DYNA
Chassis/Eng# : KDY31-8027989
Accident Date : 25/08/2019
Claim No.
Reference : TP VS AXA
Policy No.

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	RH TAIL LAMP <i>CM</i>		220.00
2.	1	RH TAIL LAMP HOLDER <i>X 3/4</i>		71.60
3.	1	TAILGATE <i>h</i>		1,010.00
4.	1	DYNA STICKER <i>h</i>		32.00
5.	1	CORNER RUBBER <i>h</i>		48.00
6.	1	RH SIDE GATE LOCK <i>X 3/4</i>		113.70
7.	1	REAR END PANEL <i>repair</i>		584.30
8.	1	REAR NUMBER PLATE BASE <i>h</i>		145.80
List Total S\$:				2,225.40
25.00% Discount S\$:				556.35
				1,669.05
SPECIAL NETT ITEMS :				
1.	1	70 KM/HR STICKER <i>h</i>		10.00
2.	1	REAR NUMBER PLATE <i>h</i>		35 40.00
Special Nett Total S\$:				50.00
LABOUR :				
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				JSU 800.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7867
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg



FALCON-AIR

POWER HYDRAULICS & ENGINEERING PTE LTD
C/O BLK K NO.8 PANDAN LOOP SINGAPORE
128226

Attention: Motor Claim Department
Contact: 82643063

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate: ES003525

Date: 29/08/2019
Vehicle Num: GBG6021P
Make/Model: TOYOTA DYNA
Chassis/Eng#: KDY31-8027989
Accident Date: 25/08/2019
Claim No:
Reference: TP VS AXA
Policy No.:

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO RUSTPROOF ON ACCIDENT DAMAGE AREAS
TO CUT OUT REWELD REAR END PANEL. REPAIR RH SIDE LOWER
BODY. RH SIDE GATE INCLUDES KNOCKING & REPLACEMENT
OF PARTS

400 700.00

Labour Total S\$:

1,500.00

Form
Hp 20010068
4 days
4/5
10/09/19 @ 1625
Revy after repair

SingDollars: Three Thousand Two Hundred Nineteen & Cents Five Only

E. & O.E.

Total S\$: 3,219.05

for FALCON AIR AUTO SERVICES PTE LTD



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is not allowed
- No illegal modification is allowed
- Supplementary items for repair is subject to approval

Acknowledged by Repairer:

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003525

Date : 02/09/2019
Vehicle Num. : GBG6021P
Make/Model : TOYOTA DYNA
Chassis/Eng# : KDY31-8027989
Accident Date : 25/08/2019
Claim No. :
Reference : TP VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	RH TAIL LAMP		220.00
2.	1	RH TAIL LAMP HOLDER X		X
3.	1	TAILGATE		1,010.00
4.	1	DYNA STICKER		32.00
5.	1	CORNER RUBBER		48.00
6.	1	RH SIDE GATE LOCK X		X
7.	1	REAR END PANEL X		X
8.	1	REAR NUMBER PLATE BASE		145.80
List TotalS\$:				1,455.80
25.00% Discount S\$:				363.95
				1,091.85 ✓
		SPECIAL NETT ITEMS :		
1.	1	70 KM/HR STICKER		10.00
2.	1	REAR NUMBER PLATE		35.00
Special Nett Total S\$:				
				45.00 ✓
		LABOUR :		
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		550.00

CONTINUE / ...

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

Estimate : ES003525

Date : 02/09/2019
Vehicle Num. : GBG6021P
Make/Model : TOYOTA DYNA
Chassis/Eng# : KDY31-8027989
Accident Date : 25/08/2019
Claim No. :
Reference : TP VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO RUSTPROOF ON ACCIDENT DAMAGE AREAS TO CUT OUT REWELD REAR END PANEL, REPAIR RH SIDE LOWER BODY, RH SIDE GATE INCLUDES KNOCKING & REPLACEMENT OF PARTS		400.00
		Labour Total S\$:		950.00

SingDollars : Two Thousand Eighty-Six & Cents Eighty-Five Only

	E. & O.E.	Total S\$:	2,086.85 =====
	L/S LESS 20%		417.37
			1669.48
for FALCON AIR AUTO SERVICES PTE LTD			
		L/S 1650.00	
		4 DAYS	