

SUPREME AUTO SERVICE PTE LTD

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

AIK SUN DEMOLITION & ENGINEERING PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Not Notified
11 Sep @?
Runny After Rain
5 day

Date: 28/08/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: TOYOTA DYNA / GBA 4265 Y	
1 pc	front grille	564.10 ?
1 pc	front bumper	768.90 ✓
2 pcs	front bumper bracket	348.40 x
2 pcs	front head lamp assy	1,527.40 ?
1 pc	front panel	1,264.30 ✓
1 pc	front corner panel	264.30 ✓
1 pc	front corner panel garnish	217.80 x
1 pc	front inner lower panel	574.80 x
1 pc	front top inner panel	465.40 x
1 pc	front wiper centre panel	745.20 x
1 pc	front wiper side panel	376.40 x
1 pc	front windscreen glass rubber	198.90 509m
1 pc	front emblem logo	84.20 —
1 pc	front "DYNA" emblem	78.40 —
1 pc	air con fan blower assy	1,193.00 ?
1 pc	air con cooling coil housing assy.	674.00 x
1 pc	front wiper motor	954.00 x
1 pc	front wiper motor linkage	345.10 x
	sub-total	10,644.60
	less 25%	2,661.15
	sub-total	7,983.45
1 pc	number plate	35.00 20m
	s.nett	
	sub-total	8,018.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledge by Repairer
Signature:
Date:

balance brought forward.	8,018.45	
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	1,200.00	6001
To check wiring system.	50.00	201
To remove and install air-con components and top up gas.	220.00	1001
To spray painting on affected areas.	800.00	6001
To apply rust proofing.	150.00	301
To remove dashboard to enable repair.	300.00	2401
To remove cabin trimming to enable repair.	180.00	nm X
Total	10,918.45	