



Case Details

Case Reference Number : TAX/08/19/2099
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4510H

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8244-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd
 Accident Date and Time : 24/08/2019 12:50 PM
 Vehicle Age(In Months) : 22

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	BR-
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Give	X N/A
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give	X N/A
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Not Give	X N/A
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Not Give	X N/A
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	/ MC
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Give	X N/A
One Time Key In	Main			FENDER SUB-ASSY, FR, LH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace	/ DD
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	/ N/A
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0	Not Give	X N/A

Total Spare Part Cost 9,540.63

Surveyor Total 1,122.38

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 8,690.85

Final Sur Total 1,122.38

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PAD, FR WHEEL LH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	X N/A
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	175.80	175.80	25.00	131.85	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Not Give	X N/A
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	X N/A
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, LH	1	1,283.90	1,283.90	10.00	1,155.51	Replace	0	0	Not Give	X N/A
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	89.50	89.50	25.00	67.13	Replace	1	0	Repair	X R
One Time Key In	Main			LAMP ASSY, SIDE MIRROR TURN SIGNAL, LH	1	162.20	162.20	10.00	145.98	Replace	0	0	Not Give	X N/A
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	0	0	Not Give	
Total Spare Part Cost									9,540.63	Surveyor Total		1,122.38		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									8,690.85	Final Sur Total		1,122.38		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
Total:			2,232.00	450.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO REPSRAY FRONT HOOD	378.00	0	
4	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
5	Main	TO RESPRAY RIM	180.00	0	
6	Main	RESPRAY WHEEL CAP	180.00	0	
7	Main	TO RESPRAY FRONT DOOR LH	378.00	0	
8	Main	RESPRAY MIRROR COVER LH	180.00	50	
Total:			2,232.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20 <i>AK</i>	
2	Main	TO REMOVE AND REFIX WING MIRROR	120.00	20 <i>AK</i>	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	120.00	20 <i>AK</i>	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
6	Main	TO REPLACE SUNDRY PARTS	100.00	20 <i>AK</i>	
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			720.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,690.85	1,122.38
Total Labour Cost	845.00	400.00
Total Spray Painting	2,232.00	450.00
Other	720.00	80.00
Overall Total	12,487.85	2,052.38
Lump Sum Repair Option		
Lump Sum Total	0.00	2,052.38

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Approved Amount

2,052.38

No of Repair Days*

6

4

Remarks

P/P repair, take before spray. Finalize sent to
stevechen@lkkauto.com

Surveyor Name

STEVE CHEN

Signature



Save

Clear

Survey Date

28/08/2019

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**