



**AIG Singapore**  
78 Shenton Way  
Singapore 079120

**TeamWork Garage Pte Ltd**  
53 Ubi Avenue 1 #01-23/24 Spore 408934  
Paya Ubi Industrial Park  
Tel : 6844 2475  
E-mail : claims@teamworkgarage.com  
ROC number : 201015366H  
3RD PARTY CLAIM ESTIMATION

|                |                   |
|----------------|-------------------|
| Vehicle number | SLZ7272G          |
| Make / Model   | SUBARU/FORESTER   |
| Chassis number | JF1SJGK85GG082126 |
| Accident date  | 22 August 2019    |
| Reference      | 1908-56           |

| Qty                                           | Particulars                                       | Unit Price - SGD \$ |
|-----------------------------------------------|---------------------------------------------------|---------------------|
| <b>PARTS REPLACEMENT - LIST ITEMS</b>         |                                                   |                     |
| 1                                             | END PANEL <del>X</del> <i>sub</i>                 | 381.80 X            |
| 1                                             | END PANEL TOP GARNISH <del>X</del> <i>sub</i>     | 74.52 X             |
| 1                                             | REAR BUMPER TOP PLATE <del>sub</del>              | 316.25              |
| 2                                             | REAR BUMPER SIDE BRACKET <del>X</del> <i>sub</i>  | 64.40 X             |
| 2                                             | REAR BUMPER SIDE RETAINER <del>X</del> <i>sub</i> | 64.40 X             |
| 2                                             | REAR BUMPER REFLECTOR <del>X</del> <i>sub</i>     | 47.10 X             |
| 1                                             | REAR BUMPER REINFORCEMENT <del>X</del> <i>sub</i> | 331.20 X            |
| 1                                             | REAR BUMPER <del>be</del>                         | 750.00              |
|                                               |                                                   | 2029.67             |
|                                               | Less 20 %                                         | 405.93              |
|                                               | Subtotal                                          | 1623.74             |
|                                               | Balance C/F                                       | 1623.74             |
| <b>PARTS REPLACEMENT - SPECIAL NETT ITEMS</b> |                                                   |                     |
|                                               | Balance B/F                                       | 1623.74             |
| 1 SET                                         | REAR BUMPER CLIP <del>new</del>                   | 30.00               |
| 1 SET                                         | REAR REVERSE SENSOR <del>new</del>                | 400.00              |
| 1                                             | JOINT SEALANT <del>X</del> <i>an</i>              | 150.00              |
|                                               | Subtotal                                          | 580.00              |
|                                               | Balance C/F                                       | 2203.74             |
| <b>LABOUR AND MISCELLANEOUS CHARGES</b>       |                                                   |                     |
|                                               | Balance B/F                                       | 2203.74             |
| 1                                             | CHECK REAR WIRING AND LIGHTNING SYSTEM            | 60.00 X <i>an</i>   |
| 2                                             | REMOVE AND RENEW REAR REVERSE SENSOR              | 120.00 <i>60</i>    |
| 3                                             | REMOVE, REFIT REAR LINING, TRIM AND GARNISH       | 150.00 X <i>an</i>  |
| 4                                             | REMOVE AND STRAIGHTEN REAR EXHAUST                | 120.00 X <i>an</i>  |
| 5                                             | PANEL BEATING ON AFFECTED AREAS                   | 800.00 <i>250</i>   |
| 6                                             | SPRAY PAINTING ON AFFECTED AREAS                  | 700.00 <i>250</i>   |
| 7                                             | APPLY ANTI RUST ON AFFECTED AREAS                 | 120.00 X <i>an</i>  |
|                                               | Subtotal                                          | 2070.00             |
|                                               | Grand total                                       | 4273.74             |

1066.25  
20%  
853

230

560

853  
230

560  
1643

20%  
1314.40  
45-1,300