



Case Details

Case Reference Number : TAX/08/19/2107
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1854R

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8254-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 26/08/2019 05:15 PM
 Vehicle Age(In Months) : 60

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR ASSY, RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0	Not Give	X NN
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair	X R
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ IPC
One Time Key In	Main			FENDER PROTECTOR FRT/RH SIDE	1	113.90	113.90	25.00	85.43	Replace	0	0	Not Give	X NN
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check	X NN
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	X R
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X NN
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	174.10	174.10	25.00	130.57	Replace	1	130.57	Replace	/ CHT
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	/ DD
Total Spare Part Cost									6,429.40	Surveyor Total		1,716.73		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									6,429.40	Final Sur Total		1,373.38		

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾	✓ nec
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace ▾	✓ BR
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Givr ▾	X 1/1/1
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Givr ▾	X 1/1/1
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Givr ▾	X 1/1/1
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Givr ▾	X 1/1/1
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	1	265.68	Replace ▾	✓ CRA
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Givr ▾	X 1/1/1
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Givr ▾	X 1/1/1
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Givr ▾	X 1/1/1
One Time Key In	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Givr ▾	X 1/1/1
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace ▾	✓ CHT
Total Spare Part Cost									6,429.40	Surveyor Total		1,716.73		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									6,429.40	Final Sur Total		1,373.38		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	676.00	250	
Total:			676.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	RESPRAY MIRROR COVER RH	180.00	0	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
3	Main	TO REPSRAY FRONT BUMPER	378.00	200	
4	Main	TO RESPRAY RIM	180.00	50	
Total:			1,116.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	84.00	0	
2	Main	TO WASH AND VACUUM	60.00	0	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	NA
4	Main	TO REPLACE SUNDRY PARTS	100.00	20	NA
5	Main	ADVERTISEMENT STICKER	148.44	148.44	NA
6	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	NA
Total:			572.44	208.44	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,429.40	1,373.38
Total Labour Cost	676.00	250.00
Total Spray Painting	1,116.00	450.00
Other	572.44	208.44
Overall Total	8,793.84	2,281.82
Lump Sum Repair Option		☒
Lump Sum Total	0.00	2,300.00

Estimator Assessment(\$)

Surveyor Assessment(\$)

* Surveyor Approved Amount

2,300.00

No of Repair Days*

6

3

Remarks


-

L/S repair, take after spray. Finalize sent to
stevechen@lkkauto.com

Surveyor Name

STEVE CHEN

Signature



Save

Clear

Survey Date

28/08/2019

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: