

ESTIMATE

Our Ref: AC2019032/TP/GBH2574G - 28.08.2019

Vehicle number: GBH2574G

Vehicle Made & Model: TOYOTA DYNA

Items	Qty	List Items	Amount \$
1	1	Tailgate	DD/set 1,485.60 ✓
2	1	Tailgate sticker "TOYOTA"	nee 189.60 ✓
3	1	Tailgate sticker "DYNA"	nee 58.60 ✓
4	1	Tailgate lower member	DD/set 541.90 ✓
5	4	Tailgate hinges @ 65.50	1/5 cut 262.00 X
6	2	Tailgate stoppers @ 28.60	1/5 cut 57.20 1AC
7	2	Taillamps - L/R @ 291.33	nee 582.60 1AC
8	2	Taillamp panels - L/R @ 185.90	nee 371.80 1AC
9	1	Rear licence plate bracket	BD 186.50 ✓
10	1	Rear sidegate - LH	17 1,685.90 X
11	1	Rear sidegate lock hinge - LH	BD 195.50 ✓
12	1	Rear sidegate lower member	R 591.90 X
Sub-total			6,209.10
Less 25%			1,552.28
Total List			4,656.83

SVZ 3163.53

Special Nett Items

1	1	Rear sticker "70 KM/H"	nee 10.00 ✓
2	1	Rear licence plate	BD 40.00 15
3	1 set	Rear reverse sensor	SMH 280.00 200
Total Special Nett			330.00

Labour charges

1	To check rear electrical wiring	50.00 1.0
2	To remove, refix rear reverse sensor	80.00 50
3	To respray undercoating	120.00 50
4	To respray painting and etc	1,080.00 550
5	Panel beating, cut, weld remove & replacing above parts	1,200.00 600
Total Labour		2,530.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Acknowledged
29/8/19
2/5 #3050
Whipin Attorney

P-3163.53
SVZ
P-1581.76
S.W-225.00
L-1260.00
3066.76