

15/5/2010

INS. CASE OWNER:

CC4/ASM19015321/Bga3

LKK:

IDAC: 134394

Surveyor:

LTG

DOI:

ASSIGNMENT


29/08/2019

Date / Time :

29/08/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : YN 9162L

Claim No. : S9M01YRI

Name of Insured : BIG-FOOT LOGISTIC PTE LTD

Policy No. :

Insured Tel No. : HP:

Make / Model : MITSUBISHI CANTER-3.0 D (A)

Excess Sec II : \$

D.O.A : 28/08/2019 18:35

Place of Accident : WOODLAND AVE 12 NEAR SLE

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : KALIYAPERUMAL KATHIRAN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO


Driver Tel No. : +65-84314340 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

YN 9162L

SKJ 5450T

GBC 9989Z



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel : Team AutoPro

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	SKJ 5450T - X	YN 9162L - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
4/11	To Email LOI		Non-Reporting ltr (2nd):	
6/11	Email LOI		Non-Reporting ltr (Final):	
	- to check to Mr Lim on COR amt not tally with his finalise amt.		Notification ltr (if non-pickup):	
7/11	01 WP & DL in.		Call OI:	
12/11	01 WA 2. Addendum form in.		After call ltr to OI:	
	- Rec W2 to TP (pending LOD).		Documentation Check List: Handler Typist	
13/12	Rec Survey photos from Mr Lim.		Notification ltr (if non-pickup)	☒
	booked things x no photo. COR admit to		After call ltr to OI:	☒
17/12	US \$13,600.00. To notify TP (pending amended tax inv & LOD).		Authorisation To Act:	☒
20/12	Pending BXA approval for COR finalise @ US \$13,200.		Release Voucher:	☒
22/12	off \$14,585.45 (pending acceptance)		Final Repair Bill:	☒
24/12	TP reject offer. Re-offr G/S \$14,900. (pending acceptance)		Car Rental Invoice:	☒
27/12	Settle @ G/S \$14,900, DV send (pending PV).		Towing Invoice	☒
1/1	DV in, the pay MC to close.		LTA / GIA :	☒
			Medical Bill:	☒
			PIR:	☒
			Mandate/Reject Instruction:	☒
			LOD	☒
			Payment Breakdown Form:	☒
			Post-Repair Photos:	☒
			Others:	☒

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$13,600.00

(10 days)

Reduction: \$18,093.58 % 57

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia :

Repair Cost:

\$13,054.00

(ATA instructions)

C.C (01 last)

Loss of Rental (LOR):

\$1605.00

(10 days)

x \$160.50

Loss of Use (LOU):

\$240.00

(\$ 80 x 3 days)

Loss of Income (LOI):

\$ -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$7.45

Medical:

\$ -

Disbursement:

\$ -

(e.g. Tow/ Independent)

Legal Cost

\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$14,906.45

Global Sum \$:

\$14,900.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$14,900.00

Name 1:

Team AutoPro Pte Ltd

Payee 2: (Strike if N.A.)

\$ -

Name 2:

Payee 3: (Strike if N.A.)

\$ -

Name 3:

COPY SENT

REF:

Asm(AxA)

ASSIGNMENT

Cedra

From

Date:

29.8.2019

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SKJ 5450 T

at Workshop m/s Teon Auto pro

of 160 sin ming dr # 01-14

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 10 days

Res.: Yes or No

Lum Sum: 80 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

mp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKJ 5450 T

Yr Regn:

17/4/2013

Type: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make:

Toyota Camry 2.0

C.C. 1998

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

104326

T/Radio:

Insured / Std / NI / NA

Eng/No:

1 A Z E 267243

C/No:

MR053BK5104011664

Gen. Cond: Good / Fair / ☒ Poor / BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt or

Modi:

Nil / ☒ Rim / STD A/Rim or

Tyre Size:

F: 215/60/16

R: 215/60/16

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/8/19

D.O.I.

29/8/19

Survey held at

Teon Auto pro

Des. of Damages:

☒ Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S 13,600 / 2
Teon Auto pro
27/11/19Teon Auto pro
2/9/19

(Red = \$18,093.58 / 571.)

Finalised on 3/12/19 at
lump sum \$13,650.00 with
10 repair days Teon Auto pro
4/12/19MV 56,500 / 2
PV 41,609 / 2
NV 14,891 / 2Teon Auto pro
29/8/19

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / L.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **3KJ** **SJK 5450T**

Make Toyota

Model Camry 2.0

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 1,055.90	\$ 888.60 1,055.90
2	Bootlid logo	1	\$ 61.70	\$ 61.70
3	Bootlid emblem '2.0'	1	\$ 48.60	\$ 48.60
4	Bootlid emblem 'camry'	1	\$ 49.50	\$ 49.50
5	Bootlid inner lock	1	\$ 349.50	\$ 200.00 349.50
6	Bootlid striker	1	\$ 79.90	\$ 79.90
7	Bootlid switch	1	\$ 45.20	\$ 45.20
8	Bootlid lock sensor/antenna	1	\$ 228.00	\$ 168.90 228.00
9	Bootlid weatherstrip	1	\$ 221.90	\$ 168.90 221.90
10	Bootlid outer moulding	1	\$ 358.95	\$ 358.95
11	Bootlid inner trim	1	\$ 560.00	\$ 560.00
12	Bootlid hinge <i>Error RH? suppose to cancel</i>	2	\$ 80.00	\$ 160.00
13	Bootlid reflector	2	\$ 389.83	\$ 561.60 779.66
14	Rear bumper	1	\$ 828.00	\$ 656.20 828.00
15	Rear bumper retainer	2	\$ 85.50	\$ 171.00
16	Rear bumper bracket	2	\$ 49.80	\$ 99.60
17	Rear bumper sensor	4	\$ 152.30	\$ 200.00 609.20
18	Rear bumper reinforcement	1	\$ 531.50	\$ 425.00 531.50
19	Rear bumper inner sponge	1	\$ 240.00	\$ 240.00
20	Rear end panel	1	\$ 523.60	\$ 523.60
21	Rear end panel top garnish	1	\$ 357.40	\$ 357.40
22	Taillamp	2	\$ 546.30	\$ 816.60 1,092.60
23	Taillamp base panel	2	\$ 135.10	\$ 270.20
24	Bootlid lamp	2	\$ 382.20	\$ 764.40
25	Spare tyre panel	1	\$ 1,086.50	\$ 780.05 1,086.50
26	Spare tyre sponge	1	\$ 35.80	\$ 35.80
27	Spare tyre panel top board	1	\$ 399.70	\$ 298.10 399.70
28	Spare tyre fastener	1	\$ 68.90	\$ 68.90
29	Tool holder left right	2	\$ 24.80	\$ 49.60
30	Rear chasis member	1	\$ 825.00	\$ 825.00
31	Exhaust pipe centre	1	\$ 1,365.00	\$ 1,365.00
32	Exhaust muffler tip	1	\$ 256.70	\$ 182.10 256.70
33	Exhaust silencer	1	\$ 805.00	\$ 805.00
34	Reverse camera	1	\$ 180.00	\$ 180.00
35	Number plate lamp	2	\$ 30.00	\$ 60.00
36	Rear shock absorber	2	\$ 880.00	\$ 1,760.00
37	Rear fender Rh	1	\$ 925.00	\$ 925.00
38	Rear fender Lh	1	\$ 925.00	\$ 925.00

DDV

NECV

JMV

BRV

BRV

DISC

BRV

BRV

BRV

BRV

DDV

NECV

BRV

SC

BT

NN

DDV

BLV

BRV

DDV

BRV

BRV

BRV

DIS

NN

DIS

BRV

SVC

DDV

SVC

SVC

BRV

SVC

DDV

DDV

39	Rear fender inner trim Rh	1	\$	337.90	\$	337.90	?NNX
40	Rear fender inner trim Lh	1	\$	337.90	\$	337.90	?NNX
41	Rear fender inner sheild	2	\$	155.50	\$	311.00	?NNX
42	Rear windscreen moulding	1	\$	165.00	\$	130.60 165.00	NECV
43	Bonnet	1	\$	1,120.00	\$	1,120.00	?NNX
* 44	Bonnet chrome moulding	1	\$	213.00	\$	189.20 213.00	?SCR ✓
45	Bonnet lock	1	\$	110.00	\$	110.00	SVCX
46	Front grille	1	\$	478.80	\$	289.40 478.80	BT ✓
47	Front grille logo	1	\$	51.90	\$	51.90	NECV ✓
48	Front grille chrome moulding	1	\$	172.00	\$	172.00	?SCR ✓
49	Headlamp Rh	1	\$	1,621.60	\$	1,364.60 1,621.60	?BR ✓
50	Headlamp Lh	1	\$	1,621.60	\$	1,364.60 1,621.60	?BR ✓
51	Headlamp lower bracket Rh	1	\$	154.00	\$	154.00	?NNX
52	Headlamp bracket Lh	1	\$	154.00	\$	154.00	?NNX
53	Front bumper	1	\$	1,590.90	\$	655.10 1,590.90	DEBR ✓
54	Front bumper side retainer	2	\$	134.00	\$	103.10 268.00	NECV
* 55	Front bumper grille	1	\$	415.60	\$	415.60	BT ✓
56	Front bumper reinforcement	1	\$	287.00	\$	287.00	?DD ✓
57	Front bumper inner sponge	1	\$	182.00	\$	182.00	?BR ✓
58	Front bumper sensor	2	\$	155.80	\$	200.00 311.60	MIS ✓
59	Front bumper side garnish	1	\$	327.50	\$	327.50	?NNX
60	Front support panel	1	\$	699.40	\$	699.40	?NNX
61	Front support panel top garnish	1	\$	327.50	\$	327.50	?NNX
62	Front fog lamp chrome cover	2	\$	127.50	\$	144.00 255.00	?BR
63	Front fog lamp	2	\$	318.20	\$	636.40	?BR
				Parts Sub Total :	\$17,162.40 30,378.11		
				Discount	\$ 4,290.60 7,594.53		
				PARTS TOTAL :	\$12,871.80 22,783.58		

@25%

12,662.40
3,165.60
9496.80

25%

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Bootlid inner trim clips	1	\$	50.00	\$ 50.00 ?NNX
2	Rear bumper screw cover	2	\$	20.00	\$ 40.00 ?NNX
3	Rear bumper clips	1	\$	50.00	\$ 30.00 50.00 ✓
4	Rear end panel top garnish clips	1	\$	50.00	\$ 30.00 50.00 ✓
5	Rear fender inner trim clips Rh	1	\$	50.00	\$ 30.00 50.00 ✓
6	Rear fender inner trim clips Lh	1	\$	50.00	\$ 30.00 50.00 ✓
7	Rear fender inner sheild clips	2	\$	50.00	\$ 60.00 100.00 ✓
8	Number plate with garnish	2	\$	70.00	\$ 50.00 140.00 ✓
9	Bootlid reflector seal	2	\$	60.00	\$ 120.00 ✓
10	Taillamp seal	2	\$	80.00	\$ 160.00 ✓
11	Rear windscreen sealant	1	\$	100.00	\$ 30.00 100.00 ✓
12	Front grille clips	1	\$	50.00	\$ 30.00 50.00 ✓
13	Front bumper clips	1	\$	50.00	\$ 30.00 50.00 ✓
14	Front support panel top garnish clips	1	\$	50.00	\$ 30.00 50.00 ✓
15	Front fender inner sheild clips	1	\$	50.00	\$ 50.00 ?NNX
16	Front fender sealant	1	\$	100.00	\$ 100.00 ?NNX
17	Rear end panel sealant	1	\$	100.00	\$ 60.00 100.00 ?NECV
18	Spare tyre panel insulation pad	1	\$	300.00	\$ 150.00 300.00 ?NECV
				SPECIAL NETT TOTAL :	\$560.00 1,610.00

Nos.	LABOUR	S\$
1	To Panel Beat & realign Front Accident Damage Portion	\$ 600.00 1,600.00
	To Panel Beat & realign Rear Accident Damage Portion	\$ 1000.00 1,200.00
2	To Spray Front Accident Damage Portion	\$ 400.00 1,600.00
	To Spray Rear Accident Damage Portion	\$ 1000.00 1,200.00
3	Alignment	\$ 80.00 NAX
4	Bootlid water leaking test	\$ 80.00 NAX
5	R&R bootlid component	\$ 80.00 120.00
6	Chasis alignment	\$ 350.00 } ? NECV
7	Mount bench work	\$ 400.00 } 250.00
8	R&R rear under carriage Lh + Rh	\$ 400.00 ? NNX
9	R&R wire harness and check function	\$ 50.00 150.00
10	Test drive & reverse sensors	\$ 20.00 NAX
11	Rust proofing	\$ 100.00 200.00 ?
LABOUR TOTAL :		\$ 3630.00 7,350.00

PARTS TOTAL : \$ 22,783.58 12,871.80
 SPECIAL NETT TOTAL : \$ 1,610.00 560.00
 LABOUR TOTAL : \$ 7,350.00 3630.00
 GRAND TOTAL : \$ 31,743.58 17,061.80
 @ 20% 3412.36
 13649.44

survey on 29/8/19
 Taim Lin
 1600 hrs

H/S 13,650/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

? photo

Lump sum repair

Repair days 10

Resurvey on 30/8/19

Taim Lin

Time 1600 hrs

Lin
 29/9/19