

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO.6366 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7864Y - AIG

Dome

ROEL*Not Authorized
C1 Rep @ 7300/*

Vehicle No.:

SHB7864Y - ROEL

Chassis No.:

LK1LA69RJBB095719*

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident:

01.03.2014

Third Party Insurer:

AIG**PART****LIST**

1	1	Rear Bumper	\$	<i>R</i> 1,202.00 ✓
2	1	Rear Bumper Beam	\$	<i>R</i> 239.94 ✓
3	1	Rear Bumper Centre Absorber	\$	<i>CMA</i> 260.00 ✓
4	1	Rear Bumper Side Retainer RH	\$	<i>CMA</i> 68.76 ✓
5	1	Rear Bumper Side Retainer LH	\$	<i>Sm</i> 68.76 X
6	1	Rear Bumper Reflectors LH	\$	<i>Sm</i> 119.74 X
7	1	Rear Bumper Reflectors RH	\$	<i>Br</i> 119.74 ✓
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sm</i> 93.00 X
9	1	Rear Luggage Floor Panel	\$	<i>R</i> <i>Br</i> 973.00 ✓ X
10	1	Rear Luggage Floor Panel Insulator	\$	<i>nm</i> 63.50 X
11	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sm</i> 378.00 X
12	1	Rear End Panel Inner	\$	<i>R</i> 336.84 ✓
13	1	Rear End Panel Outer	\$	<i>R</i> 623.76 ✓
14	1	Rear End Panel Inner Trim	\$	<i>Di</i> 263.84 ✓
15	1	Bootlid	\$	<i>R</i> 973.00 ✓
16	1	Bootlid Weatherstrip	\$	<i>Di</i> <i>Di</i> 344.28 ✓
17	1	Bootlid Lock - Top	\$	<i>R</i> 466.56 X
18	1	Bootlid Lock - Bottom	\$	<i>R</i> 39.40 X
19	1	Bootlid 'CHEVROLET' Badge	\$	<i>nm</i> 120.62 ✓
20	1	Bootlid Logo	\$	<i>nm</i> 138.84 ✓
21	1	Bootlid 'EPICA LT' Badge	\$	<i>nm</i> 119.84 ✓
22	1	Bootlid Reflector Centre	\$	<i>Sm</i> 217.97 X
23	1	Bootlid Reflector RH	\$	<i>CMA</i> 128.40 ✓
24	1	Bootlid Reflector LH	\$	<i>CMA</i> 128.40 ✓
25	1	Rear Tail Lamp LH	\$	<i>mg Di</i> 479.30 ✓
26	1	Rear Tail Lamp Panel LH	\$	<i>R</i> 359.00 X
27	1	Rear Tail Lamp Panel RH	\$	<i>CMA</i> 479.30 ✓
28	1	Rear Tail Lamp Panel RH	\$	<i>R</i> 359.00 ✓
29	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00 X
30	1	Rear Fender LH	\$	<i>R</i> 1,145.00 X
31	1	Rear Fender Inner Trim LH	\$	<i>Sm</i> 298.00 X
32	1	Rear Fender Inner Cowling LH	\$	<i>Sm</i> 76.60 X
33	1	Rear Fender RH	\$	<i>R</i> 1,145.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7064Y - AIG**ROEL**

34	1	Rear Fender Inner Trim RH	\$	Refer 298.00 ✓
35	1	Rear Fender Inner Cowling RH	\$	76.60 X
			\$	13,313.99
10%			\$	1,331.40
Total			\$	11,982.59

Special Nett

1 Set	Rear Bumper Parking Sensor	\$	Ref 300.00 ✓
1 Set	Rear Bumper Fastener Clip	\$	30.00 ✓
1 Set	Rear Boot Inner Trim Clip	\$	60.00 X
1	Rear Boot Sticker 'Trans-cab'	\$	30.00 ✓
1	Rear Boot Sticker '6555-3333'	\$	30.00 ✓
1 Set	Rear Fender Inner Trim Clip	\$	60.00 ✓
2	Rear Windscreen Sealant	\$	100.00 40ml ✓
1	Rear Windscreen Inner Sponge Seal	\$	100.00 30ml ✓
1	Rear windscreen Inner Top garnish	\$	80.00 X
1 Set	Rear End Panel Cover Clip	\$	30.00 ✓
2 Set	Rear Fender Inner Cowling Clip	\$	60.00 X
1	Spare Tyre Board	\$	10.00 X
1	Spare Tyre	\$	180.00 X
1	Spare Wheel Rim	\$	126.74 X
1	Spare tyre fastener bolt	\$	65.00 X
TOTAL		\$	1,261.74
TOTAL PARTS		\$	13,244.33

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 900 ✓
To Rust-Proofing Of The Affected Areas.	\$	220.00 60 ✓
To Check Electrical Lighting Concerned.	\$	170.00 20 ✓
Putty And Spray Painting Of The Affected Portion.	\$	2,700.00 1200 ✓

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO. 6287 6666 FAX NO. 6366 8862

CO/GST REG NO. 201019026G

SHB 7854Y - AIG

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 <i>601</i>
To Reinstall Rear Bumper Parking Sensor.	\$	170.00 <i>601</i>
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair.	\$	280.00 <i>801</i>
To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 <i>601</i>
To check steering geometry and computer wheel alignment	\$	<i>220.00 X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>Repair</i> 170.00 <i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 <i>1201</i>
Towing Fees	\$	<i>220.00 X</i>
To Repair And Realign Rear Exhaust Pipe.	\$	<i>Repair</i> 170.00 <i>X</i>

TOTAL	\$	7,530.00
--------------	-----------	-----------------

Over All Total	\$	20,774.33
-----------------------	-----------	------------------

REPAIR DAYS**10 DAYS**