

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :65421

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1020/2019/NS
Date : 27-Aug-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Teo Ah Suan
Address : 10 Thomson Heights
Singapore 574839
Telephone : HP +65 97370331
Type of Claim : Own Damage Claim
Policy No. : 2100467948-03
Vehicle No : **SDP 89 M**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : May-16
Engine No : CZC 527058
Chassis No : WAUZZZ8V0G1078474
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Aug-19
Place of Accident : Toa Payoh Lorong 6 And Lorong 1 (Filter Lane)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDP 89 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and reinstall aircond condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	?
3	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 300.00	X.
4	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,250.00	1250 without lock carrier 2500 with lock carrier
5	To respray front bumper, lhs front fender, bonnet and lhs front door.	\$ 3,700.00	1650
6	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,002.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 89 M

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted.</i>	\$ 1,830.00	✓
2	FROONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	x
3	FRONT BUMPER COVER TRIM - LH <i>new</i>	\$ 148.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 148.00	+
5	FRONT BUMPER PULL STRAP <i>new</i>	4 \$ 187.00	x
6	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 35.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>missing</i>	\$ 99.00	✓
8	RADIATOR GRILLE <i>crushed</i>	\$ 637.00	✓
9	RADIATOR GRILLE COVER <i>new</i>	\$ 89.00	x
10	FRONT BUMPER SIDE REINFORCEMENT <i>Best</i>	\$ 660.00	✓
11	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	\$ 125.00	✓
12	FRONT BUMPER COVER ?	\$ 51.00	?
13	CAUTION SIGN <i>3 new</i>	NEC \$ 13.00	✓
14	AIRCON STICKER	NEC \$ 7.00	✓
15	SIGNAL HORN - LH LOW TONE ?	\$ 182.00	?
16	FENDER - LH <i>Regis</i>	\$ 778.00	x.
17	FENDER ATTACHMENT PARTS <i>new</i>	\$ 65.00	x
18	FENDER BRACKET - LH	\$ 25.00	x
19	FENDER CENTRE BRACKET <i>2 new nec</i>	\$ 35.00	+
20	FENDER BRACE	\$ 88.00	+
SUB TOTAL SPARE PARTS		\$ 5,372.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 89 M

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	WHEEL HOUSING LINER - LH	\$ 158.00	x
22	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 81.00	x
23	BONNET <i>Dented</i>	\$ 2,898.00	✓
24	BONNET ATTACHMENT PARTS ?	\$ 149.00	?
25	BONNET LID HINGE - LH / RH	2 \$ 112.00	f
26	BONNET HOOD RELEASE LEVER	\$ 81.00	x
27	BONNET STRIKER - LH / RH	2 \$ 200.00	x
28	BONNET EDGE PROTECTION - FRONT <i>NEC</i>	NEC \$ 25.00	✓
29	BONNET CATCH HOOK <i>NEC</i>	\$ 58.00	x
30	LID LOCK WITH MICRO SWITCH <i>NEC</i>	\$ 184.00	x
31	BONNET BOWDEN CABLE <i>NEC</i>	\$ 53.00	x
32	BONNET LID LOCK CABLE <i>NEC</i>	\$ 67.00	x
33	GAS DISCHARGE LAMP HEAD LIGHT - LH <i>cracked</i>	\$ 1,825.00	✓
34	GAS DISCHARGE LAMP <i>Not a</i>	\$ 398.00	x
35	GAS DISCHARGE LAMP CONTROL UNIT <i>NEC</i>	\$ 1,051.00	f
36	DAY DRIVING LIGHTS POWER MODULE	\$ 522.00	x
37	HEADLIGHT HOSE - LH <i>Not a</i>	\$ 46.00	x
38	HEADLIGHT WASHER SYSTEM LIFT CYLINDER <i>Damaged</i>	\$ 181.00	✓
39	LIFT CYLINDER HOSE <i>NEC</i>	\$ 170.00	x
40	WASH WATER PUMP ?	\$ 147.00	?
SUB TOTAL SPARE PARTS		\$ 8,406.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDP 89 M

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
41	WASH WATER RESERVOIR <i>Deformed</i>	\$	186.00	<i>✓</i>
42	WINDSCREEN WASHER SYSTEM PUMP ?	\$	118.00	<i>✓</i>
43	WASH WATER STRAINER <i>✓</i>	\$	19.00	<i>✓</i>
44	WASH WATER END CAP <i>✓</i>	\$	19.00	<i>✓</i>
45	COOLANT RADIATOR LOCK CARRIER ?	\$	663.00	<i>✓</i>
46	READY MIX COOLANT ?	4 \$	84.00	<i>✓</i>
47	RADIATOR AIR GUIDE - LH ?	\$	22.00	<i>✓</i>
48	RADIATOR AIR GUIDE - UPPER CENTRE ?	\$	11.00	<i>✓</i>
49	WINDOW SLOT SEAL WITH TRIM STRIP - LH FRONT <i>✓</i>	\$	282.00	<i>✓</i>
50	WINDOW GUIDE TRIM STRIP - LH <i>✓</i>	\$	235.00	<i>✓</i>
51	FRONT NO. PLATE <i>Ne</i>	S/N \$	40.00	<i>✓</i>
52	SUNDRIES ?	\$	300.00	<i>✓</i>
TOTAL SPARE PARTS		:	\$ 15,757.00	
TOTAL LABOUR CHARGES		:	\$ 11,002.00	
GRAND TOTAL		:	\$ 26,759.00	

All charges are not inclusive of GST.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *29/08/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

without Lock Carrier 88 Days
with Lock Carrier 05 Days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant