

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 06 Sep 2019

Preliminary Advice

Insured Vehicle No : SLE9495C
TP Vehicle No : SH8963B
Make : HYUNDAI I40
Date of Inspection : 30/08/2019
Inspection At : Soon Hock Motor Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Singapore 568047

Accident Date : 27/08/2019
Assignment Date : 29/08/2019
Est. Duration of Repair : 9 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,830.38
Revised Amount	:S\$	20,693.06
Check Items (Estimated)	:S\$	0.00
Total	:S\$	20,693.06
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.