



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower, Singapore 079909		NAME : Ms Ho Siew Lee ADDRESS : 89A Sommerville Estate Road Sommerville Park Singapore 258059		WIP : 49666 EXCESS : DATE : 27.08.2019	
ATTN : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SLH44P	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZZ95ZFLB67269	MILEAGE :		TYPE OF CLAIM :	OD
MODEL :	Macan S	DATE REG.:	13.03.2015	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	P95B-805-475-Y-GRV/HEADLAMP PANEL <i>Repair</i>	1	P95B-805-475-AY-GRV		\$ 302.80
2	FRONT FENDER TOP PANEL <i>bt</i>	1	P95B-821-103-BY-GRV		\$ 283.80
3	SPLASH SHIELD <i>de</i>	1	P95B-809-961-F -		\$ 292.40
4	BUMPER CENTER GRILLE <i>cd</i>	1	P95B-807-683-H -1E0		\$ 329.10
5	BUMPER GRILLE FRAME LH <i>?</i>	1	P95B-807-681- -1E0		\$ 80.90
6	FRONT BUMPER <i>90RN</i>	1	P95B-807-221-A -G2X		\$ 1,084.90
7	BUMPER SIDE TRIM COVER OUTER LH <i>scr</i>	1	P95B-807-819- -1E0		\$ 53.80
8	REINFORCEMENT FOAM <i>?</i>	1	P95B-807-550-G -		\$ 65.80
9	RADIATOR AIR FLAP <i>?</i>	1	P95B-121-257-CY-		\$ 362.70
10	RADIATOR CENTER AIR GUIDE FRONT <i>?</i>	1	P95B-121-710- -1E0		\$ 145.50
11	FRONT TOP SUPPORT PANEL <i>cm</i>	1	P95B-805-931-G -		\$ 362.70
12	TOP SUPPORT PANEL CABLE MOUNTING <i>X</i>	1	P95B-823-411- -		\$ 8.70
13	TOP SUPPORT PANEL CABLE COVER CAP <i>X</i>	1	P95B-823-347- -		\$ 6.40
14	RADIATOR SIDE AIR GUIDE LH <i>?</i>	1	P95B-121-673- -1E0		\$ 43.50
15	FRONT BUMPER GUIDE <i>cm</i>	1	P95B-807-889-C -		\$ 77.40
16	CHARGE AIR COOLER AIR DUCT RR <i>?</i>	1	P95B-117-339-B -		\$ 74.00
17	CHARGE AIR COOLER BRACE <i>?</i>	1	P95B-805-527- -		\$ 98.70
18	CHARGE AIR COOLER BRACKET <i>?</i>	1	P95B-805-295-C -		\$ 225.00
19	CHARGE AIR COOLER AIR DUCT FRT <i>?</i>	1	P95B-117-335- -		\$ 108.80
20	BONNET <i>bu</i>	1	P95B-823-031-KY-GRV		\$ 3,057.90
21	BONNET SEAL <i>re</i>	2	P95B-823-739- -		\$ 14.80
22	BONNET SIDE SEAL LH <i>re</i>	1	P95B-823-721-A -		\$ 22.20
23	BONNET SIDE SEAL RH <i>re</i>	1	P95B-823-722-A -		\$ 22.20
24	BONNET STOPPER <i>re</i>	2	P95B-845-471- -		\$ 36.20
25	BONNET LOCK LOWER <i>bt</i>	1	P95B-823-509-A -		\$ 130.60
26	TOP SUPPORT PANEL TRIM COVER <i>de</i>	1	P95B-805-806-N -1E0		\$ 68.30
27	TOP SIDE TRIM COVER LH <i>de</i>	1	P95B-806-583-B -1E0		\$ 67.40
28	HEADLAMP TRIM COVER LH <i>de</i>	1	P95B-807-173-A -1E0		\$ 53.30
29	PORSCHE CREST <i>re</i>	1	P9P1-853-601- -		\$ 248.60
30	P991-559-215-02-/DESK PAD CREST <i>re</i>	1	P9P1-853-611- -		\$ 14.40
31	HOOD BADGE NUT <i>re</i>	2	PWHT-004-974- -		\$ 3.00
32	FRONT DOOR MOULDING OUTER <i>at</i>	1	P95B-837-475-C -GV9		\$ 130.50
33	NOZZLE TRIM COVER LH <i>mis</i>	1	P95B-955-099-A -		\$ 125.10
34	NOZZLE SUPPORT LH <i>cm</i>	1	P95B-955-159-D -		\$ 38.40

	JZZLE MECHANISM ?	1	P95B-955-978- -		\$ 177.30
	HEADLAMP CR ✓	1	P95B-941-029-EK-		\$ 3,122.50
	HEADLAMP GASKET re ✓	1	P95B-941-323-E -		\$ 92.20
38	HEADLAMP RETAINER PLATE ?	1	P95B-941-121-B -		\$ 63.00
39	SPEED NUT ?	4	PWHT-006-897- -		\$ 53.20
40	P95B-941-181- -/ADDITIONAL HEADLAMP sub ✓	1	P95B-941-181-A -		\$ 348.30
41	DRIVE BELT STICKER re ✓	1	P95B-010-013-P -		\$ 16.40
42	AIR CON INDICATION STICKER re ✓	1	P95B-010-820-D -		\$ 8.90
43	CONDENSER ?	1	P9A7-260-403-01-		\$ 1,437.70
44	RADIATOR ?	1	P9A7-121-251-01-		\$ 1,223.30
45	RADIATOR COVER CAP ?	1	P9A7-133-335-00-		\$ 24.30
46	P000-043-301-47-/ANTIFREEZE PROTECTION re ✓	6	P000-043-305-15-		\$ 190.20
47	CHARGE AIR COOLER LH ?	1	P95B-145-803-B -		\$ 1,523.30
48	MOBIL 1 STICKER re ✓	1	P7PP-010-786-T -		\$ 6.30
49	(WB35) WARNING SIGN STICKER re ✓	1	P7PP-010-006-A -		\$ 5.90
50	BONNET CATCH LH bt ✓	1	0		\$ -
51	BONNET CATCH LOCK NUT re ✓	2	0		\$ -
TOTAL PARTS					\$ 16,332.60
LESS 10%					\$ 1,633.26
TOTAL PARTS COST					\$ 14,699.34
Labour Description					
1	TO REPLACE BONNET, FRONT BUMPER, LH FRONT FENDER, FRONT SUPPORT PANEL, HEADLAMP PANEL & TO REPAIR LH A-PILLAR & LH FRONT DOOR ALL AREAS AFFECTED BY THE ACCIDENT.			7800	\$ 12,480.00
2	TO RESPRAY BONNET, FRONT BUMPER, LH FRONT FENDER, FRONT SUPPORT PANEL, HEADLAMP PANEL, LH A-PILLAR & LH FRONT DOOR.			5100	\$ 6,800.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.			X	\$ 200.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.			150	\$ 200.00
5	TO REMOVE & REPLACE AIR CHARGE COOLER, CONDENSER AND RADIATOR & ASSY.			NETT ?	\$ 1,560.00
6	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.			NETT	\$ 200.00
7	TO SUPPLY 1 PC CHASSIS STICKER			NETT re ✓	\$ 150.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			NETT	\$ 200.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			NETT	\$ 600.00
10	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. receipt ?			NETT	\$ 250.00
11	SUNDRIES.			NETT	\$ 30 50.00
TOTAL LABOUR				\$ -	\$ 22,690.00
TOTAL PARTS				\$ -	\$ 14,699.34

TOTAL	\$ -	\$ 37,389.34
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

***DISCLAIMER**

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE

ASUL

HP 90010068

9 days

30/08/19 @ 1150

EXCESS: TBA

REURT

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: