



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower, Singapore 079909		NAME : Ms Ho Siew Lee		WIP : 49666	
ATTN : MOTOR CLAIMS		ADDRESS : 89A Sommerville Estate Road Sommerville Park Singapore 258059		EXCESS :	
FAX :		TEL :		DATE : 27.08.2019	
VEH NO :	SLH44P	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZZ95ZFLB67269	MILEAGE :		TYPE OF CLAIM :	OD
MODEL :	Macan S	DATE REG.:	13.03.2015	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	P95B-805-475- Y-GRV/HEADLAMP PANEL <i>Repair</i>	1		\$ 302.80
2	FRONT FENDER TOP PANEL <i>bt</i>	1		\$ 283.80
3	SPLASH SHIELD <i>de</i>	1		\$ 292.40
4	BUMPER CENTER GRILLE <i>end</i>	1		\$ 329.10
5	BUMPER GRILLE FRAME LH <i>?</i>	1		\$ 80.90
6	FRONT BUMPER <i>90R</i>	1		\$ 1,084.90
7	BUMPER SIDE TRIM COVER OUTER LH <i>sur</i>	1		\$ 53.80
8	REINFORCEMENT FOAM <i>?</i>	1		\$ 65.80
9	RADIATOR AIR FLAP <i>?</i>	1		\$ 362.70
10	RADIATOR CENTER AIR GUIDE FRONT <i>?</i>	1		\$ 145.50
11	FRONT TOP SUPPORT PANEL <i>cm</i>	1		\$ 362.70
12	TOP SUPPORT PANEL CABLE MOUNTING <i>X</i>	1		\$ 8.70
13	TOP SUPPORT PANEL CABLE COVER CAP <i>X</i>	1		\$ 6.40
14	RADIATOR SIDE AIR GUIDE LH <i>?</i>	1		\$ 43.50
15	FRONT BUMPER GUIDE <i>cm</i>	1		\$ 77.40
16	CHARGE AIR COOLER AIR DUCT RR <i>?</i>	1		\$ 74.00
17	CHARGE AIR COOLER BRACE <i>?</i>	1		\$ 98.70
18	CHARGE AIR COOLER BRACKET <i>?</i>	1		\$ 225.00
19	CHARGE AIR COOLER AIR DUCT FRT <i>?</i>	1		\$ 108.80
20	BONNET <i>bu</i>	1		\$ 3,057.90
21	BONNET SEAL <i>re</i>	2		\$ 14.80
22	BONNET SIDE SEAL LH <i>re</i>	1		\$ 22.20
23	BONNET SIDE SEAL RH <i>re</i>	1		\$ 22.20
24	BONNET STOPPER <i>re</i>	2		\$ 36.20
25	BONNET LOCK LOWER <i>bt</i>	1		\$ 130.60
26	TOP SUPPORT PANEL TRIM COVER <i>de</i>	1		\$ 68.30
27	TOP SIDE TRIM COVER LH <i>de</i>	1		\$ 67.40
28	HEADLAMP TRIM COVER LH <i>de</i>	1		\$ 53.30
29	PORSCHE CREST <i>re</i>	1		\$ 248.60
30	P991-559-215-02-/DESK PAD CREST <i>re</i>	1		\$ 14.40
31	HOOD BADGE NUT <i>re</i>	2		\$ 3.00
32	FRONT DOOR MOULDING OUTER <i>at</i>	1		\$ 130.50
33	NOZZLE TRIM COVER LH <i>mis</i>	1		\$ 125.10
34	NOZZLE SUPPORT LH <i>cm</i>	1		\$ 38.40

35	NOZZLE MECHANISM ?	1		P95B-955-978- -		\$	177.30
36	HEADLAMP CR ✓	1		P95B-941-029-EK-		\$	3,122.50
37	HEADLAMP GASKET ne ✓	1		P95B-941-323-E -		\$	92.20
38	HEADLAMP RETAINER PLATE ?	1		P95B-941-121-B -		\$	63.00
39	SPEED NUT ?	4		PWHT-006-897- -		\$	53.20
40	P95B-941-181- -/ADDITIONAL HEADLAMP sub ✓	1		P95B-941-181-A -		\$	348.30
41	DRIVE BELT STICKER ne ✓	1		P95B-010-013-P -		\$	16.40
42	AIR CON INDICATION STICKER ne ✓	1		P95B-010-820-D -		\$	8.90
43	CONDENSER ?	1		P9A7-260-403-01-		\$	1,437.70
44	RADIATOR ?	1		P9A7-121-251-01-		\$	1,223.30
45	RADIATOR COVER CAP ?	1		P9A7-133-335-00-		\$	24.30
46	P000-043-301-47-/ANTIFREEZE PROTECTION ne ✓	6		P000-043-305-15-		\$	190.20
47	CHARGE AIR COOLER LH ?	1		P95B-145-803-B -		\$	1,523.30
48	MOBIL 1 STICKER ne ✓	1		P7PP-010-786-T -		\$	6.30
49	(WB35) WARNING SIGN STICKER ne ✓	1		P7PP-010-006-A -		\$	5.90
50	BONNET CATCH LH bt ✓	1		0		\$	-
51	BONNET CATCH LOCK NUT ne ✓	2		0		\$	-
TOTAL PARTS							\$ 16,332.60
LESS 10%							\$ 1,633.26
TOTAL PARTS COST							\$ 14,699.34
<u>Labour Description</u>							
1	TO REPLACE BONNET, FRONT BUMPER, LH FRONT FENDER, FRONT SUPPORT PANEL, HEADLAMP PANEL & TO REPAIR LH A-PILLAR & LH FRONT DOOR ALL AREAS AFFECTED BY THE ACCIDENT.					7800	\$ 12,480.00
2	TO RESPRAY BONNET, FRONT BUMPER, LH FRONT FENDER, FRONT SUPPORT PANEL, HEADLAMP PANEL, LH A-PILLAR & LH FRONT DOOR.					5100	\$ 6,800.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.					X	\$ 200.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.					150	\$ 200.00
5	TO REMOVE & REPLACE AIR CHARGE COOLER, CONDENSER AND RADIATOR & ASSY.					NETT ?	\$ 1,560.00
6	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.					NETT	\$ 200.00
7	TO SUPPLY 1 PC CHASSIS STICKER					NETT ne ✓	\$ 150.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.					NETT	\$ 200.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.					NETT	\$ 600.00
10	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. receipt ?					NETT	\$ 250.00
11	SUNDRIES.					NETT	\$ 30 50.00
TOTAL LABOUR						\$ -	\$ 22,690.00
TOTAL PARTS						\$ -	\$ 14,699.34

TOTAL	\$ -	\$ 37,389.34
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

***DISCLAIMER**

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE

Paul

Hp 90010068

9 days

30/08/19 @1150

EXCESS: TBA

REUR

Remove before print