

22/03/2002

ASS. REP. BY:

REF:

CS/C7219015337/K9F3N2

Special Instructions:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Glaine Chong

of

CTI

Date/Time:

30.8.19 10.27.07

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 4662

Insured:

SV 22875

at Workshop m/s

Yu Auto

Tel:

64572620

of

160 sin ming drive #02-17

Policy No:

DMPCSN300179100

Claim No:

SNM 190 204051102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27.8.19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

30.8.19 11.31A.M

Person Contacted:

winnie

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SV 22875 - NA/C7217007375/Y D.O.A. 13/04/2019

SME 4662 - X

13/9 11.31P & 2800 email & confirm (Red 150042.40, 77%)

ASS. REC. BY:

REF: 0721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: DM 41888 Yr Regn: 11, 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M. A180 c.c. 1595Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 38804 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W001760422J393319Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / RIM orTyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 24/8/19

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 30/8/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / Fix pass to

RECEIVED 20 SEP 2019

Date/Time, File Pass to?

1) 20/9 12:15

Date/Time, File Return to?

2)

☐ : Prell. Report☐ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

220

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format:

MER-TP

Lump Sum / I.B.F. (\$)

2900

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019		30 Aug 2019 10:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: LEE POH THYE (LI BAOTAI) , ID: S8119415G									
Vehicle Reg. No.:		SME4166Z	Date of Loss:	27/08/2019 08:00 - :59					
Claim Type:		TP / SNM19D204051C02	Policy/Cover Note No.:	DMPCSN3001791900					
Vehicle Reg. No. (Insured):		SJV2287S	Policy No. (Claimant):	5107249593					
		Excess:	S\$500.00						
Repairer: Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 6457 2625									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/09/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SIN MING AUTOCITY

Work Order: R007074
 Name 2: YEE AUTO PTE LTD
 License: SME 4166 Z
 Odometer: 35605
 Date: 30.8.19 17:01

Mercedes-Benz : 176 (A Class 2012-18) : with Code 485 (W)
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-1°01'		-1°17' -0°37'
0°00'		
0°04'		0°02' 0°12'
1°01'		
0°00'		
		-1°24' -0°24'
	0,0BAR	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.
 Tire Pressure

Front : Right

Actual	Before	Specified Range
-0°47'		-1°17' -0°37'
0°00'		
0°08'		0°02' 0°12'
0°47'		
0°00'		
		-1°24' -0°24'
	0,0BAR	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°14'		-0°24' 0°24'
0°00'		-0°30' 0°30'
0°14'		
0°12'		0°04' 0°24'

Rear : Left

Actual	Before	Specified Range
-2°31'		-1°50' -0°50'
1°04'		-0°04' 0°11'
	0,0BAR	

Camber
 Toe
 Tire Pressure

Rear : Right

Actual	Before	Specified Range
-1°07'		-1°50' -0°50'
0°08'		-0°04' 0°11'
	0,0BAR	

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-1°25'		-0°30' 0°30'
1°11'		0°00' 0°14'
0°28'		-0°08' 0°08'



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Estimate No: ES1900067

Date: 29 Aug 2019

Policy No:

Veh Reg No: SME4166Z

Make/Model: MERCEDES BEN A180 (R17)

Chassis No: WDD1760422J393319

Engine No: 27091030731249

Reg. Date: 02/11/2015

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 27/08/2019

TP Veh Reg No: SJV2287S

Not Attached

Primary After Pay

11 days @ 2900k

4 days

Estimate Repair Cost to Vehicle No :SME4166Z

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR SPORT RIM - LH '17'	880.00	1 PC	880.00	✓
2 REAR TYRE - LH '17'	400.00	1 PC	400.00	X
			1,280.00	1,280.00
Spare Parts				
3 REAR BUMPER	1,850.10	1 PC	1,850.10	X
4 REAR BUMPER CLIPS	60.00	1 SET	60.00	X
5 REAR CONTROL ARM - LH	582.00	1 PC	582.00	X
6 REAR DOOR - LH	1,680.20	1 PC	1,680.20	X
7 REAR FENDER - LH	1,560.10	1 PC	1,560.10	X
8 REAR KNUCKLE ARM - LH	1,098.00	1 PC	1,098.00	X
9 REAR LOWER ARM - LH	526.00	1 PC	526.00	X
10 REAR SHOCK ABSORBER - LH	784.00	1 PC	784.00	X
11 REAR WHEEL BEARING - LH	642.00	1 PC	642.00	X
			8,782.40	8,782.40
Labour				
12 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	480
13 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	600
14 TO REMOVE/RENEW LH REAR UNDERCARRIAGE.	300.00	1 JOB	300.00	180
15 WHEEL ALIGNMENT	120.00	1 T	120.00	60
16 TO CHECK WIRING FUNCTIONS.	60.00	1 JOB	60.00	20
			2,880.00	2,880.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 27/08/2019
TP Veh Reg No: SJV2287S

Estimate No: ES1900067
Date: 29 Aug 2019
Policy No:
Veh Reg No: SME4166Z
Make/Model: MERCEDES BEN A180 (R17)
Chassis No: WDD1760422J393319
Engine No: 27091030731249
Reg. Date: 02/11/2015

Estimate Repair Cost to Vehicle No :SME4166Z

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 12,942.40
			Add GST @ 7%	905.97
			Total Amount Payable	SS 13,848.37

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND EIGHT HUNDRED FORTY EIGHT AND CENTS THIRTY SEVEN ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119015337/KQF3N2

Date: 23/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3001791900
Claimant Vehicle No :	SME4166Z	Insured Vehicle No :	SJV2287S
Date of Loss:	27/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D204051C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME4166Z	Engine No:	27091030731249
Make & Model:	MERCEDES-BENZ A180, 1.6 (A)	Chassis No:	WDD1760422J393319
Reg. Date:	02/11/2015 (Man. Year: 2015)	Odometer:	38604 km
Colour:	Metallic Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,062.40	2,385.07	7,677.33	76.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,340.00	1,540.00	53.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,942.40	3,725.07	9,217.33	71.22
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	12,942.40	2,900.00	10,042.40	77.59
+ GST 7.00/7.00% (S\$)	905.97	203.00	702.97	77.59
Nett Amount (S\$)	13,848.37	3,103.00	10,745.37	77.59

INSPECTION

Date of Assignment:	30/08/2019	
Date Inspected:	30/08/2019 Inspected At:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Sep 2019)	
Parts:	N/A	MERCEDES-BENZ A180 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME4166Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,850.10 F	*- FL
2	1		*SET REAR BUMPER CLIPS	Not Necessary	60.00 F	*- FL
3	1		*REAR CONTROL ARM-LH	Serviceable	582.00 F	*- FL
4	1		*REAR DOOR-LH	Repair	1,680.20 F	*- FL
5	1		*REAR FENDER-LH	Repair	1,560.10 F	*- FL
6	1		*REAR KNUCKLE ARM-LH	Bent	1,098.00 F	*1,098.00 FL
7	1		*REAR LOWER ARM-LH	Distorted	526.00 F	*187.40 FL
8	1		*REAR SHOCK ABSORBER-LH	Serviceable	784.00 F	*- FL
9	1		*REAR WHEEL BEARING-LH	Necessary	642.00 F	*386.90 FL
10	1		*REAR SPORT RIM-LH 17	Dented	880.00 FS	*880.00 FS
11	1		*REAR TYRE-LH 17	Serviceable	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,062.40	2,552.30
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	167.23
Total Parts (\$\$)	10,062.40	2,385.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,200.00	480.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,200.00	600.00
3	TO REMOVE/RENEW LH REAR UNDERCARRIAGE	New	300.00	180.00
4	WHEEL ALIGNMENT	New	120.00	60.00
5	TO CHECK WIRING FUNCTIONS	New	60.00	20.00
Gross Labour Cost (S\$)			2,880.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >