

趙 源 摩 哆

Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 566047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0466
 Business Reg. No: 221880/00C GST Reg. No: MX-0485007-A0

To: MSIG Insurance (S) Pte Ltd

Not Authorized
 Wpy 87
 ER 500h

5day

A80458027QMY

Policy No:

29.08.2019

Date:

Accident Date : 27.08.2019

File: 62564315

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	金额 Amount \$ cts.
Estimate Cost of Repair to "Nissan Pulsar" Reg. No. SLQ1878X			
1pc	Bonnet		1,204.90 N
1pc	Bonnet Rubber Seal		77.50 N
8pc	Bonnet Insulator Clips	2.60	20.80 N
1pc	Bonnet Lock		244.10 N
1pc	Grille		CM 422.70 N
1pc	Grille Emblem		82.00 N
1pc	Grille Chrome Moulding		285.00 N
2pcs	Headlamps (LED)	1,436.40	2,872.80 N
1pc	Front Bumper		1,117.40 N
12pcs	Front Bumper Clips	2.60	31.20 N
2pcs	Front Bumper Top Retainers	28.20	56.40 N
1pc	Front Bumper Bracket LH		143.20 N
1pc	Front Bumper Sponge		176.00 N
1pc	Front Bumper Reinforcement		454.50 N
1pc	Front Bumper Tow Cover		28.10 N
1pc	Front Bumper Corner Retainer LH		35.20 N
1pc	Support Panel		Ben 329.60 N
1pc	Support Panel Top Ganish		CM 417.20 N
11pcs	Support Panel Top Ganish Clips	2.60	28.60 N
			8,027.20
			802.72
	Less 10%		7,224.48
1pc	Front Number Plate		45.00 SN
1pc	Air Con Condenser		443.40 SN
1pc	Radiator		638.00 SN
	To Conduct Electrical Check, Focus Headlamp		30.00 200
	To Remove / Refit Air Con Condenser & Refill Gas		120.00 1000
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 500
	Labour Charge - Panel Beating, Repairing Of Chassis Member, Inner Panel, Front Fenders etc. Cnt, Weld Support & Parts Replacement.		900.00 6000
	To Spray Painting Affected Areas		850.00 7200
	Total :		10,310.88

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: