

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10321

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1033/2019/NS
Date	:	29-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Xinsha Holding Pte Ltd
Address	:	Blk 6A Boon Tiong Road Singapore 164006
Telephone	:	(HP)+65 96552323
Type of Claim	:	Own Damage Claims
Policy No.	:	1800108691
Vehicle No	:	SME 2447 B
Model Code	:	Audi Q7 2.0 TFSI QU
Model / Year	:	24/9/2018
Engine No	:	CYR 066147
Chassis No	:	WAUZZZ4M8JD050408
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	25-Aug-19
Place of Accident	:	Havelock Rd Turning To Clemenceau Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 2447 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle and renew front bumper assy. Re-organise crash management components. Reinstall all parts removed.	\$ 1,350.00	600
3	To respray front bumper.	\$ 1,350.00	600
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>3,372.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2447 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>rehd</i>	\$ 2,242.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 403.00	+
3	FRONT BUMPER AIR GUIDE - LH / RH <i>?</i>	2 \$ 120.00	?
4	FRONT BUMPER END CAP - LH / RH <i>new</i>	2 \$ 64.00	+
6	FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE <i>?</i>	\$ 252.00	?
7	FRONT BUMPER GRILLE-LOWER CENTRE <i>new</i>	\$ 187.00	+
8	FRONT BUMPER UNDERRUN BAR <i>new</i>	\$ 735.00	+
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 191.00	+
10	FRONT BUMPER SPOILER-LH <i>new</i>	\$ 126.00	+
11	FRONT BUMPER SPOILER-LH OUTER <i>new</i>	\$ 40.00	+
12	RADIATOR GRILLE <i>new</i>	\$ 2,269.00	✓
13	RADIATOR GRILLE COVER <i>?</i>	\$ 62.00	?
14	RADIATOR GRILLE INNER COVER <i>?</i>	\$ 56.00	?
15	FRONT BUMPER AIR GUIDE GRILLE-LH <i>?</i>	\$ 271.00	?
16	FRONT BUMPER AIR GUIDE GRILLE CAP- LH <i>new</i>	\$ 30.00	+
17	AIR GUIDE GRILLE SPOILER - LH FRONT INNER <i>new</i>	\$ 55.00	+
18	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	\$ 156.00	?
19	FRONT BUMPER CARRIER <i>?</i>	\$ 791.00	?
20	FRONT BUMPER CARRIER SUPPORT-LH/RH	2 \$ 66.00	
SUB-TOTAL SPARE PARTS		: \$ 8,116.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2447 B

S/N	Parts Description	<u>Damaged Parts & Prices</u>		Remark
		S/Nett		
21	FRONT BUMPER GUIDE SECTON- LH <i>new</i>	\$	40.00	<i>x</i>
22	FRONT BUMPER COVER <i>new</i>	\$	119.00	<i>x</i>
23	CAUTION SIGN <i>new</i>	NEC \$	13.00	<i>x</i>
24	FANFARE BRACKET - LH LOW TONE <i>new</i>	\$	206.00	<i>x</i>
25	FRONT PARKING AID SENSOR - INNER OUTER <i>3 new</i>	2 \$	462.00	<i>x</i>
26	FRONT PARKING AID SENSOR SEAL RING	4 \$	12.00	<i>x</i>
27	RADIATOR AIR GUIDE - LH <i>3 new</i>	\$	25.00	<i>x</i>
28	RADIATOR AIR GUIDE - LOWER	\$	37.00	<i>x</i>
29	FRONT WHEEL COVER - LH / RH <i>new</i>	2 \$	604.00	<i>✓</i>
30	WHEEL COVER CLIP <i>new</i>	NEC \$	5.00	<i>✓</i>
31	GROMMET <i>?</i>	NEC \$	63.00	<i>?</i>
32	FRONT NO. PLATE <i>Bent</i>	S/N \$	40.00	<i>✓</i>
33	SUNDRIES <i>?</i>	\$	300.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 10,042.00	
TOTAL LABOUR CHARGES			\$ 3,372.00	
GRAND TOTAL			\$ 13,414.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *30/08/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *not authorized, 03 days*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant