

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10306

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1032/2019/NS
Date : 29-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Li Yang
Address : 3 Leedon Heights
#24-03
Singapore 267951
Telephone : HP +65 84916241
Type of Claim : Own Damage Claims
Policy No. : 1800152058
Vehicle No : **SMG 6109 R**
Model Code : Audi Q5 SPORT 2.0 TFSI qu
Model / Year : 26/12/2018
Engine No : DAX 046779
Chassis No : WAUZZZFYXJ2241758
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Aug-19
Place of Accident : NTU Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMG 6109 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00	✓
2	To dismantle and renew rhs front door and rhs rear door. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,400.00	1000 ✓
3	To respray rhs front door, rhs rear door and door covers.	\$ 3,000.00	1500 550 x 2 = 1100 Door Cover x 2 = 200 x 2 = 400
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 6,152.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMG 6109 R**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - ^{LH} RT Dented.	\$ 2,829.00	✓
2	BONDING AGENT ?	NEC \$ 45.00	?
3	CLEANING SOLUTION ?	NEC \$ 65.00	?
4	FRONT DOOR ATTACHMENT PARTS ?	\$ 239.00	?
5	FRONT DOOR CATCH the new	\$ 132.00	+
6	TYRE PRESSURE DATA PLATE new	\$ 35.00	✓
7	FRONT DOOR COVER - RH new	\$ 661.00	✓
8	REAR DOOR - ^{LH} RT Dented	\$ 2,829.00	✓
9	BONDING AGENT ?	NEC \$ 45.00	?
10	CLEANING SOLUTION ?	NEC \$ 65.00	?
11	REAR DOOR SEALING STRIP new	\$ 15.00	+
12	REAR DOOR ATTACHMENT PARTS ?	\$ 201.00	?
13	REAR DOOR OUTER SEAL new	NEC \$ 190.00	✓
14	REAR WEATHER STRIP - RH new	\$ 201.00	+
15	REAR DOOR CATCH new	\$ 132.00	+
16	REAR DOOR COVER - ^{LH} RT new	\$ 577.00	✓
17	OUTER DOOR SEAL - FRONT new	NEC \$ 185.00	✓
18	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		\$ 8,746.00	
TOTAL LABOUR CHARGES		\$ 6,152.00	
GRAND TOTAL		\$ 14,898.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 30/08/14.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant