



AMA Autocare Pte Ltd
 Enterprise Hub 36 Toh Guan Road East #01-36
 Singapore (608580)
 E: ama.claim@gmail.com
 T: 87783636

Vehicle No. Estimate SLS7565Z Toyota prius 1.8A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front door RH		1294.00	Ry
1	Front door handle RH		279.00	Ry
1	Front door hinges LH@\$107.00		214.00	X
1	Front fender inner shield RH		236.00	X
1	Side mirror cover RH		363.00	dis ✓
1	Side mirror glass RH		280.00	dis ✓
1	Side mirror motor RH		473.00	* 3 dis ✓
1	Side mirror signal light RH		184.00	dis ✓
1	Side mirror side garnish RH		241.00	X
			3564.00	0.00
		less 25%	891.00	25% 0.00
			2673.00	0.00
SPECIAL NETT ITEMS				
1	Front fender inner shield clips		40.00	X
	TOTAL PARTS		2713.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636

Page No. 2

Vehicle No. Estimate SLS7565Z Toyota prius 1.8A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	600.00	200.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	600.00	250
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	150.00	30
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	100.00	X
5	To provide anti-rust treatment on affected areas	100.00	X
	Labour Total :	1550.00	
	TOTAL (PARTS & LABOUR):	4263.00	

Taylor 97495745
"WP"
25/9/14 @ 5:15pm
Impson 02 days
Rong after repair