

Date: 29.08.2019
Vehicle No: SLF3233B
Model: KIA FORTE K3 1.6A
Chassis: KNAFX411MH5656166 - 2016
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SKL4932R
Date of Accident: 27.08.2019

*Not Authorise
61 Day 87
Resurvey After Paint 3 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>R</i> \$864.00 ✓
2	REAR BUMPER CLIPS	12	\$5.50	<i>na</i> \$66.00 ✓
3	REAR BUMPER SIDE BRACKET RH	1		<i>D.1</i> \$48.00 ✓
4	REAR BUMPER LOWER COVER	1		<i>Red / na</i> \$468.00 ✓
5	REAR BUMPER UPPER BRACKET RH	1		\$64.20 ✓
6	REAR QUARTER PANEL RH			REPAIR ✓
			SUB TOTAL	\$1,510.20
			LESS 10%	\$151.02
			PARTS TOTAL	\$1,359.18

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC

200
\$300.00 *200*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC

400
\$600.00

TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC

\$80.00 *50*

TO CHECK WIRING & ELECTRICAL SYSTEMS

\$60.00 *20*

TO TUFF KOTE & UNDERSEAL MATERIALS

na \$100.00 *X*

LABOUR TOTAL \$1,140.00

ONG	TOTAL \$2,499.18
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplemental claim(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Sign Date	

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

