

FIRST AUTOWORKS

Repair Estimate

Date : 28/08/2019

Reference: SMH 595D

To Whom It May Concern

Make: VW
Scirocco

Dear Sir,

RE: VEHICLE : SMH 595D
CHASSIS NO.: WVWZZZ13ZBV004660
ENGINE NO.: CAV210503

TP A19
Khanchar.

Name of insured : Dickson Soh Ming Hao
Date of accident.: 24/08/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	REAR BUMPER <i>Distal d</i>	1,200.00 ✓
2	1	REAR BUMPER REFLECTOR RH <i>Best New</i>	130.00 +
3	1	REINFORCEMENT, RR END PANEL <i>Best</i>	390.00 ✓
4	1	REAR BUMPER GUIDE CENTER <i>New</i>	130.00 ✓
5	1	REAR BUMPER GUIDE LH <i>New</i>	87.00 ✓
6	1	REAR VW EMBLEM <i>2 New</i>	120.00 +
7	1	LETTERING SCIROCCO <i>2 New</i>	110.00 +
8	1	REAR TAILGATE <i>Distal d</i>	1,800.00 +
		<i>Reverse sensor</i>	
		<i>2800 (2015/16)</i>	
		<i>1957</i>	
		<i>1761.30</i>	
Parts Total:			3,967.00
Less 10%:			396.70
Total :			3,570.30

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2100.00 <i>400</i>
2	Carry out spray painting on accident affected area. (Rear Tailgate, Rear bumper, Rear end panel)	1900.00 <i>800.</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	150.00 <i>30</i>
4	Remove and refit reverse sensor (Labour)	1080 <i>130.00</i> <i>50</i>
Labour Total :		4,280.00

Adrian Lij
H/S 29/08/19.
04 Days.

Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	Sealant <i>HE</i>	50.00 ✓
2	Rear number plate <i>HE</i>	40.00 ✓
3	Rear Bumper Clip Set <i>HE</i>	40.00 ✓
Other Total :		130.00

Total : \$7,980.30
Gst (7%) : \$558.62
GRAND TOTAL: \$8,538.92

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Service Advisor
Ronnie Tan
DID: 6844 1985 Fax:6844 5185

*total: 2881.30
4/5: 2.3K.
03 Day.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16, Singapore 079120

GST Ref. No: M2-0111811-5

Vehicle No: SMH 595D
Chasis No : WVWZZZ13ZBV004660
Engine No: CAV210503

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.	Description	Price (SGD)
1	1	REAR BUMPER	1,200.00
2	1	REINFORCEMENT, RR END PANEL	390.00
3	1	REAR BUMPER GUIDE LH	87.00
4	1	REVERSE SENSOR SET	280.00

Total: 1957.00
Less 10%: 195.70
Parts Total : 1761.30

Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	400.00
2	Carry out spray painting on accident affected area. (Frt Bumper, Rear Tailgate, Rear bumper, Rear end panel)	600.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	30.00
4	Remove and refit reverse sensor (Labour)	50.00

Labour Total : 1080.00

Other

No.	Other Description	Price (SGD)
1	Rear Bumper clip Set	40.00

Other Total : 40.00

Total : 2881.30
Lump sum Less 20%: 576.26
Total : 2305.04
GST (7%) 161.35
Grand Total: 2466.39

Yours Faithfully,



Ronnie Tan
Service Advisor
Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185