



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Teo Wei Xiong, Justin ADDRESS : 26 Palm Grove Avenue Singapore 547334 TEL : 91594043		WIP : 61798 EXCESS : DATE: 29-Aug-19	
VEH NO :	SLC1192P	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	MM6DL2SAAGW185987	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA2	DATE REG.	29-Apr-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	REAR BUMPER <i>de-</i>	1	MDB7A-50-221BBB		\$ 954.50
2	BRACKET CENTER ?	1	MKD53-50-251		\$ 5.40
3	STAY, REAR BUMPER ?	2	MDB7A-50-271		\$ 26.00
4	REFLECTOR LHS X	1	MD350-51-5L0E		\$ 53.00
5	TAPE PROTECTOR, REAR BUMPER <i>ne /</i>	3	MGS1D-50-EM1A		\$ 25.80
6	GROMMET, REAR BUMPER <i>ne /</i>	4	MBHN1-50-0Z1A		\$ 10.80
7	GROMMET, REAR BUMPER <i>ne /</i>	2	M9991-00-501		\$ 6.00
8	FASTENER, REAR BUMPER <i>ne /</i>	7	MB45A-56-146A		\$ 21.00
9	REAR END PANEL <i>repair</i>	1	MDBYA-70-75Z		\$ 656.00
10	TRIM, END PANEL ?	1	MDB7G-68-89X 02		\$ 57.60
11	BEZEL, LOCK X	1	MDB7G-68-894 02		\$ 5.70
12	FASTENER, TRIM <i>ne -</i>	32	MGJ21-68-885B02		\$ 96.00
13	ORNAMENT, MAZDA X	1	MDB7G-51-721		\$ 57.90
14	MASCOT, REAR X	1	MDB7G-51-730		\$ 58.20
15	ORNAMENT, SKYACTIVE X	1	MDB7G-51-771		\$ 67.60
16	GROMMET, BOOTLID X	2	MGA7B-51-146		\$ 6.60
17	GASKET LHS, BOOTLID X	1	MDB7A-51-3J8		\$ 48.60
18	GASKET RHS, BOOTLID X	1	MDB7A-51-3H8		\$ 48.60
19	GASKET LHS, TAILLAMP <i>ne /</i>	1	MDB7A-51-163		\$ 33.50
20	GASKET RHS, TAILLAMP <i>ne /</i>	1	MDB7A-51-153		\$ 33.50
21	GUARD STONE LHS, X	1	MDB1L-50-4R2		\$ 14.70
22	GUARD STONE RHS, X	1	MDB1L-50-4P2		\$ 14.70
TOTAL PARTS					\$ 2,301.70
LESS 10%					\$ 230.17
TOTAL PARTS COST					\$ 2,071.53

Labour Description

1	TO REPLACE REAR BUMPER, REAR END PANEL. TO REPAIR, REAR FLOOR PANEL, BOOTLID, REAR FENDER LH, REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.	990	\$ 4,620.00
2	MZ-SP-SREAR7 TO RESPRAY REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL, BOOT LID, REAR FENDER LH AND REAR FENDER RH.	1260	\$ 4,095.00

3	MZ-BR-REVERSE	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	330 ³	NETT	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA. X		NETT	\$ 330.00
5	MZ-BR-TRIMS	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION. X			\$ 990.00
6	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING X			\$ 350.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150		\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150		\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180		\$ 350.00
10		TO SUPPLY BODY COATING. X		NETT	TBA
11	MZ-BR-SUNDRI	SUNDRIES.		NETT	\$ 20 100.00

TOTAL LABOUR	\$ -	\$ 11,995.00
TOTAL PARTS	\$ -	\$ 2,071.53
TOTAL	\$ -	\$ 14,066.53
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION
AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE
PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE
THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT
SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS,
A QUOTATION FEE OF \$400 WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR
PARTS PRICE AS WELL AS LABOUR CHARGES

TRANS EUROKARS PTE LTD

Authorised Signature

RASUL
Hp 900 10068
4-5 days
17/09/19 @ 1045
Resurvey before part

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: