



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
Our Ref : TP0065/08/19 Date : 30/08/2019

THIRD PARTY CLAIM

M/S : J & J GLASS CONSTRUCTION

Attn :
Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GZ2449G - NISSAN CABSTAR LORRY
INSURED : J & J GLASS CONSTRUCTION
DATE OF ACCIDENT : 23/08/2019
POLICY NO : A29068134MRC

ENGINE# :
CHASSIS# :

Not Altered
slur
1/5 #4300
30/8/19
take the 1/5 up
5 day.

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

Qty	U/Price	Total
	\$	\$
Netts Items		
1 rear tailgate center door	10 1459.60	1,459.60
2 rear tailgate top lock L&R	20 182.90	365.80
3 rear tailgate lower bracket L&R	20 52.00	104.00
4 rear tailgate lower panel	10 417.00	417.00
5 rear lamp assy L&R	20 174.80	349.60
6 rear tailgate stopper mounting L&R	20 14.00	28.00
7 rear number plate bracket	10 64.40	64.40
8 rear number plate lamp	10 80.20	80.20
9 rear chassis member centre cross member	10 588.00	588.00
10 rear lamp bracket L&R	20 45.00	90.00
11 rear spare tyre bracket with chain	10 291.60	291.60
12 rear exhaust pipe	10 627.40	627.40
13 rear tailgate aluminum rivet	400 5.00	200.00
		4,665.60
Less 10%		-466.56
Total Nett		\$4,199.04
Special Nett Items		

15 rear tailgate 70km/h sticker	10 20.00	20.00
16 rear tailgate 13 PAX sticker	10 20.00	20.00
17 rear number plate with casing	10 45.00	45.00
18 rear tailgate railing bar L&R	20 450.00	900.00
19 rear step bar L&R	20 200.00	400.00
20 towing hook bar	10 350.00	350.00
		1,735.00
		0.00
Total S/Nett		\$1,735.00

L/Alke Asher

body 100

1/5 set

Best

one

1/5 torn 1/5 set

Best

Best

1/5

3078.36

1/5

1/5

1/5

1/5

1/5



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Registration No: QAIC/SG/106

Your Ref :
Our Ref : TP0065/08/19

Page : 2/2
Date : 30/08/2019

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Labour & Misc				
1 Remove & install rear cabin door, cut out & renew r/cabin lower panel, chassis member, knock r/cabin side panel, chassis crossmember, stepboard panel and restraighthen body & chassis.				1,800.00 ¹⁰⁰⁰
2 Spray painting with tuff kote.				1,000.00 ⁸⁰⁰
3 Car-O-Liner.	11	380.00		4180.00 ^x
4 Check wiring system.				35.00 ²⁰
				<u>3,215.00</u>
Total Labour				<u>\$3,215.00</u>
Nett Total Before Gst				<u>\$9,149.04</u>

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-307836
S.W 510.00
L -1820.00
540836
202
4326.