

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-4B PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

ATTN: MARCUS
(4 pages)

k

not Adm
HALL

$\frac{2/5 \times 2800}{4 \text{ days}}$
 2800 lbs. at the cage

ABWIN 論輝
Service Centre

ESTIMATED COST: HQQ000094

TO : AIG ASIA PACIFIC INSURANCE PTE, LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SKB8596D
SOH SEN KIAN
BLK 972 HOUGANG STREET
91
#14-196
SINGAPORE 530972
CONTACT NO : 98233924

DATE	:	03-SEP-2019
MAKE	:	DAIHATSU
MODEL	:	MATERIA 1.5L AUTO ABS
		AIRBAG 2WD
CHASSIS NO	:	JDAM402S001015057
ENGINE NO	:	2382686
SERVICE ADVISOR	:	SHARIFAH
PAGE	:	1 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FRONT DOOR LH	2	1,134.00	α	1,134.00
1	REAR DOOR LH	20/sep	960.00	—	152 1,693.20
1	ROCKER PANEL GARNISH LH	Deep cam	1,032.00	—	3,513.20
1	REAR FENDER LH	2	832.50	α	
Sub Total			3,958.50		0.00

SPECIAL NETT

1	FRONT DOOR LH SEALANT	n7	50.00	X
1	REAR DOOR LH SEALANT	n7	50.00	9
10	ROCKER PANEL GARNISH LH CLIPS	neu	50.00	✓
1	REAR FENDER LH SEALANT	n7	50.00	X
1	REAR WHEEL RIM LH	C47/Bef	480.00	300 s.w
1	REAR TYRE LH	for	250.00	X
Sub Total			930.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00	500
1	TO SPRAY PAINT ON AFFECTED AREAS	1,000.00	800
1	TO CHECK WIRING	120.00	20
1	TO APPLY UNDERCOATING FOR RUST PROOFING	150.00	30
1	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	120.00	60
1	TO DISMANTLE, REPLACE AND/OR REPAIR FRONT DOOR LH COMPONENTS	150.00	11
1	TO DISMANTLE, REPLACE AND/OR REPAIR REAR DOOR LH COMPONENTS	150.00	11
LKK Auto Consultants hence notify the Subcontractor the following:		2,490.00	0.00

LKK Auto Consultants hence notify the **Sub Total** line following: **2,490.00**

- To resurvey before other spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
- The initial survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

5. Sep. 2019 10:34

No. 3094 P. 2

ABWIN SERVICE PTE LTD

8 KAKI BUKI AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000094**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 03-SEP-2019
 MAKE : DAIHATSU
 MODEL : MATERIA 1.5L AUTO ABS
 AIRBAG 2WD
 CHASSIS NO : JDAM402S001015057
 ENGINE NO : 2382686
 SERVICE ADVISOR : SHARIFAH
 PAGE : 2 OF 2

SKB8596D
SOH SEN KIAN
 BLK 972 HOUGANG STREET
 91
 #14-196
 SINGAPORE 530972
 CONTACT NO : 98233924

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

SUB-TOTAL	7,378.50	0.00
GST - 7 %	516.50	0.00
TOTAL	7,895.00	0.00

ABWIN SERVICE PTE LTD

Prepared By