

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67483016
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 2004025700

AA: Adrian
Fax: 62564315

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68367416

TPALG.
Jiale.

Estimate : TP19-112

Date : 28/08/2019
Vehicle Num. : SEB6789J
Make/Model : Honda Vezel-2014
Chassis/Eng# : RU11018590/L15B3516305
Accident Date : 28/08/2019
Claim No. :
Reference :
Policy No. : (13/05/2020)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Bonnet <i>Distorted</i>		982.50 ✓
2.	2 pcs	Bonnet Hinge L/R <i>Best</i>	68.50	137.00 ✓
3.	1 pc	Bonnet Mechanism Lock		115.90 ✓
4.	1 pc	Bonnet Lock Bracket <i>cut</i>		74.10 ✓
5.	1 pc	Bonnet Weatherstrip <i>new</i>		52.80 X
6.	1 pc	Bonnet Stand <i>new</i>		39.10 X
7.	1 pc	Bonnet Insulator <i>sampled</i>		172.30 ✓
8.	3 pcs	Bonnet Insulator Clips <i>new</i>	4.20	33.60 ✓
9.	2 pcs	Headlamp Assy L/R <i>Attended</i>	1,820.40	3,640.80 <i>1820.40</i>
10.	2 pcs	Headlamp Bracket L/R <i>Attended</i>	53.00	106.00 <i>53</i>
11.	2 pcs	Frt Bumper Side Holder L/R <i>new</i>	36.20	72.40 ✓
12.	1 pc	Frt Bumper Assy <i>Distorted</i>		503.20 ✓
13.	12 pcs	Frt Bumper Clips <i>new</i>	3.80	45.60 ✓
14.	1 pc	Frt Bumper Reinforcement <i>Best</i>		481.00 ✓
15.	1 pc	Frt Bumper Foglamp Garnish RH <i>Deformed</i>		56.50 ✓
16.	1 pc	Frt Bumper Foglamp RH <i>new</i>		387.10 X
17.	1 pc	Frt Bumper Lower Air Grille <i>Deformed</i>		110.75 ✓
18.	1 pc	Frt Bumper Lower Lip <i>Distorted</i>		250.00 ✓
19.	1 pc	Frt Bumper Under Cove <i>torn</i>		151.80 ✓
20.	1 pc	Frt Grille Assy <i>cut</i>		506.20 ✓
21.	1 pc	Frt Grille Chrome Trim <i>new</i>		95.00 X
22.	1 pc	Horn <i>new</i>		63.00 X
23.	2 pcs	Radiator Support Panel Assy (Top/Lower) <i>Distorted</i>	676.10	1,352.20 <i>5%</i>
24.	1 pc	Radiator Support Panel Top Cover Garnish <i>Deformed</i>		105.00 ✓
25.	1 pc	Radiator Assy <i>new</i>		1,250.60 X
26.	2 pcs	Radiator Top Bush Mounting <i>new</i>	21.40	42.80 ✓
27.	1 pc	Radiator Top Hose <i>new</i>		55.00 X
28.	1 pc	Radiator Spare Tank <i>new</i>		79.50 X
29.	1 pc	Radiator Auxiliary Fan Assy <i>new</i>		605.80 X
30.	1 pc	Aircon Condenser <i>Dented</i>		350.00 ✓
31.	1 pc	Aircon Liquid Pipe <i>new</i>		235.00 X
32.	1 pc	Aircon Discharge Hose <i>new</i>		275.00 X

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-112

Date : 28/08/2019

Vehicle Num. : SBE6789J

Make/Model : Honda Vezel-2014

Chassis/Eng#: RU11016590/L15B3516605

Accident Date : 28/08/2019

Claim No. :

Reference :

Policy No. : (13/05/2020)

S/N	Quantity	Particular	Unit Price	Amount \$
-----	----------	------------	------------	-----------

33.	1 pc	Aircon Aluminium Pipe <i>new</i>		259.00 +
34.	1 pc	Air Intake Duct <i>del</i>		95.20
35.	1 pc	Gearbox Mounting <i>torn</i>		345.90
36.	3 pcs	Engine Mounting <i>pipe torn</i>	265.00	795.00 265.
37.	1 pc	Frt Fender RH <i>distorted</i>		620.00
38.	1 pc	Frt Fender Guard Garnish RH <i>del</i>		210.65
39.	1 pc	Frt Fender Inner Liner RH <i>torn</i>		352.20 229
40.	1 pc	Frt Fender Inner Panel RH <i>distorted</i>		218.90
41.	1 pc	Frt Wheel House Panel RH <i>del</i>		400.50 +
42.	1 pc	Windscreen Washer Tank <i>del</i>		135.00
43.	1 pc	Windscreen Washer Tank Motor <i>new</i>		89.00 +
44.	1 pc	Frt Chassis Frame RH <i>del</i>		955.00 +
45.	1 pc	Frt Wiper Garnish <i>del</i>		280.00
46.	1 pc	Steering Airbag <i>Activated</i>		1,805.80
47.	1 pc	Dashboard Airbag <i>torn</i>		2,366.80
48.	1 pc	Dashboard Fascia		980.60
49.	1 pc	Air Bag Sensor <i>Activated</i>		195.00
50.	1 pc	Air Bag ECU		980.00
51.	2 pcs	Frt Bumper Bracket L/R <i>new</i>	36.20	72.40 +
52.	1 pc	Roof Top Inner Upholstery Trim <i>new</i>		1,250.00 +
53.	1 pc	Roof Airbag RH (Curtain) <i>Activated</i>		1,180.10
54.	1 pc	Frt Windscreen Pillar Inner Trim Garnish RH <i>new</i>	18,362.60	151.60 +
55.	1 pc	Frt Driver Seatbelt RH <i>Activated</i>		654.80
56.	1 pc	Frt Passenger Seatbelt LH <i>Activated</i>	14,690.08	654.80
57.	2 pcs	Centre Pillar Inner Lower Trim Garnish L/R <i>new</i>	132.80	265.60 +

List Total \$:

28,301.60

20.00% Discount \$:

5,660.32

22,641.28

1. 1 pc SPECIAL NETT ITEMS:

Frt No Plate w/frame *sent*

35

35.00

Special Nett Total \$:

35.00

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-112

Date : 28/08/2019

Vehicle Num. : SBB6789J

Make/Model : Honda Vezel-2014

Chassis/Eng# : RU11016590/L15B3516605

Accident Date : 28/08/2019

Claim No. :

Reference :

Policy No. : (13/05/2020)

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		To remove, rearrange electrical wirings, check lighting	120.00	30
		To remove, reinstal aircon parts, vacuum, refill gas.	250.00	120
		To remove & replace engine to facilitate repair.	450.00	280
		To remove, replace frr undercarriage parts.	320.00	X
		Wheel Alignment Test.	180.00	X
		To remove, replace frr dashboard to facilitate repair.	250.00	220
		To remove, replace airbag, change sensor, wiring dashboard airbag & seatbelts.	500.00	350
		To remove, replace roof top lining upholstery.	220.00	150
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	3,200.00	1400
		To putty and respray painting on affected area.	1,800.00	1200
		Labour Total S\$:	7,290.00	

3750

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 29,966.28

total: 18475.08

w/s : 14-71C ✓

14 Days