

INS. CASE OWNER:

CC6/CTI19015394/ T1 ha3 n2

LKK:
IDAC:

Surveyor:

TAUMIKH

DOI:

ASSIGNMENT

30/08/19

Date / Time : 30/08/2019

Registered in Merimen: —

Pre-assign / CCU / FTE



Insured Vehicle No. : SDN 8203H

Claim No. : SNM19D204066

Name of Insured : THASNEEM PARVEEN S Q SIRAZUDEEN

Policy No. : DMPCSN3002181900

Insured Tel No. : HP: 8139 8465

Make / Model :

Excess Sec II : S\$ D.O.A : 29/08/2019

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

SHD 2252K

INSRS:
WSP: PRIME AUTO
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	SHD 2252K - CS/INC10011107/Kfg1;DOA:4/4/10 SDN 8203H - X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
03/09/19	- POSSIBLE 3 TP CLAIMS - MUST BE REVIEWED. OIC HAT 3 VEHICLES. - UNABLE TO STOP IN TIME, 4 SQUADERS - IN BETWEEN LANSO. SEND LETTER & - EMAIL TO OI TO NOTIFY TP CLAIM & AGO - ISSUED. - TP VIDEO IN. V/LIC / SHD 2252K - TP LOD IN BY EMAIL.	Call OI:	
		After call ltr to OI: 03/09/19 - vic	
		Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
11/09/19	- TYPE REPORT FOR MANDATE APPROVAL	Car Rental Invoice:	☒
	- REPORT DONE	Towing Invoice	☐
07/10/19	- SEND MANDATE TO OI	LTA / GIA :	☒
	- OI APPROVED MANDATE	Medical Bill:	☐
	- SEND 1ST OFFER TO TP.	PIR:	☐
01/10/19	- TP ACCEPTED OFFER.	Mandate/Reject Instruction:	☒
14/10/19	- ALL DONE IN ORDER. - TO CLOSE	LOD	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE Date/Time: 10/09/19 Sent By: 93

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: L9	SS 6,100.00 / 6	days) Reduction: 36 %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☒ Call ☐
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No. : NIL	If NO or B 28, Ass. Lia :
Repair Cost: (w/ass)	SS 6,527.00		(OIC HAT 3 VEHICLES)
Loss of Rental (LOR):	SS 657.30 (7 days) X \$ 93.90		
Loss of Use (LOU):	SS — (\$ x 7 days)		
Loss of Income (LOI):	SS 350.00 (\$ 50 x 7 days)		
LOR only ☐ LOU only ☐	☐ LOR + LOU ☐ LOR + LOI ☒ (Tick only one)		
GIA/LTA Search	SS 2.00		
Medical:	SS —		
Disbursement:	SS — (e.g. Tow/ Independent)		
Legal Cost	SS —		
Total:	SS 7,536.30	Global Sum SS: —	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 7,536.30	Name 1: PRIME AUTO CLAIMS SERVICE PTE LTD	
Payee 2: (Strike if N.A.)	SS —	Name 2: —	
Payee 3: (Strike if N.A.)	SS —	Name 3: —	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM19D204066
Our ref: CC6/CTI19015394/T1ha3

Date: 10/09/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 2252K

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/8/2019 at the premises of M/s Prime Auto Claims Services Pte Ltd - Tuas and have the following to report:-

Workshop Estimate Amount	: S\$	9,591.48
Revised Estimate Amount	: S\$	7,656.96
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	7,656.96

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 30.08.2019

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE REPAIR TO VEHICLE SHD2252K HONDA SHUTTLE HYBRID (2016)

To Supply

1)	1pc	left rear fender	\$	bt ✓	1,010.90 /
2)	1pc	left rear fender lining	\$	un x	455.00
3)	1pc	left rear door	\$	bt ✓	1,275.30 /
4)	1pc	left front door	\$	bt ✓	1,275.30 /
5)	1pc	left front door outer handle with cover	\$	Rx	322.70
6)	1set	left front door tape	\$	ner ✓	60.55 -
7)	1pc	left front door outer moulding (black color)	\$	cut ✓	250.00 -
8)	1pc	left side mirror assy	\$	dis ✓	527.55 -
9)	1pc	left front quarter glass	\$	un x	290.70
10)	1pc	left front quarter glass seal	\$	un x	55.00
11)	1pc	left front fender	\$	bt ✓	368.95 -
12)	1pc	left front fender "Hybrid" emblem	\$	ner ✓	58.00 -
13)	1pc	left front fender lining	\$	de ✓	115.90 -
14)	1pc	front bumper	\$	de ✓	1,350.00 /
15)	1pc	front bumper left side retainer	\$	ner ✓	35.00 -
16)	1pc	front bumper left side bracket	\$	un x	38.00
17)	1pc	left side skirt	\$	Rx	563.00

Sub total parts	\$	8,051.85
Less: 20% discount	\$	(1,610.37)
	\$	6,441.48

S.Nett parts

1)	1set	rear bumper clip	\$	x	30.00
-----	------	------------------	----	---	-------

2) 1set	front bumper clip	\$	new	30.00	✓
3) 1set	left front fender cowling clip	\$	new	15.00	✓
4) 1set	left rear fender cowling clip	\$	new	15.00	✓
5) 1pc	left rear tyre wheel cover	\$	new	195.00	✓
6) 1pc	"Prime Taxi" sticker	\$	new	55.00	✓
7) 1pc	"Dial-A-Cab" sticker	\$	new	90.00	✓

Sub total S.Nett Parts \$ 430.00

L/charges

1)	To tuff kote	\$	30.	80.00
2)	To remove & refit fuel tank to facilitate the repair	\$	60.	120.00
3)	To transfer left rear door glass, handle, trim board & mechanism parts	\$	✓	60.00
4)	To transfer left front door glass, handle, trim board & mechanism parts	\$	✓	60.00
5)	To remove rear bumper, left rear door, left front door, left side skirt, left front fender, front bumper. To cut / welding left rear fender, repair rear bumper & replace the above parts	\$	800.	1,000.00
6)	To putty, respray painting front bumper, left front fender, left front door, left rear door, left rear fender, rear bumper & left side skirt	\$	1200.	1,400.00

Sub total L/charges \$ 2,720.00
Estimated Total \$ 9,591.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
- WP
30/8/19 & 24 Spu
Lumpsum
Resurvey after repair.
6 days.
sur @ lkkauto.com

Mei Kwan (LKKAuto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 2 September, 2019 12:31 PM
To: Mei Kwan (LKKAuto)
Cc: Tan Kah Leong
Subject: CTP REF NO. SNM19D204066C02 LKK REF NO. CC6/CTI19015394/HA3
Attachments: 20190902122620.pdf

Dear Mdm,

We refer to the above matter and enclosed herewith our insured GIA REPORT.

Regards,

Irene Tay

Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 09.10.2019

Our ref: SHD2252K

LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park
#02-25 Ubi Ave 1
Singapore 408933

Attn: Mr. Vic
Motor Claims Dept

Dear Sir,

ACCIDENT ON 29.08.2019 INVOLVING VEHICLES SHD2252K & SDW8203H

The above referred.

We enclosed herewith our client signed discharge voucher for your payment processing. Please let us have your payment of \$7,536.30 make payable to Prime Auto Claims Service Pte Ltd soonest possible.

Please mail your cheque to our new office at No.6 Benoi Place Singapore 629927

Thank you.

Yours faithfully,

Ms. Alice Leong
E-mail: aliceleong@primeautoclaims.com

Encl.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI19015394/T1ha3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 16-10-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDN 8203H	Veh. Inspected	SHD 2252K	
Policy No.	DMPCSN3002181900	Coverage (\$)	0.00	
Claim No.	SNM19D204066C02/3	Excess (\$)	0.00	
Assign From		Assign Date	30/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GP71109804	Colour	ORANGE	
Odometer	232315	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	NEXEN	6 mm	
L/H Front Tyre	185/60 R15	NEXEN	6 mm	
R/H Rear Tyre	185/60 R15	NEXEN	6 mm	
L/H Rear Tyre	185/60 R15	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2019	Inspection Date	30/08/2019	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2252K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LEFT REAR FENDER	BENT	1,010.90	1,010.90
1	LEFT REAR FENDER LINING	NOT NECESSARY	455.00	-
1	LEFT REAR DOOR	BENT	1,275.30	1,275.30
1	LEFT FRONT DOOR	BENT	1,275.30	1,275.30
1	LEFT FRONT DOOR OUTER HANDLE WIHT COVER	TO REPAIR SEE LABOUR	322.70	-
1	SET LEFT FRONT DOOR TAPE	NECESSARY	60.55	60.55
1	LEFT FRONT DOOR OUTER MOULDING (BLACK COLOR)	CUT	250.00	250.00
1	LEFT SIDE MIRROR ASSY	DISTORTED	527.55	527.55
1	LEFT FRONT QUATER GLASS	NOT NECESSARY	290.70	-
1	LEFT FRONT QUATER GLASS SEAL	NOT NECESSARY	55.00	-
1	LEFT FRONT FENDER	BENT	368.95	368.95
1	LEFT FRONT FENDER 'HYBRID' EMBLEM	NECESSARY	58.00	58.00
1	LEFT FRONT FENDER LINING	DEFORMED	115.90	115.90
1	FRONT BUMPER	DEFORMED	1,350.00	1,350.00
1	FRONT BUMPER LEFT SIDE RETAINER	NECESSARY	35.00	35.00
1	FRONT BUMPER LEFT SIDE BRACKET	NOT NECESSARY	38.00	-
1	LEFT SIDE SKIRT	TO REPAIR SEE LABOUR	563.00	-
	LESS 20% DISCOUNT		-1,610.37	-1,265.49
			6,441.48	5,061.96
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET LEFT FRONT FENDER COWLING CLIP (SN)	NECESSARY	15.00	15.00
1	SET LEFT REAR FENDER COWLING CLIP (SN)	NOT NECESSARY	15.00	-
1	LEFT REAR TYRE WHEEL COVER (SN)	CUT	195.00	195.00
1	'PRIME TAXI' STICKER (SN)	NECESSARY	55.00	55.00
1	'DIAL-A-CAB' STICKER (SN)	NECESSARY	90.00	90.00
			430.00	385.00

Report Ref No. CC6/CTI19015394/T1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO TUFF KOTE.		80.00	30.00
	TO REMOVE & REFIT FUEL TANK TO FACILITATE THE REPAIR.		120.00	60.00
	TO TRANSFER LEFT REAR DOOR GLASS ,HANDLE ,TRIM BOARD & MECHANISM PARTS.		60.00	60.00
	TO TRANSFER LEFT FRONT DOOR GLASS ,HANDLE ,TRIM BOARD & MECHANISM PARTS.		60.00	60.00
	TO REMOVE REAR BUMPER ,LEFT REAR DOOR ,LEFT FRONT DOOR ,LEFT SIDE SKIRT ,LEFT FRONT FENDER ,FRONT BUMPER ,TO CUT/WELDING LEFT REAR FENDER ,REPAIR REAR BUMPER & REPLACE THE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF LEFT FRONT DOOR OUTER HANDLE WIHT COVER AND LEFT SIDE SKIRT .		1,000.00	800.00
	TO PUTTY,RESPRAY PAINTING FRONT BUMPER ,LEFT FRONT FENDER ,LEFT FRONT DOOR ,LEFT REAR DOOR ,LEFT REAR FENDER ,REAR BUMPER & LEFT SIDE SKIRT.		1,400.00	1,200.00
			2,720.00	2,210.00
	GRAND TOTAL		9,591.48	7,656.96
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,100.00

Report Ref No. CC6/CTI19015394/T1ha3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.