



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

Date: 30.08.2019

China Taiping Insurance (S) Pte Ltd

2 Anson Road #16-00

Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE REPAIR TO VEHICLE SHD2252K HONDA SHUTTLE HYBRID (2016)

To Supply

1) 1pc	left rear fender	\$	bt ✓ 1,010.90
2) 1pc	left rear fender lining	\$	x 455.00
3) 1pc	left rear door	\$	bb ✓ 1,275.30
4) 1pc	left front door	\$	bb ✓ 1,275.30
5) 1pc	left front door outer handle with cover	\$	Rx 322.70
6) 1set	left front door tape	\$	ne ✓ 60.55
7) 1pc	left front door outer moulding (black color)	\$	cut ✓ 250.00
8) 1pc	left side mirror assy	\$	dis ✓ 527.55
9) 1pc	left front quarter glass	\$	x 290.70
10) 1pc	left front quarter glass seal	\$	x 55.00
11) 1pc	left front fender	\$	bt ✓ 368.95
12) 1pc	left front fender "Hybrid" emblem	\$	ne ✓ 58.00
13) 1pc	left front fender lining	\$	de ✓ 115.90
14) 1pc	front bumper	\$	de ✓ 1,350.00
15) 1pc	front bumper left side retainer	\$	ne ✓ 35.00
16) 1pc	front bumper left side bracket	\$	x 38.00
17) 1pc	left side skirt	\$	Rx 563.00

Sub total parts	\$	8,051.85
Less: 20% discount	\$	(1,610.37)
	\$	6,441.48

S.Net parts

1) 1set	rear bumper clip	\$	x 30.00
----------	------------------	----	---------

2) 1set	front bumper clip	\$	new	30.00
3) 1set	left front fender cowling clip	\$	new	15.00
4) 1set	left rear fender cowling clip	\$	X	15.00
5) 1pc	left rear tyre wheel cover	\$	new	195.00
6) 1pc	"Prime Taxi" sticker	\$	new	55.00
7) 1pc	"Dial-A-Cab" sticker	\$	new	90.00

Sub total S.Nett Parts \$ 430.00

L/charges

1)	To tuff kote	\$	30.	80.00
2)	To remove & refit fuel tank to facilitate the repair	\$	60.	120.00
3)	To transfer left rear door glass, handle, trim board & mechanism parts	\$	✓	60.00
4)	To transfer left front door glass, handle, trim board & mechanism parts	\$	✓	60.00
5)	To remove rear bumper, left rear door, left front door, left side skirt, left front fender, front bumper. To cut / welding left rear fender, repair rear bumper & replace the above parts	\$	800.	1,000.00
6)	To putty, respray painting front bumper, left front fender, left front door, left rear door, left rear fender, rear bumper & left side skirt	\$	1200.	1,400.00

Sub total L/charges \$ 2,720.00
Estimated Total \$ 9,591.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
- WP'
30/8/19 @ 245pm
Lumpsum
Resurvey after repair.
6 days.
sur @ lkkauto.com.